

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0222/2022/JT
DATE : 23-Mar-22
WIP : 16593

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 24/3/22

CHINA TAIPING INSURANCE (S) PTE LTD

105 CECIL STREET

#19-00 THE OCTAGON

SINGAPORE 069534

Attn: Ms Angie - Motor Claims Dept/ Windscreen

Tel: 6389 6541 - Fax: 6224 7175

OWNER'S NAME : MR TEO POH CHUAN EDWIN
ADDRESS : BLK 481 YIO CHU KANG ROAD
#03-04
SINGAPORE 787056
TELEPHONE : HP +65 81637757
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : DMPCSNA00261722101
VEHICLE NO : **SBV 3388 Y**
MODEL CODE : RS6 AVANT 4.0 TFSI Q
MODEL YEAR : 18/12/2013
ENGINE NO : CRD 002885
CHASSIS NO : WAUZZZ4G3EN901479
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 19-Mar-22
PLACE OF ACCIDENT : YIO CHU KANG



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SBV 3388 Y

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00	X
2	TO REMOVE AND REINSTALL FRONT SEAT ASSY, BACK REST, AB PILLAR TRIMS, SILL TRIMS, CARPETS, ELECTRONIC COMPONENTS. AND FUSE TRAYS.	S/N \$ 1,800.00	X
3	TO REMOVE AND TRANSFER RHS FRONT DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$ 400.00	✓
4	TO DISMANTLE AND REINSTALL FRONT BUMPER. TO RENEW RHS FRONT FENDER, RHS FRONT DOOR AND RHS SILL PANEL TRIM. TO CUT OUT RHS A-PILLAR AND RHS SILL PANEL. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 7,200.00	2800 3.5 x 800 = 2800
5	TO RESPRAY RHS FRONT FENDER, RHS FRONT DOOR, RHS SILL PANEL TRIM, RHS SILL PANEL, DOOR ENTRANCE AND RHS A-PILLAR.	\$ 5,500.00	3200
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 15,572.00	

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SBV 3388 Y

		DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT FENDER <i>Dented.</i>	1	\$ 4,192.00	✓
2	FRONT FENDER BRACE - RH <i>Not m</i>	1	\$ 107.00	+
3	FRONT FENDER CLOSING ELEMENT - RH ?	1	\$ 60.00	?
4	FRONT DOOR - RH <i>Dented</i>	1	\$ 4,760.00	✓
5	FRONT DOOR OUTER SEAL <i>Not m</i>	1	\$ 256.00	✓
6	BONDING AGENT ?	1	\$ 51.00	?
7	CLEANING SOLUTION ?	1	\$ 74.00	?
8	APPLICATOR ?	1	\$ 8.00	?
9	FRONT DOOR OUTER SEAL LOWER - RH <i>Not m</i>	1	\$ 256.00	?
10	FRONT DOOR CATCH - RH ?	1	TBC	?
11	FRONT DOOR SEAL OUTER - RH LOWER <i>Not m</i>	1	\$ 213.00	X
12	FRONT DOOR HINGE - RH LOWER <i>Best</i>	1	TBC	✓
13	TREADED PLATE - UPPER / LOWER - LH / RH <i>Lower 2nd</i>	2	\$ 35.00 17.50	
14	TYRE PRESSURE DATA PLATE <i>Not m</i>	1	\$ 42.00	✓
15	AB PILLAR TRIM - RH <i>Repis</i>	1	\$ 2,857.00	X
16	A PILLAR END CAP - RH FRONT / REAR <i>Not m</i>	2	\$ 1,496.00	+
17	A PILLAR TRIM BRACKET - RH <i>Not m</i>	1	\$ 92.00	X
18	AB PILLAR ATTACHMENT PARTS <i>Not m</i>	1	\$ 656.00	✓
19	DOUBLE-SIDED ADHESIVE TAPES <i>Not m</i>	1	TBC	✓
20	A-PILLAR - RH <i>Repis</i>	1	\$ 8,190.00	+
SUB TOTAL SPARE PARTS		:	\$ 23,345.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SBV 3388 Y

		DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT STONE GUARD FILM - RH <i>Not m</i>	1	\$ 770.00	X
22	FRONT DOOR LIGHT FIBRE - RH <i>Not m ?</i>	1	\$ 2,410.00	X ?
23	REAR DOOR LIGHT FIBRE - RH <i>Not m</i>	1	\$ 1,887.00	X
24	FRONT DOOR WINDOW SLOT SEAL TRIM STRIP - RH <i>Not m</i>	1	\$ 571.00	X
25	ROOF MOLDING - RH <i>Not m</i>	1	\$ 902.00	X
26	DATA TAG <i>Not m</i>	1	\$ 515.00	X
27	ARYLIC SEALANT <i>Not m</i>	S/N	\$ 180.00	X
28	CAVITY WAX <i>Not m</i>	S/N	\$ 140.00	X
29	STONE CHIP <i>Not m</i>	S/N	\$ 180.00	X
30	METAL FILLER POWDER <i>Not m</i>	S/N	\$ 280.00	X
31	SUNDRIES <i>?</i>		\$ 350.00	?
TOTAL SPARE PARTS		:	\$ 31,530.00	
TOTAL LABOUR CHARGES		:	\$ 15,572.00	
GRAND TOTAL		:	\$ 47,102.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

 PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian Ly*
SURVEYED DATE : *25/03/22*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not Authorised, 06 Days*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT