

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL NORA KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0222/2022/JT
DATE : 23-Mar-22
WIP : 16593

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 24/3/22

CHINA TAIPING INSURANCE (S) PTE LTD

105 CECIL STREET

#19-00 THE OCTAGON

SINGAPORE 069534

Attn: Ms Angie - Motor Claims Dept/ Windscreen

Tel: 6389 6541 - Fax: 6224 7175

Hi Adrian,

6 days - ok - Jy - 18 May 22

OWNER'S NAME : MR TEO POH CHUAN EDWIN
ADDRESS : BLK 481 YIO CHU KANG ROAD
#03-04
SINGAPORE 787056
TELEPHONE : HP +65 81637757
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : DMPCSNA00261722101
VEHICLE NO : SBV 3388 Y
MODEL CODE : RS6 AVANT 4.0 TFSI Q
MODEL YEAR : 18/12/2013
ENGINE NO : CRD 002885
CHASSIS NO : WAUZZZ4G3EN901479
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 19-Mar-22
PLACE OF ACCIDENT : YIO CHU KANG

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SBV 3388 Y

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS , OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00	
2	TO REMOVE AND REINSTALL FRONT SEAT ASSY, BACK REST, AB PILLAR TRIMS, SILL TRIMS, CARPETS, ELECTRONIC COMPONENTS. AND FUSE TRAYS.	S/N \$ 1,800.00	
3	TO REMOVE AND TRANSFER RHS FRONT DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$ 400.00	\$ 400.00
4	TO DISMANTLE AND REINSTALL FRONT BUMPER. TO RENEW RHS FRONT FENDER, RHS FRONT DOOR AND RHS SILL PANEL TRIM. TO CUT OUT RHS A-PILLAR AND RHS SILL PANEL. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 7,200.00	\$ 2,800.00
5	TO RESPRAY RHS FRONT FENDER, RHS FRONT DOOR, RHS SILL PANEL TRIM, RHS SILL PANEL, DOOR ENTRANCE AND RHS A-PILLAR.	\$ 5,500.00	\$ 3,200.00
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		: \$ 15,572.00	\$ 6,592.00

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SBV 3388 Y

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT FENDER	1	\$ 4,192.00	\$ 4,192.00
2	FRONT FENDER BRACE - RH	1	\$ 107.00	
3	FRONT FENDER CLOSING ELEMENT - RH	1	\$ 60.00	
4	FRONT DOOR - RH	1	\$ 4,760.00	\$ 4,760.00
5	FRONT DOOR OUTER SEAL	1	\$ 256.00	\$ 256.00
6	BONDING AGENT	1	\$ 51.00	
7	CLEANING SOLUTION	1	\$ 74.00	
8	APPLICATOR	1	\$ 8.00	
9	FRONT DOOR OUTER SEAL LOWER - RH	1	\$ 256.00	
10	FRONT DOOR CATCH - RH	1	TBC	
11	FRONT DOOR SEAL OUTER - RH LOWER	1	\$ 213.00	\$ 213.00
12	FRONT DOOR HINGE - RH LOWER	1	TBC	\$ 112.50
13	TREADED PLATE - UPPER / LOWER - LH / RH	2	\$ 35.00	\$ 17.40
14	TYRE PRESSURE DATA PLATE	1	\$ 42.00	\$ 30.00
15	AB PILLAR TRIM - RH	1	\$ 2,857.00	
16	A PILLAR END CAP - RH FRONT / REAR	2	\$ 1,496.00	
17	A PILLAR TRIM BRACKET - RH	1	\$ 92.00	
18	AB PILLAR ATTACHMENT PARTS	1	\$ 656.00	\$ 656.00
19	DOUBLE-SIDED ADHESIVE TAPES	1	TBC	\$ 55.00
20	A-PILLAR - RH	1	\$ 8,190.00	
SUB TOTAL SPARE PARTS		:	\$ 23,345.00	\$ 10,291.90

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SBV 3388 Y

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
				\$ 10,291.90
21	FRONT STONE GUARD FILM - RH	1	\$ 770.00	
22	FRONT DOOR LIGHT FIBRE - RH	1	\$ 2,410.00	
23	REAR DOOR LIGHT FIBRE - RH	1	\$ 1,887.00	
24	FRONT DOOR WINDOW SLOT SEAL TRIM STRIP - RH	1	\$ 571.00	
25	ROOF MOLDING - RH	1	\$ 902.00	
26	DATA TAG	1	\$ 515.00	
27	ARYLIC SEALANT	S/N	\$ 180.00	
28	CAVITY WAX	S/N	\$ 140.00	
29	STONE CHIP	S/N	\$ 180.00	
30	METAL FILLER POWDER	S/N	\$ 280.00	
	Supp - See Attachment			\$ 4,368.00
31	SUNDRIES		\$ 350.00	\$ 30.00
TOTAL SPARE PARTS			\$ 31,530.00	\$ 14,689.90
TOTAL LABOUR CHARGES			\$ 15,572.00	\$ 6,592.00
GRAND TOTAL			\$ 47,102.00	\$ 21,281.90

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

**Supplementary Estimate**

GST Reg No. 19-9902271-W

China Taiping Insurance (SG) Pte Ltd
105 Cecil Street
#19-00 The Octagon
Singapore 069534
Attn: Motor Claims Dept
Tel: 6389 6541 - Fax: 6224 7175

Estimate No. PA/OD/0222/2022/JT
Date 08-Apr-21
Service Advisor GLORY
Pages 1 of 1
Regn No SBV 3388 Y
Model No RS6 AVANT 4.0 TFSI Q

Quantity	Description	Unit Price	Amount
Labours			
1	RHS FRONT DOOR BOARD PANEL	\$ 4,368.00	\$ 4,368.00
GRAND TOTAL		\$ 4,368.00	\$ 4,368.00

For Premium Automobiles Pte Ltd

Authorised Signature

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF
THE AFFECTED VEHICLE. SHOULD WE REQUIRE
FURTHER LABOUR CHARGES AND SPARE PARTS IN THE
PROGRESS OF REPAIR, WE SHALL INFORM YOU
ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR
APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT