

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0224/2022/NK
DATE : 23-Mar-22
WIP : 16627

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE SURVEY ON 25/3/22

CHINA TAIPING INSURANCE (S) PTE LTD

105 CECIL STREET

#19-00 THE OCTAGON

SINGAPORE 069534

Attn: Ms Angie - Motor Claims Dept/ Windscreen

Tel: 6389 6541 - Fax: 6224 7175

Hi Steve,

7 days - ok - Jy - 15 Dec 22

OWNER'S NAME : MR LI WUJIAN
ADDRESS : 462 CORPORATION ROAD
#08-02
SINGAPORE 649816
TELEPHONE : HP +65 90608754
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 5114210486-02
VEHICLE NO : **SKQ 8674 H**
MODEL CODE : VOLKSWAGEN JETTA 1.4
MODEL YEAR : 2/1/2015
ENGINE NO : CAXE81341
CHASSIS NO : WAUZZZ16ZEM059492
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 18-Mar-22
PLACE OF ACCIDENT : NEAR 7 PIONEER PI



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKQ 8674 H**

S/N	NATURE OF JOBS		ESTIMATED CHARGES		SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER RHS FRONT DOOR AND RHS DOOR'S MULTI LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$	700.00	\$	700.00
2	TO DISMANTLE AND RENEW RHS FRONT DOOR AND RHS REAR DOOR. TO REPAIR RHS SILL PANEL AND RHS REAR FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPOENENTS. REINSTALL ALL PARTS REMOVED.	\$	2,800.00	\$	1,500.00
3	TO RESPRAY RHS FRONT DOOR, RHS REAR DOOR, DOOR HANDES, RHS SILL PANEL, RHS REAR FENDER AND DOOR ENTRANCE.	\$	2,000.00	\$	1,500.00
4	TO RENEW RHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT.	SN \$	280.00	\$	280.00
6	SUPPLEMENTARY	\$	2,000.00	\$	1,000.00
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	\$	192.00
TOTAL LABOUR CHARGES		: \$	7,972.00	\$	5,172.00

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKQ 8674 H

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT DOOR RH	1	\$ 2,701.00	\$ 2,445.23
2	MULTI POINT SOCKET HEAD BOLT	5	\$ 32.00	
3	ANTI COROSION WAX	1	\$ 51.00	
4	DOOR INNER SEAL	1	\$ 345.00	
5	DOOR CATCH	1	TBC	
6	FRONT DOOR HANDLE RH	1	\$ 204.00	
7	FRONT DOOR HANDLE CAP RH	1	\$ 41.00	
8	WINDOW SLOT SEAL OUTER RH	1	\$ 315.00	
9	REAR DOOR RH	1	\$ 2,701.00	\$ 2,445.23
10	SOCKET HEAD BOLT	2	\$ 15.00	
11	MULTI POINT SOCKET HEAD BOLT	4	\$ 24.00	
12	ANTI COROSION WAX	1	\$ 51.00	
13	DOOR INNER SEAL REAR RH	1	\$ 345.00	
14	DOOR CATCH	1	TBC	
15	DOOR OUTER SEAL	1	\$ 182.00	\$ 181.50
16	WINDOW SLOT SEAL OUTER RH	1	\$ 315.00	
17	WINDOW APERTURE SEAL-BLACK	1	\$ 174.00	
18	WINDOW REGULATOR RH	1	\$ 377.00	
19	WINDOW REGULATOR COVER RH	1	\$ 34.00	
20	WINDOW REGULATOR MOTOR RH	1	\$ 934.00	
SUB TOTAL SPARE PARTS		:	\$ 8,841.00	\$ 5,071.96

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKQ 8674 H

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
				\$ 5,071.96
21	RHS REAR RIM RH	1	\$ 1,047.00	\$ 1,047.00
22	STONE CHIP	S/N	\$ 180.00	\$ 180.00
23	SUPPLEMENTARY		\$ 480.00	\$ 478.40
24	SUNDRIES	1	\$ 300.00	\$ 22.60
TOTAL SPARE PARTS		:	\$ 10,848.00	\$ 6,799.96
TOTAL LABOUR CHARGES		:	\$ 7,972.00	\$ 5,172.00
GRAND TOTAL		:	\$ 18,820.00	\$ 11,971.96

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.
 BL-[02/11/22



Supplementary Estimate-1

GST Reg No. 19-9902271-W

China Taiping Insurance (SG) Pte Ltd 105 Cecil Street #19-00 The Octagon Singapore 069534 Attn: Motor Claims Dept Tel: 6389 6541 - Fax: 6224 7175		Estimate No. Date Service Advisor Pages Regn No Model No	PA/TP/0224/2022/NK 20-Apr-22 CHANG 1 of 1 SKQ 8674 H VOLKSWAGEN JETTA 1.4
Quantity	Description	Unit Price	Amount
<u>Labours</u>			
1	TO DISMANTLE AND REINSTALL REAR BUMPER.	\$ 1,000.00	\$ 500.00
2	TO RESPRAY REAR BUMPER.	\$ 1,000.00	\$ 500.00
<u>Parts</u>			
1	FRONT DOOR LOWER SEAL - RH	\$ 117.00	\$ 116.50
2	REAR DOOR BOWDEN CABLE - RH	\$ 69.00	\$ 68.10
3	REAR DOOR FIXED WINDOW WITH SEAL - RH	\$ 196.00	\$ 196.00
4	DOOR SOUND ABSORBER 2	\$ 98.00	\$ 97.80
GRAND TOTAL		\$ 2,480.00	\$ 1,478.40

For Premium Automobiles Pte Ltd

Authorised Signature



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT