



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

ALLIANZ INSURANCE SINGAPORE PTE LTD

Ref: CS/LAW22002725/Kqce2

C/O: TAN KOK QUAN PARTNERSHIP

Date: 12/04/2022

1 WALLICH STREET #07-02

GUOCO TOWERSINGAPORE 078881

Code: AIS

### 1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)

<b>Insured Veh.</b>	SMQ 368X	<b>Veh. Inspected</b>	GBE 1305P
<b>Policy No.</b>	SPMF1000000405	<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	CF.clm.1895.21-ais	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	SAMANTHA CHEW	<b>Assign Date</b>	24/03/2022

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	NISSAN NV350 (M)	<b>c.c</b>	2488
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2015
<b>Chassis No.</b>	JN1MC2E26Z0003471	<b>Colour</b>	SILVER
<b>Odometer</b>	210957 KM	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	NIL
<b>General</b>	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
<b>R/H Front Tyre</b>	195 R15X8	BRIDGESTONE	6 mm
<b>L/H Front Tyre</b>	195 R15X8	BRIDGESTONE	6 mm
<b>R/H Rear Tyre</b>	195 R15X8	TOURADOR	3 mm
<b>L/H Rear Tyre</b>	195 R15X8	TOURADOR	3 mm

### 4. Description of Damages

THE VEHICLE HAD COMPLETED ITS REPAIR WORKS.

REPAIR CONDITION SEE DETAILS.

### 5. General Information

<b>Accident Date</b>	24/07/2021	<b>Inspection Date</b>	29/03/2022
<b>Survey held at</b>	60 JALAN LAM HUAT #02-45 CARROS CENTRE		
<b>Repairer</b>	J.L.CAR AUTO SERVICE		

### 5a. Remarks

- A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **18 Working Days**