

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22002728/APA3Q2**Date:** 17/05/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100375889
Claimant Vehicle No :	SNE1296P	Insured Vehicle No :	SKN8222U
Date of Loss:	22/03/2022	Nature of Claim:	TP
		Claim No:	6357208282SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNE1296P	Engine No:	HIDDEN
Make & Model:	TOYOTA AXIO, 1.5 (A)	Chassis No:	NZE1416096073
Reg. Date:	01/05/2009 (Man. Year: 2009)	Odometer:	116426 km
Colour:	Blue		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/60 R15	Rear Tyre Size:	195/60 R15
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,997.60	3,136.25	2,861.35	47.71
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,900.00	1,920.00	980.00	33.79
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,897.60	5,056.25	3,841.35	43.17
Approved Total (Overridden) (S\$)		4,000.00		
(S\$)	8,897.60	4,000.00	4,897.60	55.04
+ GST 7.00/7.00% (S\$)	622.83	280.00	342.83	55.04
Nett Amount (S\$)	9,520.43	4,280.00	5,240.43	55.04
+ Loss of Use (7.0 x S\$60.00/day) (S\$)		420.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		4,707.45		
Global Sum Settlement (S\$)		4,700.00		

INSPECTION

Date of Assignment:	23/03/2022	Mirage Motorwerkz Pte Ltd (HQ)
Date Inspected:	23/03/2022 Inspected At:	10 KAKI BUKIT ROAD 2 #01-29 FIRST EAST CENTRE
Estimated Period of Repair:	6.0 days	Singapore 417868

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR NUMBER PLATE	Not Necessary	30.00 FS	*- FS
2	1		*REAR NUMBER PLATE HOLDER	Not Necessary	30.00 FS	*- FS
3	1		*REAR BUMPER	Distorted	585.10 F	*585.10 FL
4	1		*REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
5	2		*REAR BUMPER SIDE HOLDER	Necessary	83.80 F	*83.80 FL
6	1		*REAR BUMPER IMPACT BRACKET	N/S Dented	225.60 F	*112.80 FL
7	1		*REAR END PANEL	Dented	595.90 F	*595.90 FL
8	1		*REAR END PANEL TOP GARNISH	Deformed	166.30 F	*166.30 FL
9	1		*REAR END PANEL TOP GARNISH CLIPS	Necessary	20.00 FS	*20.00 FS
10	1		*REAR END PANEL SEALANT	Necessary	60.00 FS	*60.00 FS
11	2		*TAILLAMP	N/S Cracked / O/S Cut	642.00 F	*642.00 FL
12	2		*TAILLAMP PANEL	Repair	321.60 F	*- FL
13	2		*TAILLAMP LOWER BRACKET	Not Necessary	128.80 F	*- FL
14	1		*BOOTLID	Buckled	849.30 F	*849.30 FL
15	1		*BOOTLID LOCK	Damaged	185.20 F	*185.20 FL
16	1		*BOOTLID WEATHERSTRIP	Cut	172.90 F	*172.90 FL
17	2		*BOOTLID HINGE	Not Necessary	85.80 F	*- FL
18	1		*BOOTLID INNER TRIM BOARD	Not Necessary	296.60 F	*- FL
19	1		*BOOTLID INNER TRIM BOARD CLIPS	Not Necessary	30.00 FS	*- FS
20	1		*TOYOTA LOGO	Necessary	47.20 F	*47.20 FL
21	1		*AXIO EMBLEM	Necessary	44.20 F	*44.20 FL
22	1		*X EMBLEM	Necessary	34.40 F	*34.40 FL
23	2		*REAR FENDER INNER TRIM	Not Necessary	757.00 F	*- FL
24	1		*REAR FENDER INNER TRIM CLIPS	Not Necessary	60.00 FS	*- FS
25	1		*SPARE TYRE PANEL TOP BOARD	Deformed	515.90 F	*515.90 FL
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)					5,997.60	4,145.00
- List Item Discount on L Items 0.00/25.00% (\$\$)					0.00	1,008.75
Total Parts (\$\$)					5,997.60	3,136.25

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,200.00	800.00
2	SPRAY PAINTING	New	1,200.00	850.00
3	WIRING	New	50.00	30.00
4	TO SPRAY TUFF COAT	New	150.00	80.00
5	TO REMOVE UPHOLSTERY	New	150.00	80.00
6	TO TRANSFER BOOTLID FITTINGS	New	150.00	80.00
Gross Labour Cost (\$\$)			2,900.00	1,920.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >