

SNE1296P.

TP Alg.
Xino Tony.

Toyota Axio. 1496 CC

NZE1416096073

Rear Number Plate	2 x 1/2	30(SN) x
Rear Number Plate Holder	1/2	30(SN) x
Rear Bumper	Distorted	S85.10. ✓
Rear Bumper Clips	new	30(SN). ✓
Rear Bumper Side Holder x 02	new	41.9 x 2 = 83.80 ✓
Rear Bumper Impact Bracket x 02	LH Dented	112.80. ✓
		112.8 x 2 = 225.60
Rear End Panel	Dented	S85.90. ✓
Rear End Panel Top Garnish	Dented	166.30 ✓
Rear End Panel Top Garnish Clips	new	20(SN) ✓
Rear End Panel Sealant	new	60(SN) ✓
Taillamp x 02	LH cracked, RH cut	321 x 2 = 642 ✓
Taillamp Panel x 02	Rejs	160.8 x 2 = 321.60 x.
Taillamp Lower Bracket x 02	new	64.4 x 2 = 128.80 x

SNE 1296P.

Boothid Buckled
Boothid Lock Darg 1

849.30 ✓

185.20 ✓

172.90 ✓

Boothid Weatherstrip cut

Boothid Hinge x 02 ne m

42.9 x 2 = 85.80 x

Boothid Inner Trim Board 2 NY 296.60 x

Boothid Inner Trim Board Clips! m 30(SN) x

Toyota Logo }

47.20 ✓

Axio Emblem

44.20 ✓

X Emblem

34.40 ✓

Rear Fender Inner Trim x 02 M m

378.5 x 2 = 757 x

Rear Fender Inner Trim Clips. NY m

60(SN) x

Spare Tyre Panel Top Board Rehd 515.90 x ✓

4035, SN: 80.

3026.25

SNE1296P.

Panel Beating	1250 80
Spray Painting.	1250 850
Wiring	50 30
	150 80
To spray tuff coat	150 80
To remove upholstery.	150 80
To transfer bootlid fittings.	

total: 5026.25

L/S: AIC.

06 Days

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: