

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
 TEL: 6741 5336 FAX: 6741 7208 Email: claims@procarcare.com.sg
 GST:201006949C RCB NO:201006949C

M/S : CHOI HAN KWAI
 50 LORONG 40 GEYLANG #02-39
 SINGAPORE 398074

Estimate No: EST1507963
Date: 23 Mar 2022
Policy No: GA091473
Veh Reg No: SJN9531H
Make/Model: HYUNDAI HD AVANTE
 1.6 A
Chassis No: KMHDU41BR9U706685
Engine No: G4FC9U614693
Reg. Date: 06/03/2009

ATTN: CHINA

Your Ref No: TP 0322-6715
Claim Type: Third Party
Accident Date: 28/02/2022
TP Veh Reg No: GBF 2967 S

Estimate Repair Cost to Vehicle No :SJN9531H

Description	U/Price	Quantity	Price	Amount
			SS	SS
List Price				
1 REAR BUMPER W/SIDE HOLDER	447.0000	1 PC	447.00	447.00
2 REAR BUMPER CLIPS	49.0000	10 PC	49.00	49.00
3 REAR BUMPER FOAM	110.0000	1 PC	110.00	110.00
4 REAR BUMPER REINFORCEMENT	270.0000	1 PC	270.00	270.00
			5,346.00	
		Less 20%	1,069.20	4,276.80
Labour				
5 TO KNOCK OUT DENTS, REMOVE, REPLACE ACCIDENT PARTS	600.0000	1 JOB	600.00	600.00
6 TO RESPRAY PAINT ON ACCIDENT PORTIONS	500.0000	1 JOB	500.00	500.00
7 TO CHECK WIRING	50.0000	1 JOB	50.00	50.00
8 TO TRANSFER REAR BUMPER SENSOR	120.0000	1 JOB	120.00	120.00
			1,270.00	1,270.00
		Total		SS 5,546.80
		Add GST @ 7%		388.28
		Total Amount Payable		SS 5,935.08

TOTAL: SINGAPORE DOLLAR FIVE THOUSAND NINE HUNDRED THIRTY FIVE AND CENTS EIGHT ONLY

Not Authorized
 19/9/22
 2 days
 2 days

For Progressive Car Care Pte Ltd

7-496
 200
 396.60

LKK Auto Consultants hence notify the Receiver of the following:

AUTHORISED SIGNATURE

- To display damaged parts, for a survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____