

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	MS FIRST CAPITA	L INSURANCE LTD		Ref:	CS/FCI22002732/Evy3m4	
	36 ROBINSON RO #16-01 CITY HOUS	AD SESINGAPORE 068877		Date:	05/10/2022	
				Code:	FCI2	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SG 5878P	Veh. Inspected	d	SJJ 698R	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	D22000775MFBP	Excess (\$)		0.00	
	Assign From	JOANNE TAN	Assign Date		24/03/2022	
2.	2. Vehicle Particulars & Condition					
	Make & Model	PORSCHE 911	c.c		3800	
	Engine No.	HIDDEN	Year of Reg.		2010	
	Chassis No.	WP0ZZZ99ZAS730600	Colour		BLUE	
	Odometer	75702 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	FAIR				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	305/30 ZR19	PIRELLI		5 mm	
	L/H Front Tyre	305/30 ZR19	PIRELLI		5 mm	
	R/H Rear Tyre	305/30 ZR19	PIRELLI		5 mm	
	L/H Rear Tyre	305/30 ZR19	PIRELLI		5 mm	
4.	4. Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	13/03/2022	Inspection Da	te	13/04/2022	
	Survey held at	STUTTGART AUTO PTE LTD	•			
		27A TANJONG PENJURU SINGAPORE 609042				
5a.	Remarks					
	A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days					