



STUTTGART AUTO PTE LTD
27A TANJONG PENJURU, SINGAPORE 60904 **EUROKARS GROUP**
ESTIMATE COST OF REPAIRS

PORSCHE

First Capital Insurance Limited		NAME :		WIP : 28434			
36 Robinson Road		ADDRESS :		EXCESS :			
#16-01 City House				DATE: 18-Mar-22			
Singapore 068877							
ATTN. : MOTOR CLAIMS		TEL :					
FAX :							
VEH NO :	SJJ698R	DATE IN :		CONTACT PERSON :	DEREK 63310683		
CHASSIS NO :	WP0ZZZ99ZAS730600	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY		
MODEL :	911 Targa 4S	DATE REG.:	9-Oct-10	POLICY NO. :			
NATURE OF WORKS							
S/NO	Parts Description			QTY	1ST SUPP	REVISED	PRICES
1	REAR BUMPER <i>X R</i>	1	P997-505-911-08-G2L				\$ 3,208.80
2	TOWING COVER <i>X NN</i>	1	P997-505-803-03-				\$ 37.60
3	RETAINING STRIP-RR BUMPER LWR <i>X NN</i>	1	P997-505-837-00-				\$ 72.80
4	BLIND RIVET (NEC) <i>/ nec</i>	8	P999-190-104-30-				\$ 12.80 ✓
5	EXHAUST TRIM LH <i>/ nec (pnl)</i>	1	P997-505-651-01-01C				\$ 273.60 ✓
6	EXHAUST TRIM RH <i>/ nec (pnl)</i>	1	P997-505-652-01-01C				\$ 273.60 ✓
7	RIVET (NEC) <i>/ nec</i>	4	P999-591-941-40-				\$ 10.80 ✓
8	BUMPER REINFORCEMENT <i>? X NN</i>	1	P997-505-121-12-				\$ 934.50
9	IMPACT PIPE BUMPER <i>? X NN</i>	2	P996-505-019-01-				\$ 168.60
10	R/BUMPER TUBE SEAL <i>? X NN</i>	2	P996-505-775-00-				\$ 25.00
11	SUPPORT BRACKET LH <i>? X NN</i>	1	P997-505-831-03-				\$ 546.30
12	SUPPORT BRACKET RH <i>? X NN</i>	1	P997-505-832-03-				\$ 546.30
13	REAR BUMPER CENTER BRACKET <i>? X NN</i>	1	P997-505-641-03-				\$ 134.30
14	RIVET (NEC) <i>/ nec</i>	4	P999-591-941-40-				\$ 10.80 ✓
15	PROTECTIVE FILM (NEC) <i>/ nec</i>	2	P997-504-631-00-				\$ 24.00 ✓
16	SENSOR <i>? X NN</i>	4	P997-606-191-01-				\$ 1,462.80
17	STRUT-RR BUMPER BRACE LH <i>X NN</i>	1	P997-505-681-01-				\$ 112.90
18	STRUT R RBUMPER BRACE RH <i>X NN</i>	1	P997-505-682-01-				\$ 112.90
19	REFLECTOR COVER <i>X NN</i>	1	P997-512-259-05-				\$ 2,497.50
20	REAR LIGHT (RH) <i>X NN</i>	1	P997-631-418-05-				\$ 1,443.50
21	REAR SILENCER MUFFLER <i>X NN</i>	1	P997-111-159-32-				\$ 2,023.70
22	RESTRAINING STRAP <i>X NN</i>	2	P997-113-119-31-				\$ 324.00
23	GASKET <i>X NN</i>	2	P997-111-113-30-				\$ 50.80
24	TAIL PIPE RH <i>/ cut</i>	1	P997-111-982-34-				\$ 1,844.00 ✓
25		0	0				\$ -
TOTAL PARTS							\$ 16,151.90
							\$ -
TOTAL PARTS COST							\$ 16,151.90

SUPPLEMENTARY							
NO	DESCRIPTION	QTY	PARTS NO	1st	Supp	REVISED	PRICES
1							
2							
3							
	Labour Description						
1	TO REMOVE /REPLACE REAR BUMPER, REINFORCEMENT & ALL ACCIDENT DAMAGED BODY PARTS. TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.					1560 ✓	\$ 3,900.00
2	TO RESPRAY REAR BUMPER .					1300 ✓	\$ 1,500.00
3	TO SUPPLY REAR LICENCE PLATE WITH CASING					NETT	\$ X 70.00
4	TO REMOVE & REPLACE THE REAR EXHAUST ASSY.					NETT ?	\$ X 1,560.00
5	TO TRANSFER THE REVERSE SENSORS.					150 ✓	\$ 300.00
6	TO INSTALL / SUPPLY BODY WRAP STICKER (PRICE TO BE ADVISE) (Invoire)					NETT	? X
7	TO APPLY SPECIAL CERAMIC COATING. (PRICE TO BE ADVISE) (Inrak & bill)					NETT	X
8	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.					150 ✓	\$ 250.00
9	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.					NETT	\$ 600.00
10	SUNDRIES.					NETT	\$ 20 ✓ 50.00

Steve (LKK)
13/4/22, 10.30 am

nn PL
4 Lys
P/P

ly R ly

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT.

TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400.00 WILL BE APPLY AS ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

TOTAL LABOUR	\$ -	\$ 8,230.00
TOTAL PARTS	\$ -	\$ 16,151.90
TOTAL	\$ -	\$ 24,381.90
LESS EXCESS	\$ -	\$ -
TOTAL AFTER EXCESS	\$ -	\$ 24,381.90
GST 7%	\$ -	\$ 1,706.73
GRAND TOTAL	\$ -	\$ 26,088.63

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

* Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

HOUS INVOLVED

Acknowledged by Repairer

Signature:

Date: