



**STUTTGART AUTO PTE LTD**  
**27A TANJONG PENJURU, SINGAPORE 609042**  
**ESTIMATE COST OF REPAIRS**



**PORSCHE**

<b>First Capital Insurance Limited</b>		<b>NAME :</b>		<b>WIP :</b>		28434	
36 Robinson Road		<b>ADDRESS :</b>		<b>EXCESS :</b>			
#16-01 City House				<b>DATE:</b>		18-Mar-22	
Singapore 068877							
<b>ATTN. :</b>		<b>TEL :</b>					
MOTOR CLAIMS							
<b>FAX :</b>							
<b>VEH NO :</b>	<b>SJJ698R</b>	<b>DATE IN :</b>		<b>CONTACT PERSON :</b>		DEREK	63310683
<b>CHASSIS NO :</b>	WP0ZZZ99ZAS730600	<b>MILEAGE :</b>		<b>TYPE OF CLAIM :</b>		THIRD PARTY	
<b>MODEL :</b>	911 Targa 4S	<b>DATE REG.:</b>	9-Oct-10	<b>POLICY NO. :</b>			

**NATURE OF WORKS**

S/NO	Parts Description						
	QTY			1ST	SUPP	REVISED	PRICES
1	REAR BUMPER	1	P997-505-911-08-G2L				\$ 3,208.80
2	TOWING COVER	1	P997-505-803-03-				\$ 37.60
3	RETAINING STRIP-RR BUMPER LWR	1	P997-505-837-00-				\$ 72.80
4	BLIND RIVET (NEC)	8	P999-190-104-30-			\$ 12.80	\$ 12.80
5	EXHAUST TRIM LH	1	P997-505-651-01-01C			\$ 273.60	\$ 273.60
6	EXHAUST TRIM RH	1	P997-505-652-01-01C			\$ 273.60	\$ 273.60
7	RIVET (NEC)	4	P999-591-941-40-			\$ 10.80	\$ 10.80
8	BUMPER REINFORCEMENT	1	P997-505-121-12-				\$ 934.50
9	IMPACT PIPE BUMPER	2	P996-505-019-01-				\$ 168.60
10	R/BUMPER TUBE SEAL	2	P996-505-775-00-				\$ 25.00
11	SUPPORT BRACKET LH	1	P997-505-831-03-				\$ 546.30
12	SUPPORT BRACKET RH	1	P997-505-832-03-				\$ 546.30
13	REAR BUMPER CENTER BRACKET	1	P997-505-641-03-				\$ 134.30
14	RIVET (NEC)	4	P999-591-941-40-			\$ 10.80	\$ 10.80
15	PROTECTIVE FILM (NEC)	2	P997-504-631-00-			\$ 24.00	\$ 24.00
16	SENSOR	4	P997-606-191-01-				\$ 1,462.80
17	STRUT-RR BUMPER BRACE LH	1	P997-505-681-01-				\$ 112.90
18	STRUT R RBUMPER BRACE RH	1	P997-505-682-01-				\$ 112.90
19	REFLECTOR COVER	1	P997-512-259-05-				\$ 2,497.50
20	REAR LIGHT (RH)	1	P997-631-418-05-				\$ 1,443.50
21	REAR SILENCER MUFFLER	1	P997-111-159-32-				\$ 2,023.70
22	RESTRAINING STRAP	2	P997-113-119-31-				\$ 324.00
23	GASKET	2	P997-111-113-30-				\$ 50.80
24	TAIL PIPE RH	1	P997-111-982-34-			\$ 1,844.00	\$ 1,844.00
25		0	0				\$ -
TOTAL PARTS						\$ 2,449.60	\$ 16,151.90
							\$ -
TOTAL PARTS COST						\$ 2,449.60	\$ 16,151.90

**SUPPLEMENTARY**

NO	DESCRIPTION	QTY	PARTS NO	1st	Supp	REVISED	PRICES
1							
2							
3							
<b><u>Labour Description</u></b>							

1	TO REMOVE /REPLACE REAR BUMPER, REINFORCEMENT & ALL ACCIDENT DAMAGED BODY PARTS. TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.			\$ 1,560.00	\$ 3,900.00
2	TO RESPRAY REAR BUMPER .			\$ 1,300.00	\$ 1,500.00
3	TO SUPPLY REAR LICENCE PLATE WITH CASING			\$ -	\$ 70.00
4	TO REMOVE & REPLACE THE REAR EXHAUST ASSY.			\$ -	\$ 1,560.00
5	TO TRANSFER THE REVERSE SENSORS.			\$ 150.00	\$ 300.00
6	TO INSTALL / SUPPLY BODY WRAP STICKER (PRICE TO BE ADVISE)			\$ -	
7	TO APPLY SPECIAL CERAMIC COATING. (PRICE TO BE ADVISE)			\$ -	
8	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.			\$ 150.00	\$ 250.00
9	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.			\$ 600.00	\$ 600.00
10	SUNDRIES.			\$ 20.00	\$ 50.00
		TOTAL LABOUR		\$ 3,780.00	\$ 8,230.00
		TOTAL PARTS		\$ 2,449.60	\$ 16,151.90
		TOTAL		\$ 6,229.60	\$ 24,381.90
		LESS EXCESS		\$ -	\$ -
		TOTAL AFTER EXCESS		\$ 6,229.60	\$ 24,381.90
		GST 7%		\$ 436.07	\$ 1,706.73
		GRAND TOTAL		\$ 6,665.67	\$ 26,088.63

**REMARKS:**

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING,YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT.

TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400.00 WILL BE APPLY AS ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.