



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

**ESTIMATE**

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
Leong Kin Yip (Liang Jianye)	Cust No/Name /Leong Kin Yip (Liang Jianye)
Blk 183B Boon Lay Avenue	Reg No/Reg Date SLZ3378L / 18/04/201
#12-718	Date In/Mileage / 0
Singapore 642183	Chassis No MMBSTA13AJH001872
Contact No Mobile: 94307215	Engine No 3A92UGS5752
	Make/Model MIT/18MY ATTRAGE 1.2 CVT
	Colour/Trim W05 WHITE PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00041	Cash	24/03/2022/ 10:25	BLC	442 / CocoLu	21851
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
E PNT88000	RENEW FRT AIRDAM, FRT BUMPER, FRT FENDER RH, REPAIR BONNET	450 X 1.5			675 1350.00
E PNT98000	SPRAY PAINT FOR FRT BUMPER, AIRDAM, FRT FENDER RH, BONNET	4 x 350			1400.00
E PNT88000	REMOVE & INSTALL FRT AIRDAM				100.00
A 54900099	CHECK WIRING & ELECTRICAL SYSTEM				30.00
A 10028901	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM				120.00
B WHEELALIGNMENT120L	To Conduct Computerize Full Wheel Alignment				120.00
M SUNDRY	Sundry				20.00
M UNPAINTED BODYKITS		1.00	1643.00	00.00	1643.00
M FACE,FR BUMPER		1.00	706.00	00.00	706.00
M BRACKET,FR BUMPER,RH		1.00	13.00	00.00	13.00
M AIR DAM,SIDE,FR RH		1.00	18.00	00.00	18.00
M GARNISH,FR BUMPER,RH		1.00	127.00	00.00	127.00
M HEADLAMP ASSY,RH		1.00	663.00	00.00	663.00
M FENDER,FR RH		1.00	500.00	00.00	500.00
M SHIELD,FR WHEELHOUSE,RH		1.00	98.00	00.00	98.00
<p>Steve (LKK) 24/3/22, 1.30pm</p> <p>90-M AG</p> <p>EXCEN-7</p> <p>PIP</p> <p>M BL 17</p> <p>4 dy</p>					
<p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> To resurvey before/after spray painting To display damaged part(s) during resurvey Parts prices are subject to confirmation Third party survey is on a "Without Prejudice" basis No illegal modification(s) is allowed Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company 					
<p>Confirm & accepted by</p> <p>Authorized signatory and company stamp</p>					
<p>7% GST on</p> <p>Nett</p> <p>Total Payable</p>					<p>6,908.00</p> <p>483.56</p> <p>7,391.56</p>

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.