



CYCLE &amp; CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD  
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

Co Reg No : 199405410K

## ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name LCV07996/PEH KIM HUAT Reg No/Reg Date SMG9788K / 08/01/201 Date In/Mileage 25/03/2022/ 0 Chassis No KNAF3416MK5024544 Engine No G4FGJH713520 Make/Model KIA/CERATO 1.6 A EX G333 Colour/Trim B4U GRAVITY BLUE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	24/03/2022/ 13:13	BLK	282 / Kevin Leong	48612			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE FRT BUMPER, SUPPORT & AFFECTED AREA								400 1200.00
E PNT98000 PAINT WORK ON FRT BUMPER PANEL								120.00
E PNT88000 REMOVE & INSTALL RADIATOR, CONDENSER FOR FACILITATE REPAIR								80.00
M SUNDRY TO TOP UP AIRCON GAS								30.00
A 54900099 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM								120.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM								50.00
M SUNDRY TO SUPPLY FRT NUMBER PLATE WITH FRAME BT								20 50.00
M SUNDRY SUNDRIES					1.00	1247.00	20.00	997.60
M LAMP ASSY-HEAD,RH CUT					1.00	633.00	20.00	506.40
M COVER-FR BUMPER DO					1.00	262.00	20.00	209.60
M GRILLE-FRONT BUMPER CUT nn					1.00	36.00	20.00	28.80
M MOULDING-FRONT BUMPER,RH nn					1.00	164.00	20.00	131.20
M LAMP ASSY-SIDE REPEATER,RH nn					1.00	328.00	20.00	262.40
M GRILLE ASSY-RADIATOR CUT nn					1.00	38.00	20.00	30.40
M GARNISH-RADIATOR GRILLE nn					1.00	84.00	20.00	67.20
M ABSORBER-FRONT BUMPER ENERGY nn BR					1.00	114.00	20.00	91.20
M STIFFNER-FR BPR LWR nn					1.00	497.00	20.00	397.60
M BEAM COMPLETE-FR BUMPER nn BR					1.00	675.00	20.00	540.00
M CARRIER ASSY-FRONT END MODULE					1.00	32.00	20.00	25.60
M ORNAMENT-KIA NO.115 MC								

Steve (LKK)

25/3/22, 1.09pm

OD-14 AL

EXCISE-?

P/P

My BL sy, 5.4ps

Confirm & accepted by: *[Signature]*

LKK Auto Consultants hence notify the Repairer of the following:

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Authorized signatory and company stamp

Nett 5,288.00

7% GST on 5288.00 370.16

Total Payable 5,658.16

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.