

## ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name LCV07996/PEH KIM HUAT Reg No/Reg Date SMG9788K / 08/01/201 Date In/Mileage 25/03/2022/ 0 Chassis No KNAF3416MK5024544 Engine No G4FGJH713520 Make/Model KIA/CERATO 1.6 A EX G333 Colour/Trim B4U GRAVITY BLUE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	24/03/2022/ 13:13	BLK	282 / Kevin Leong	48612			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE FRT BUMPER, SUPPORT & AFFECTED AREA					400			1200.00
E PNT98000 PAINT WORK ON FRT BUMPER PANEL								350.00
E PNT88000 REMOVE & INSTALL RADIATOR, CONDENSER FOR FACILITATE REPAIR					?			120.00
M SUNDRY TO TOP UP AIRCON GAS					?			80.00
A 54900099 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM								30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM								120.00
M SUNDRY TO SUPPLY FRT NUMBER PLATE WITH FRAME								50.00
M SUNDRY SUNDRIES					20			50.00
M LAMP ASSY-HEAD,RH / CUT					1.00	1247.00	20.00	997.60
M COVER-FR BUMPER / DO					1.00	633.00	20.00	506.40
M GRILLE-FRONT BUMPER / CUT					1.00	262.00	20.00	209.60
M MOULDING-FRONT BUMPER,RH / ?					1.00	36.00	20.00	28.80
M LAMP ASSY-SIDE REPEATER,RH / ?					1.00	164.00	20.00	131.20
M GRILLE ASSY-RADIATOR / CUT					1.00	328.00	20.00	262.40
M GARNISH-RADIATOR GRILLE / ?					1.00	38.00	20.00	30.40
M ABSORBER-FRONT BUMPER ENERGY / ?					1.00	84.00	20.00	67.20
M STIFFNER-FR BPR LWR / ?					1.00	114.00	20.00	91.20
M BEAM COMPLETE-FR BUMPER / ?					1.00	497.00	20.00	397.60
M CARRIER ASSY-FRONT END MODULE / ?					1.00	675.00	20.00	540.00
M ORNAMENT-KIA NO.115 / PK					1.00	32.00	20.00	25.60
LKK Auto Consultants hence notify the Repairer of the following: • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "not to be" basis • No illegal modification(s) is allowed • Supplementary items must be surveyed and is subject to final approval by insurance Company								
Confirm & accepted by								
Authorized signatory and company stamp								
Steve (LKK) 25/3/22, 1.0pm					OD-AL AL EXCISE-? PIP			
					My BL 14, 3 djs			
					Nett 5,288.00			
					7% GST on 5288.00			
					Total Payable 5,658.16			

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.