



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name LCV07996/PEH KIM HUAT Reg No/Reg Date SMG9788K / 08/01/201 Date In/Mileage 25/03/2022/ 0 Chassis No KNAF3416MK5024544 Engine No G4FGJH713520 Make/Model KIA/CERATO 1.6 A EX G333 Colour/Trim B4U GRAVITY BLUE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	24/03/2022/ 13:13	BLK	282 / Kevin Leong	48612			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000	REPLACE FRT BUMPER, SUPPORT & AFFECTED AREA							1200.00
E PNT98000	PAINT WORK ON FRT BUMPER PANEL							350.00
E PNT88000	REMOVE & INSTALL RADIATOR, CONDENSER FOR FACILITATE REPAIR							120.00
M SUNDRY	TO TOP UP AIRCON GAS							80.00
A 54900099	CHECK WIRING & CHASSIS ELECTRICAL SYSTEM							30.00
A 10028901	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM							120.00
M SUNDRY	TO SUPPLY FRT NUMBER PLATE WITH FRAME							50.00
M SUNDRY	SUNDRIES							50.00
M LAMP ASSY-HEAD,RH					1.00	1247.00	20.00	997.60
M COVER-FR BUMPER					1.00	633.00	20.00	506.40
M GRILLE-FRONT BUMPER					1.00	262.00	20.00	209.60
M MOULDING-FRONT BUMPER,RH					1.00	36.00	20.00	28.80
M LAMP ASSY-SIDE REPEATER,RH					1.00	164.00	20.00	131.20
M GRILLE ASSY-RADIATOR					1.00	328.00	20.00	262.40
M GARNISH-RADIATOR GRILLE					1.00	38.00	20.00	30.40
M ABSORBER-FRONT BUMPER ENERGY					1.00	84.00	20.00	67.20
M STIFFNER-FR BPR LWR					1.00	114.00	20.00	91.20
M BEAM COMPLETE-FR BUMPER					1.00	497.00	20.00	397.60
M CARRIER ASSY-FRONT END MODULE					1.00	675.00	20.00	540.00
M ORNAMENT-KIA NO.115					1.00	32.00	20.00	25.60

Confirm & accepted by

Nett 5,288.00
7% GST on 5288.00 370.16
Total Payable 5,658.16

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.