

BIFROST AUTO PTE LTD

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT

#01-49 SINGAPORE 415875

Tel: +65 64524457

Fax: +65 64524584

Company Reg No: 201929175W

Repair Estimate

Vehicle number: GBL1268B

Make & Model: Kia K2500

Chassis number: KNCSJX76M7517885

Date of survey: 25/3/2022

Name of surveyor: T. Lim / Mr.

Contacts: _____

2021

No.	Description of spare parts	Qty	Amount S\$
1	Tailgate	1	\$1050.00 1284.35
2	Tailgate RH hinge	1	\$ 119.00
3	Tailgate centre hinge	1	\$78.50 119.00
4	Tailgate LH hinge	1	\$ 119.00
5	Tailgate RH flip lock	1	\$68.70 123.00
6	Tailgate LH flip lock	1	\$68.70 123.00
7	Tailgate lower panel	1	\$ ✓ 458.80
8	RH taillamp assy	1	\$ ✓ 155.00
9	RH taillamp panel	1	\$ 358.00
10	LH taillamp assy	1	\$ ✓ 155.00
11	LH taillamp panel	1	\$ 358.00
12	Rear number plate lamp	1	\$124.00 138.00
13	Spare tyre carriage	1	\$ 428.00

DDV ✓
 NDX ✓
 NEC ✓
 NDX ✓
 BT ✓
 BT ✓
 BT ✓
 CUT ✓
 NDX ✓
 CUT ✓
 NDX ✓
 BR ✓
 NDX ✓

\$ 3,838.15
 Parts less 10% \$ 383.82
 Total \$ 3,454.34

No.	Special Nett Items		Amount S\$
1	Tailgate inner aluminium panel	1	\$500.00 750.00
2	Tailgate inner aluminium panel rivets	1set	\$30.00 80.00
3	Tailgate "70km/h" sticker	1	\$20.00 50.00
4	Tailgate "13pax" sticker	1	\$20.00 50.00
5	Tailgate advertisement sticker	1	\$250.00 480.00
6	Tailgate "C&C" emblem	1	\$50.00 85.00
7	Rear number plate	1	\$40.00 70.00
8	Rear reverse sensor	1set	\$200.00 280.00
9	Rear underrun bumper	1	\$450.00 1200.00

DDV ✓
 NEC ✓
 NEC ✓
 NEC ✓
 BT ✓
 SC ✓
 BT ✓

Total: \$ 3,045.00

No.	Labour and painting	Amount S\$
1	Labour charges to remove, check, replace and reinstall damages bodyparts. To panel beating, cut/weld and realign all affected panels and areas	\$ 800.00 1,200.00
2	Spray painting on affected areas and panels	\$ 600.00 1,200.00
3	Check wiring and lighting system on affected areas	\$ 100.00
4	Apply rust coating chemical on affected areas and panels	\$ 80.00
5	Remove and replace rear reverse sensors to assist repair	\$ 60.00 150.00
Total:		\$ 2,730.00

Agreed Amount: _____ (Part by Part / Lump sum)
Working days: 7

Spare Parts: \$ 3,454.34
Special Nett: \$ 3,045.00
Labour: \$ 2,730.00

Total Amount: \$ 9,229.34

14,703.74

Survey & Resurvey
25/3/2022
1230 hrs
TBrum Lin

Parts 4102.93
SN 1560.00
Labour 1460.00
7122.93
@20% 1424.57
5698.26

LS 5700/-

TBrum Lin
28/4/2022

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

BIFROST AUTO PTE LTD

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT

#01-49 SINGAPORE 415875

Tel: +65 64524457

Fax: +65 64524584

Company Reg No: 201929175W

Parts price revised and Supplementary

Vehicle number: GBL1268B

Make & Model: Kia K2500

No.	Description of spare parts	Qty	Amount
1	RH side gate	1	\$ 1200.00 1,308.00
2	LH side gate	1	\$ 1200.00 1,308.00

✓ DD
✓ DD

\$ 2,616.00

-10% \$ 261.60

\$ 2,354.40

No.	Description of spare parts (Special Nett)	Qty	Amount
1	RH side gate inner aluminium panel	1	\$ 880.00
	RH side gate inner aluminium panel rivets	1set	\$ 80.00
	LH side gate inner aluminium panel	1	\$ 880.00
	LH side gate inner aluminium panel rivets	1set	\$ 80.00

NDX

\$ 1,920.00

No.	Labour	Amount
1	labour charges for supplementary	\$ 600.00
2	Spray painting for supplementary	\$ 600.00

NNX

Resurvey
25/3/2003T. Lim
14 others

\$ 1,200.00

Spare Parts: \$ 2,354.40

Special Nett: \$ 1,920.00

Labour: \$ 1,200.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and subject to final approval from Insurance Company

Noted by Repairer

Total Amount: \$ 5,474.40