

MBM WHEELPOWER PTE. LTD.

YOUR REF.: SLJ7189Z

OUR REF.: SKP9838B

TO: INDIA INSURANCE

CC: MOTOR CLAIMS DEPARTMENT

FAX:

Not Notified
11 Lmp @ 23,400/hr
Presumy After Paim
9 days

DATE: 23 March 2022
FROM: Alvin Koh
FAX: 64525333
CONTACT: 81387188
MAKE & MODEL: JAGUAR XF 3.0 V6 LUXURY
CHASSIS NO.: SAJAC05D8BFR97368
ENGINE NO.: 591556333FC
YEAR MADE: 2010
ACCIDENT DATE: 23 March 2022

ESTIMATE FOR VEHICLE NO.: SKP9838B

NO.	DESCRIPTION	PART NO.	QTY.	LIST PRICE
1	FRONT WINDSCREEN		1	\$ 3,515.00 X
2	FRONT WINDSCREEN MOULDING		1	\$ 279.00
3	ROOF LINING <i>2910</i>	<i>Reform</i>	1	\$ 3,856.00
4	AIRBAG ROOF RH	<i>Butz</i>	1	\$ 1,862.00
5	AIRBAG DRIVER SEAT	<i>u</i>	1	\$ 1,672.00
6	AIRBAG CONTROL UNIT	<i>u</i>	1	\$ 1,720.00
7	SAFETY BELT DRIVER		1	\$ 914.00
8	SAFETY BELT BUCKLE DRIVER		1	\$ 787.00
9	SAFETY BELT PASSENGER		1	\$ 914.00
10	SAFETY BELT BUCKLE PASSENGER		1	\$ 787.00
11	DRIVER SEAT UPHOLSTERY	<i>Tn</i>	1	\$ 2,850.00
12	FRONT DOOR RH	<i>By</i>	1	\$ 4,865.00
13	FRONT DOOR FRAME CHROME UPPER RH	<i>Sn</i>	1	\$ 965.00
14	FRONT DOOR FRAME CHROME LOWER RH	<i>Sn</i>	1	\$ 642.00
15	FRONT DOOR PILLAR GARNISH RH	<i>Sn</i>	1	\$ 341.00
16	FRONT DOOR WEATHERSTRIP RH	<i>u</i>	1	\$ 290.00
17	FRONT DOOR HINGE RH UPPER RH		1	\$ 174.00
18	FRONT DOOR HINGE RH LOWER RH		1	\$ 174.00
19	FRONT DOOR OUTER HANDLE RH		1	\$ 718.00
20	FRONT DOOR POWER WINDOW LIFTER RH		1	\$ 794.00
21	FRONT DOOR INNER BOARD RH		1	\$ 3,145.00
22	FRONT DOOR WINDOW GLASS RH		1	\$ 684.00
23	REAR DOOR RH		1	\$ 4,865.00
24	REAR DOOR FRAME CHROME UPPER RH		1	\$ 965.00
25	REAR DOOR FRAME CHROME LOWER RH		1	\$ 642.00
26	REAR DOOR PILLAR GARNISH RH		1	\$ 341.00
27	REAR DOOR WEATHERSTRIP RH		1	\$ 285.00
28	REAR DOOR HINGE RH UPPER RH		1	\$ 174.00
29	REAR DOOR HINGE RH LOWER RH		1	\$ 174.00
30	REAR DOOR OUTER HANDLE RH		1	\$ 718.00
31	REAR DOOR POWER WINDOW LIFTER RH		1	\$ 894.00
32	REAR DOOR INNER BOARD RH		1	\$ 3,145.00

MBM WHEELPOWER PTE. LTD.

160 SIN MING DRIVE, #06-

SIN MING AUTOCIT

6262 8888 F 6452 53

COMPANY REG. NO.: 200204110

- 33 REAR FENDER RH
34 SIDE SKIRT RH
35 REAR WINDSCREEN
36 REAR WINDSCREEN MOULDING
37 REAR DRIVE SHAFT RH
38 REAR UPPER ARM RH
39 REAR LOWER ARM RH
40 REAR SHOCK ABSORBER RH
41 REAR KNUCKLE ARM RH
42 REAR WHEEL HUB + BEARING RH
43 REAR TIE ROD END RH

671 489
1196 541
382

\$	R	X	6,852.00
\$	mg/cm?		1,420.00 ✓
\$	On	X	2,850.00
\$	nn	X	298.00
\$	R		2,470.00
\$	Di7		537.00
\$	B7		689.00
\$	R		575.00
\$	nd	✓	1,205.00
\$	B/H/nc		684.00
\$	R		589.00

TOTAL: \$ 62,320.00
LESS 10%: \$ (6,232.00)
PARTS TOTAL: \$ 56,088.00

SPECIAL NETT

- BODY SEALANT
WINDSCREEN SEALANT FRONT
WINDSCREEN SEALANT REAR
REAR SPORTS RIM RH

1220

1	\$	nn	X	80.00
1	\$	40sm		80.00
1	\$	nn		80.00 X
1	\$	nd	✓	1,485.00

LABOUR

- TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS
TO REMOVE & REPLACE FRONT WINDSCREEN
TO REMOVE & REPLACE REAR WINDSCREEN
TO DISMANTLE & TRANSFER FRONT DOOR FITTINGS & MECHANISM TO NEW DOOR
TO DISMANTLE & TRANSFER REAR DOOR FITTINGS & MECHANISM TO NEW DOOR
TO REMOVE & INSTALL REAR UPHOLSTERY TO FACILIATE REPLACE REAR FENDER RH
TO DISMANTLE AND REPLACE REAR RH UNDERCARRIAGE
TO REMOVE & REPLACE ROOF LINING
TO REMOVE AND REFIT FUEL TANK FIXTURE TO FACILIATE REPAIRS
TO RE-PROGRAM SRS AIR BAG CONTROL UNIT
TO REMOVE & REPLACE SRS AIR BAG CONTROL UNIT
TO REMOVE & REPLACE SAFETY BELT DRIVER
TO REMOVE & REPLACE SAFETY BELT BUCKLE DRIVER
TO REMOVE & REPLACE SAFETY BELT PASSENGER
TO REMOVE & REPLACE SAFETY BELT PASSENGER
TO REMOVE & REPLACE AIRBAG DRIVER SEAT
TO REMOVE & REPLACE DRIVER SEAT UPHOLSTERY
TO CONDUCT ALL WHEEL COMPUTERISED ALIGNMENT
TO RESET ENGINE WARNING LIGHT (ABS, SRS, ECU MEMORY & ETC)
TO CHECK & RECONNECT ALL NECESSARY WIRING
TO APPLY ANTI RUST COATING
TO SPRAY PAINT ON THE AFFECTED AREAS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

\$	1000l	2,500.00
\$	120l	150.00
\$	nn	X 150.00
\$	80l	140.00
\$	80l	140.00
\$	NN	X 150.00
\$	200l	350.00
\$	150l	400.00
\$	nn	X 140.00
\$	300l	{ 450.00
\$		{ 250.00
\$		{ 200.00
\$	nn	X { 200.00
\$		{ 200.00
\$	180l	{ 400.00
\$		{ 300.00
\$	60l	150.00
\$	200l	250.00
\$	30l	50.00
\$	60l	80.00
\$	1000l	1,600.00

TOTAL: \$ 66,263.00
7% GST: \$ 4,638.41
GRAND TOTAL: \$ 70,901.41

MBM WHEELPOWER PTE. LTD.
160 SIN MING DRIVE, #06-02
SIN MING AUTOCITY
t 6262 8888 f 6452 5333
COMPANY REG. NO.: 200204110W

MBM WHEELPOWER PTE. LTD.

YOUR REF.: SLJ7189Z

OUR REF.: SKP9838B

TO: INDIA INSURANCE

CC: MOTOR CLAIMS DEPARTMENT

FAX:

SUPPLEMENTARY FOR VEHICLE NO.: SKP9838B

DATE: 30 March 2022

FROM: Alvin Koh

FAX: 64525333

CONTACT: 81387188


MAKE & MODEL: JAGUAR XF 3.0 V6 LUXURY

CHASSIS NO.: SAJAC05D8BFR97368

ENGINE NO.: 591556333FC

YEAR MADE: 2010

ACCIDENT DATE: 23 March 2022



NO.	DESCRIPTION	PART NO.	QTY.	LIST PRICE
1	FRONT DOOR INNER SPONGE RH		\$	CM 248.00 ✓
2	FRONT DOOR INNER HANDLE BRACKET HOLDER RH		\$	CM 480.00 ✓
3	FRONT DOOR SPEAKER HOLDER BOARD RH		\$	CM 745.00 ✓

TOTAL: \$	1,473.00
LESS 10%: \$	(147.30)
PARTS TOTAL: \$	1,325.70

SPECIAL NETT

REAR TYRE MICHELIN PILOT SPORT 4 245/45ZR18	\$	CM 490.00 ✓ 34352
---	----	----------------------

LABOUR

TO REMOVE, RENEW & REFIT REAR RH TYRE	\$	201 80.00
---------------------------------------	----	-----------

TOTAL: \$	-
7% GST: \$	-
GRAND TOTAL: \$	-

MBM WHEELPOWER PTE. LTD.

160 SIN MING DRIVE, #06-02

SIN MING AUTOCITY

T 6262 8888 F 6452 5333

COMPANY REG. NO.: 200204110W