

KY AUTO PTE LTD

25 Kaki Bukit Road 4 #05-23 Synergy Building S417800

M (65) 9807 3304 Mr. Yap

F (65)

Email : kyautosg@gmail.com

Date: 21/03/2022

SLM9864D Mazda 3 - SM B1327X (MS first cap) ✓

Damaged Area: Right Side Portion

Parts / Material :

1	Front door o/s	\$	1,059.60	-DT
2	Front door glass outer moulding o/s <i>SLC X</i>	\$	175.80	-nec X Svc
3	Front door outer handle garnish o/s	\$	176.80	X <i>SLC</i>
4	Front door outer handle cap o/s	\$	95.40	X <i>r</i>
5	Front door outer handle sensor o/s	\$	155.60	^, X Svc
6	Front door pillar garnish o/s (Black) X <i>NN</i>	\$	196.20	X Svc
7	Front door top hinge o/s X <i>SLC</i>	\$	98.20	^, X Svc
8	Front door lower hinge o/s X <i>SLC</i>	\$	95.10	^, X Svc
9	Front door checker o/s X <i>SLC</i>	\$	115.40	-nec X Svc
10	Front door inner lock o/s	\$	240 368.40	-jan
11	Front door inner trim board o/s	\$	495.80	^, -4t
12	Front door power window motor o/s <i>come one piece.</i>	\$	451 256.60	^, -cut
13	Front door regulator gear board o/s	\$	386.70	^, -cut
14	Front door speaker o/s	\$	295.60	^, X Svc
15	Front door weather strip o/s	\$	299.80	^, X Svc
16	Centre door pillar o/s	\$	486.70	X <i>r</i>
17	Tyre pressure sticker o/s	\$	106.70	-nec
18	Chassis frame sticker	\$	112.40	-nec
19	Rocker panel o/s	\$	587.60	-DT
20	Rear door o/s	1048 \$	1,148.90	-DT
21	Rear door top hinge o/s	\$	95.60	^, X Svc
22	Rear door lower hinge o/s	\$	96.40	^, X Svc
23	Rear door checker o/s	\$	115.80	-nec DLS
24	Rear door inner lock o/s	\$	356.90	^, X Svc
25	Rear door inner trimboard o/s	\$	498.70	^, X Svc
26	Rear door regulator gear board o/s	\$	382.60	^, X Svc

Parts : \$ 8,259.30 *42169*

Less Parts 20% : \$ 1,651.86

Total Parts : \$ 6,607.44 *337352*

Special Net Items :

Front door inner trimboard clips
Front door regulator board rivets
Rear door inner trimboard clips
Rear door regulator board rivets

}nec

\$ 55.00 *25*
\$ 28.00 *14*
\$ 55.00 *25*
\$ 28.00 *14*

Total S/N Parts : \$ 166.00

Labour :

To Repair, Remove & Renew On Affected Rear Accident Areas @ SGD 300.00 per	\$	1,400.00	600
To Putty, Spray Paint on Affected Rear Accident Areas @ SGD 300.00 per panel	\$	1,400.00	600
(Front Door, Rear Door, Centre Door Pillar, Rocker Panel)			
To Check & Re-Connect all electrical wiring	\$	50.00	30
To Remove & Transfer Front Door Components to Facilitate Repairs	\$	120.00	60
To Remove & Transfer Rear Door Components to Facilitate Repairs	\$	150.00	60
To Remove & Install Interior Seat, Trims, Garnish to Facilitate Repairs	\$	150.00	XNN
To Rust Proof Affected Areas	\$	250.00	40
To Conduct Nano Coating on Affected Areas	\$	500.00	XNN
Total Labour :	\$	4,020.00	

TOTAL PARTS :	\$	6,607.44
TOTAL SPECIAL NET ITEM:	\$	166.00
TOTAL LABOUR :	\$	4,020.00
TOTAL REPAIR COST :	\$	10,793.44

4841.52

3873

= ~~3900~~ 3900

Thuan@lkh auto-low

82235769

25/3/22 1600

LS repair

5clays wp

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: