



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile CS3/LPC21011664/Gvy3-1			
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555	Ref: CS3/LPC21011664/Gvy3-1 Date: 16/11/2021 24/03/2022 Code: LPC2		
1. Policy Particulars :- (THIRD PARTY CLAIM)			
Insured Veh. GBD 7967U	Veh. Inspected SLC 5508L		
Policy No.	Coverage (\$) 0.00		
Claim No. 21/21/21/NC05/025141	Excess (\$) 0.00		
Assign From GERALD POH	Assign Date 16/11/2021 24/03/2022		
2. Vehicle Particulars & Condition			
Make & Model	c.c 0		
Engine No. HIDDEN	Year of Reg.		
Chassis No.	Colour		
Odometer -	Steering		
Brakes	Modification		
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date 10/11/2021	Inspection Date 16/11/2021		
Survey held at	KUM CHEW MOTOR WORKSHOP 160 SIN MING DRIVE #05-08 SIN MING AUTOCITY SINGAPORE 575722		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			