

AUTOMAX SURVEY

Blk 110 Bedok Reservoir Road , #07-280, Singapore 470110
Mobile : 9855 6879 Email : automaxsurvey@gmail.com
Registration No. 53110062J

Report Ref : TP21090041

Date: 24 FEB 2022

Swee Heng Motor Leasing Pte Ltd
c/o Hup Ley Huat Motor Spray Painting Services
Blk 1, #01- 35
Kaki Bukit Ave 6
Singapore 417883

THIRD PARTY SURVEY ACCIDENT OCCURED ON 22 Sept 2021

Workshop Name and Address

Hup Ley Huat Motor Spray Painting Services
Blk 1, #01- 35
Kaki Bukit Ave 6
Singapore 417883

As per your instruction dated 29 Sept 2021
We have carried out a physical inspection on the said
We enclosed herewith our report and findings as follows:

with regard to the above matter.
SMJ4042X

1. VEHICLE PARTICULARS

Registration No : SMJ4042X
Model : VOLVO S60 T4 1.6
Year / Capacity : Oct 2012 / 1599 cc
Chassis No : YV1FS48HBD2186216

Engine No : B4164T1104281
Mileage : 137 363 km
Colour : Meatlic white

2. TYRES CONDITION

	<u>Size</u>	<u>Made</u>	<u>Balance</u>	<u>Rim</u>
FRONT O/S :	205/40/R18	Bridgestone	9.00 mm	Sport
REAR O/S :	205/40/R18	Bridgestone	9.00 mm	Sport
FRONT N/S :	205/40/R18	Bridgestone	9.00 mm	Sport
REAR N/S :	205/40/R18	Bridgestone	9.00 mm	Sport

AUTOMAX SURVEY

Blk 110 Bedok Reservoir Road , #07-280, Singapore 470110

Mobile : 9855 6879

Email : automaxsurvey@gmail.com

Registration No. 53110062J

3. DESCRIPTION OF DAMAGES

At the time of inspection, we noted that the vehicle has sustained an impact damages on the rear portion(s). For more detail of the damages, please see photograph attached.

4. Estimated normal period of repair : 8 working days to complete
5. In accordance to your instruction, we have **Not Authorised** repair to the vehicle and the survey done on a **"Without Prejudice"** basis. We hope that this report will be of assistance to you in dealing with the matter.
6. Should you discover any discrepancy in the report, please kindly notify us **within 1 week**, or the report will be treated as correct.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicles and/or other accidents in other legal proceedings.

Vehicle Number : SMJ4042X

SPARE PARTS

QTY	PARTS DESCRIPTION	CONDITION	Workshop Estimation (S\$)	Our Revised Estimation (S\$)
<i>List Items</i>				
1 pc	Rear bumper	bend/deformed	\$ 1,950.00	\$ 1,950.00
2 pcs	Rear bumper side retainer	bent	\$ 200.00	\$ 200.00
2 pcs	Rear bumper side attachment	bent	\$ 120.00	\$ 120.00
10 pcs	Rear bumper clips	necessary	\$ 100.00	\$ 100.00
1 pc	Rear bumper reinforcement	bent	\$ 562.80	\$ 562.80
1 pc	Rear end panel	bent/distorted - repair	\$ 798.00	\$ -
1 pc	Rear end panel top garnish	bent/distorted	\$ 425.00	\$ 425.00
Parts Sub-Total			\$ 4,155.80	\$ 3,357.80
Discount 10.00%			\$ 415.58	\$ 335.78
			\$ 3,740.22	\$ 3,022.02

Vehicle Number : SMJ4042X

SPARE PARTS

QTY	PARTS DESCRIPTION	CONDITION	Workshop Estimation (S\$)	Our Revised Estimation (S\$)
<i>Special Nett Items</i>				
1 set	Reverse sensor	electronically shocked	\$ 280.00	\$ 250.00
Special Nett Sub-Total			\$ 280.00	\$ 250.00
Spare Parts Total			\$ 4,020.22	\$ 3,272.02

LABOUR COST


S/No	JOB DESCRIPTIONS	Workshop Estimation (S\$)	Our Revised Estimation (S\$)
	Spare PartsTotal c/f	\$ 4,020.22	\$ 3,272.02
1	To tuff coat affected areas	\$ 180.00	\$ 150.00
2	To remove and replace interior upholstery	\$ 180.00	\$ 150.00
3	To remove and replace reverse sensor	\$ 180.00	\$ 150.00
4	To respray affected areas	\$ 1,600.00	\$ 1,400.00
5	To renew damaged parts, straighten and repair rear chassis member, rear fender inner panel , rear door and aligned all parts.	\$ 1,800.00	\$ 1,600.00
6	To do up paint protection coating	\$ 1,200.00	\$ 1,200.00
	Total	\$ 7,960.22	\$ 6,722.02

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a Lump Sum Repair of :

\$ 5,500.00


Fong Kok Heng
Qualified Appraiser










SURVEY

1019



AUTOMAX









SURVEY
AUTOMAX



SURVEY
AUTOMAX



SURVEY
AUTOMAX



