



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2203813

INV Date 20/06/2022

Reference CC4/LPC22002754/Eea3q2

Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. CB 6982E
Insured Veh. XD 6627Y
Claim No. 21/22/22/VC00/025591
Policy No. Z/21/VC00/112184
Accident Date 24/03/2022
Inspection Date 30/03/2022

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CC4/LPC22002754/Eea3q2 Date: 20/06/2022 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	XD 6627Y	Veh. Inspected	CB 6982E	
Policy No.	Z/21/VC00/112184	Coverage (\$)	0.00	
Claim No.	21/22/22/VC00/025591	Excess (\$)	0.00	
Assign From	GERALD	Assign Date	25/03/2022	
2. Vehicle Particulars & Condition				
Make & Model	HIGER KLQ6109Q 6.7L MT ABS TURBO	c.c	6900	
Engine No.	ISBE430021953154	Year of Reg.	201	
Chassis No.	LKLR1FSJ5CCB579871	Colour	MULTICOLOUR	
Odometer	770747 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	295/80 R22.5	DUNLOP	4 mm	
L/H Front Tyre	295/80 R22.5	DUNLOP	4 mm	
R/H Rear Tyre	295/80 R22.5	DUNLOP	4 mm	
L/H Rear Tyre	295/80 R22.5	DUNLOP	4 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	24/03/2022	Inspection Date	30/03/2022	
Survey held at	CONNECT3 7 OLD TOH TUCK ROAD SINGAPORE 597648			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			8 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. CB 6982E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR TAILGATE	DENTED	4,200.00	4,000.00
1	REAR TAILGATE INNER STRUCTURE FRAME	DENTED	1,850.00	1,700.00
1	REAR TAILGATE CENTER LOCK	BENT	588.00	588.00
2	REAR TAILGATE HINGES	BENT	770.00	770.00
2	REAR TAILGATE GAS SPRING	NOT NECESSARY	340.00	-
2	REAR TAILGATE INNER SENSOR	NOT NECESSARY	460.00	-
1	REAR TAILGATE LOCK	NOT NECESSARY	532.00	-
2	REAR TAILGATE RH & LH BRACKET	NOT NECESSARY	392.00	-
1	REAR BUMPER	DENTED	1,650.00	1,650.00
2	REAR BUMPER RH & LH BRACKET	BENT	510.00	510.00
1	REAR BUMPER INNER STRUCTURE	DENTED	850.00	850.00
2	REAR LH & RH BUMPER LOWER RELECTOR	NOT NECESSARY	370.00	-
1	REAR EXHAUST TIP	NOT NECESSARY	980.00	-
1	REAR EXHAUST MID PIPE	NOT NECESSARY	1,360.00	-
1	REAR EXHAUST BRACKET	NOT NECESSARY	135.00	-
1	REAR PULLEY	NOT NECESSARY	2,380.00	-
1	REAR CRANK PULLEY	NOT NECESSARY	2,750.00	-
1	RADIATOR SPARE TANK	NOT NECESSARY	1,420.00	-
1	TENSIONER PULLEY	NOT NECESSARY	1,260.00	-
1	FAN BLADE SET	NOT NECESSARY	670.00	-
1	FAN BELT SET	NOT NECESSARY	890.00	-
1	REAR FAN MAIN PULLEY	NOT NECESSARY	1,720.00	-
1	FAN COWLING	NOT NECESSARY	1,430.00	-
1	FAN HOUSING BRACKET	NOT NECESSARY	350.00	-
1	FAN HOUSING	NOT NECESSARY	1,760.00	-
1	FAN HOUSING COVER	NOT NECESSARY	980.00	-
	LESS 10% DISCOUNT		-	-1,006.80
			30,597.00	9,061.20

Report Ref No. CC4/LPC22002754/Eea3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>SPECIAL NETT ITEMS</u>			
1	60KM/H STICKER	NECESSARY	15.00	15.00
			15.00	15.00
	<u>LABOUR</u>			
1	CHECK WIRING		150.00	80.00
1	REMOVE & REFIT EXHAUST		200.00	-
1	LABOUR CHARGES		2,400.00	1,800.00
1	SPRAY PAINTING		1,000.00	700.00
			3,750.00	2,580.00
GRAND TOTAL			34,362.00	11,656.20
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				9,300.00

Report Ref No. CC4/LPC22002754/Eea3q2

CHEN TSUE YEE

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. CB 6982E

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. CB 6982E

RE-INSPECTION

