

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 # 01-61
SINGAPORE 408717

Tel : 6748 4422/ 6745 4422 Fax : 6747- 6720 REG NO 200501102H

2017 8pt
VSKYBAM 2020145957

EQ Insurance Co. Ltd
22 Gemmill Lane
Singapore 069257
Tel : 6223 - 9433
Fax : 6224 - 3903

Veron

Quotation
DATE : 05.04.2022
VEH NO : GBG6870E
MODEL : Nissan NV200
D O A : 23.03.202
YR REF : XE4536J

Attn : Motor Claim Dept

(Pls arrange vehicle survey & check liability)

RE ESTIMATE FOR ACCIDENT REPAIR GBG6870E (NISSAN NV200)

<u>Item</u>	<u>Description</u>	<u>Qty</u>	<u>Amt</u>
NO	LIST ITEMS		
1	Rear Bumper <i>Del d</i>	1	632.70 ✓
2	Rear Bumper Side Holder - LH & RH <i>new</i>	2	86.60 ✓
3	Rear Bumper Reflector - LH & RH <i>new</i>	2	85.00 x
4	Rear Bumper Sponge <i>new</i>	1	128.90 ✓
5	Rear End Panel Outer Panel <i>Distorted</i>	1	485.20 ✓
6	Rear End Panel Top Garnish <i>Del d</i>	1	128.40 ✓
7	Tailgate - LH <i>Distorted</i>	1	1,545.00 ✓
8	Tailgate Lower Lock - LH <i>new</i>	1	159.30 ✓
9	Tailgate Outer Garnish - LH <i>Del d</i>	1	351.50 ✓
10	Tailgate Inner Trimboard - LH <i>new</i>	1	145.20 x
11	Tailgate Hinge (Upper & Lower) - LH <i>new</i>	2	190.20 x
12	Tailgate Check - LH <i>new</i>	1	82.40 x
13	Nissan Logo <i>new</i>	1	64.90 ✓
14	NV200 Emblem <i>new</i>	1	88.00 ✓
15	Tailgate - RH <i>Distorted</i>	1	1,102.50 ✓
16	Tailgate Lower Lock - RH <i>new</i>	1	159.30 ✓
17	Tailgate Inner Trimboard - RH <i>new</i>	1	145.40 x
18	Tailgate Frame <i>Wentleshipe - cut</i>	1	285.80 ✓
19	Tailgate Check - RH <i>new</i>	1	82.40 x
20	Spare Tyre Carrier <i>new</i>	1	269.80 x
21	Spare Tyre Carrier Lock Screw <i>new</i>	1	64.50 x
22	Taillamp - LH & RH <i>LH cracked</i>	2	517.40 258.70
			\$ 6,704.80
Less 10%			(670.48)
			\$ 6,034.32

5476.90
4925.21

RE : ESTIMATE FOR ACCIDENT REPAIR GBG6870E (NISSAN NV200)

S/NET ITEMS

1	Rear Bumper Clips <i>Her</i>	1 set	30.00 ✓
2	Reverse Sensor <i>David</i>	1 set	280.00 <i>200</i>
3	Rear End Panel Sealant <i>nr</i>	1	60.00 ✓
4	Tailgate Glass Sealant - LH <i>nr</i>	1	60.00 <i>50</i>
5	70km/h Sticker <i>nr</i>	1	10.00 ✓
6	Tailgate Glass Sealant - RH <i>nr</i>	1	60.00 <i>50</i>
7	Tailgate Surround Moulding - LH <i>nr</i>	1	80.00 ✓
8	5 Pax Sticker <i>nr</i>	1	10.00 ✓
9	Advertisement Sticker <i>nr</i>	1	500.00 <i>450</i>
10	Rear Number Plate <i>Deled</i>	1	30.00 ✓
11	Rear Number Plate Holder <i>Deled</i>	1	30.00 ✓

\$ 1,150.00

Total Parts

\$ 7,184.32

LABOUR CHARGE

1	To knocking & pull out rear side portion & renew above parts	\$ 1,000.00 <i>800</i>
2	To putty & spray up paint works	\$ 1,000.00 <i>800</i>
3	To check wiring	\$ 50.00 <i>30</i>
4	To spray tuff coat	\$ 100.00 <i>80</i>
5	To remove reverse sensor	\$ 100.00 <i>50</i>
6	To transfer rear LH & RH tailgate fittings	\$ 200.00 <i>160</i>
7	To remove rear LH & RH tailgate glasses	\$ 160.00 <i>120</i>
8	To remove upholstery	\$ 100.00 <i>60</i>

Total Labour

\$ 2,730.00

Grand Total

\$ 9,914.32

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts

- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN

THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY

WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE

Total: 8029.21

M/S : G.H.K

06 Days