

ASS. REC. BY: Rasul

REF: CS/EH122002762/Rv43

369K

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SHB 5308A

at Workshop m/s STRIDES (SMET)

of 60, Woodlands Ind Pk Ek

Insured: GBB 9271R EGI

Policy No. \_\_\_\_\_


Claims No. CDMCG22000531

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)



Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SHB 5308A Yr Regn: 2017 / NOV

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or \_\_\_\_\_

Make: TOYOTA PRIMS HYBRID 1.8 CVT c.c 1798

Colour: MAROON A/C: Insured / Std / NI / NA

Sp. Reading: 411172 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: JTDKB3FU X03875400

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jaimmed / Leaked / Burnt or

Brake: Inorder / Jaimmed / Leaked / Burnt or

Modi: Nil / SRim / STD A/Rim or

Tyre Size: F: 195/65R15

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or SAILUN

Front Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 24/03/22 D.O.I. 25/03/22

Survey held at STRIDES (SMET)

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
6/5/22	Rasul informed LS \$3000 (red 11,098.20, 78%)

Date/Time, File Pass to?  : Preli. Report

: Final Report

Date/Time, File Return to?

2) 6/5/22-typist

Report Format: Merimen

Lump Sum / H.S.T. (\$3000)

Days Of Repair: 8

Resurvey No. of Trip: 1

Add Fee:  : Site Insp (\$ \_\_\_\_\_)

: Interview (\$ \_\_\_\_\_)

: Tech. Invs (\$ \_\_\_\_\_)

: Weekend (\$ \_\_\_\_\_)

Survey Fee:

Transportation:	_____
S + RS. SI	_____
Photos	_____
Others	_____

# Case Details

Case Reference Number : TAX/03/22/2051  
 Type of Repair : Accident Repair  
 Vehicle Registration Number : SHB5308A

Company Type : Strides Taxi Pte Ltd  
 Estimation ID : EST-17811-ID  
 Assigned By : Taxi Claims Manager Team

Insurance Company Name : ERGO Insurance Pte Ltd  
 Accident Date and Time : 24/03/2022 07:15 AM  
 Vehicle Age(In Months) : -

## Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 0

## Estimation Details

### Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	SMRT Recommendation				Repair/ Replace	Surveyor Approval		Remarks	
						List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)		Surveyor Quantity	Surveyor Final Price(\$)		Repair/Replace
Standard	Main			COVER, RR BUMPER ASSY	1	423.90	423.90	25.00	317.92	Replace	1	317.92	Replace	da
Standard	Main			REAR BUMPER REINFORCEMENT	1	318.80	318.80	25.00	239.10	Replace	1	239.10	Replace	bt
Standard	Main			PAD, RR BUMPER, RH & LH, 1	2	3.80	7.60	25.00	5.70	Replace	2	5.70	Replace	nee
Standard	Main			PAD, RR BUMPER, RH & LH, 2	2	3.80	7.60	25.00	5.70	Replace	2	5.70	Replace	nee
Standard	Main			PAD, RR BUMPER, RH & LH, 3	2	3.80	7.60	25.00	5.70	Replace	2	5.70	Replace	nee
Standard	Main			PAD, RR BUMPER, CTR	3	2.20	6.60	25.00	4.95	Replace	3	4.95	Replace	nee
Standard	Main			SEAL, RR BUMPER ARM, RH & LH	2	11.00	22.00	25.00	16.50	Replace	2	16.50	Replace	nee
Standard	Main			STOPPER, RR BUMPER, RH & LH	2	4.30	8.60	25.00	6.45	Replace	0	0	Not Give	Xan
Standard	Main			RETAINER, RR BUMPER, RH	1	112.70	112.70	25.00	84.53	Replace	0	0	Not Give	Xan
Standard	Main			RETAINER, RR BUMPER, LH	1	111.50	111.50	25.00	83.63	Replace	0	0	Not Give	Xan
Standard	Main			SEAL, RR BUMPER, RH	1	85.20	85.20	25.00	63.90	Replace	0	0	Not Give	Xan
Standard	Main			SEAL, RR BUMPER, LH	1	85.20	85.20	25.00	63.90	Replace	0	0	Not Give	Xan
Standard	Main			CLIPS PIECE, FRT & RR BUMPER	10	1.50	15.00	25.00	11.25	Replace	10	11.25	Replace	nee
Standard	Main			GUARD, RR BUMPER, LOWER	1	558.30	558.30	25.00	418.72	Replace	1	418.72	Replace	da
Standard	Main			FILLER, RR BUMPER, RH	1	119.90	119.90	25.00	89.93	Replace	1	89.93	Replace	ca

Total Spare Part Cost 7,955.09

Surveyor Total 2,056.21

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

Final Spare Part Cost 6,364.07

Final Sur Total 1,644.97

Item Type	Costing Type	Portion	Material Number	SMRT Recommendation						Surveyor Approval				Remarks	
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace		
Standard	Main			FILLER, RR BUMPER , LH	1	119.90	119.90	25.00	89.93	Replace	1	89.93	Replace	✓	can
Standard	Main			COVER, GUARD RR BUMPER LOWER	1	14.80	14.80	25.00	11.10	Replace	1	11.10	Replace	✓	de
Standard	Main			SENSOR REVERSE	1	180.00	180.00	0.00	180.00	Replace	1	180.00	Replace	✓	800
Standard	Main			ANTENNA, ELECTRICAL KEY	1	60.30	60.30	10.00	54.27	Replace	0	0	Not Give	✓	X11
Standard	Main			REAR BUMPER GROMMET SCREW	2	2.20	4.40	25.00	3.30	Replace	2	3.30	Replace	✓	re
Standard	Main			LENS & BODY, REAR COMBINATION LAMP , RH	1	438.10	438.10	10.00	394.29	Replace	0	0	Not Give	✓	X11
Standard	Main			LENS & BODY, REAR COMBINATION LAMP , LH	1	438.10	438.10	10.00	394.29	Replace	0	0	Not Give	✓	X11
Standard	Main			LENS & BODY ASSY , RR BUMPER , RH	1	486.80	486.80	10.00	438.12	Replace	0	0	Not Give	✓	X11
Standard	Main			LENS & BODY ASSY , RR BUMPER , LH	1	486.80	486.80	10.00	438.12	Replace	0	0	Not Give	✓	X11
Standard	Main			COVER, REAR COMBINATION LAMP, RH	1	54.00	54.00	25.00	40.50	Replace	0	0	Not Give	✓	X11
Standard	Main			COVER, REAR COMBINATION LAMP, LH	1	54.00	54.00	25.00	40.50	Replace	0	0	Not Give	✓	X11
Standard	Main			COVER, REAR FLOOR UNDER , RH	1	169.50	169.50	25.00	127.13	Replace	0	0	Not Give	✓	X11
Standard	Main			COVER, REAR FLOOR UNDER , LH	1	234.30	234.30	25.00	175.73	Replace	0	0	Not Give	✓	X11
Standard	Main			COVER, REAR FLOOR UNDER CENTER	1	222.60	222.60	25.00	166.95	Replace	0	0	Check	✓	?
Standard	Main			PANEL SUB-ASSY, FENDER REAR RH	1	824.80	824.80	25.00	618.60	Replace	0	0	Not Give	✓	X11
Standard	Main			LINER, REAR FENDER , RH	1	135.80	135.80	25.00	101.85	Replace	0	0	Not Give	✓	X11
Standard	Main			TAIL GATE PANEL SUB-ASSY, BACK DOOR	1	929.60	929.60	25.00	697.20	Replace	0	0	Not Give	✓	X11
Standard	Main			TAIL GATE WEATHERSTRIP, BACK DOOR	1	360.70	360.70	25.00	270.53	Replace	0	0	Not Give	✓	X11
Standard	Main			TAIL GATE DAM, BACK DOOR GLASS UPPER ADHESIVE	2	27.90	55.80	25.00	41.85	Replace	0	0	Not Give	✓	X11

Total Spare Part Cost 7,955.09

Surveyor Total 2,056.21

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

Final Spare Part Cost 6,364.07

Final Sur Total 1,644.97

SMRT Recommendation											Surveyor Approval			
OM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
Standard	Main			TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-ASSY	1	891.20	891.20	25.00	668.40	Replace	1	0	Repair	R
Standard	Main			NAME PLATE (HYBRID), LUGGAGE COMPARTMENT DOOR	1	52.30	52.30	25.00	39.22	Replace	1	39.22	Replace	new
Standard	Main			NAME PLATE (PRIUS), LUGGAGE COMPARTMENT DOOR	1	52.30	52.30	25.00	39.22	Replace	1	39.22	Replace	new
Standard	Main			NAME PLATE (PRIUS), LUGGAGE COMPARTMENT DOOR	1	52.30	52.30	25.00	39.22	Replace	1	39.22	Replace	new
Standard	Main			TAIL GATE LOCK ASSY, BACK DOOR	1	452.10	452.10	10.00	406.89	Replace	0	0	Not Give	X 27
Standard	Main			TAIL GATE LOCK COVER, BACK DOOR	1	25.30	25.30	25.00	18.98	Replace	0	0	Not Give	X 27
Standard	Main			TAIL GATE STRIKER ASSY, BACK DOOR	1	24.90	24.90	25.00	18.67	Replace	0	0	Not Give	X 27
Standard	Main			STRIDES LOGO	1	7.80	7.80	0.00	7.80	Replace	1	7.80	Replace	new
Standard	Main			STICKER DECAL 6555 8888	1	21.60	21.60	0.00	21.60	Replace	1	21.60	Replace	new
Standard	Main			NUMBER PLATE	1	35.00	35.00	0.00	35.00	Replace	0	0	Not Give	X 27
Standard	Main			NUMBER PLATE FRAME	1	25.00	25.00	0.00	25.00	Replace	0	0	Not Give	X 27
Standard	Main			END PANEL SUB-ASSY, BODY LOWER BACK	1	629.80	629.80	25.00	472.35	Replace	1	472.35	Replace	bf
Standard	Main			SPARE TYRE PANEL, PAN, REAR FLOOR	1	564.80	564.80	25.00	423.60	Replace	0	0	Not Give	X 27
Standard	Main			SEALANT SIKAFLEX	1	37.00	37.00	0.00	37.00	Replace	1	37.00	Replace	new
Total Spare Part Cost									7,955.09	Surveyor Total		2,056.21		
Lump Sum Discount (%)									20.00	Lump Sum Dis (%)		20		
Final Spare Part Cost									6,364.07	Final Sur Total		1,644.97		

**Labour's Cost Detail**

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR REAR PORTION	1,352.00	600	
Total:			1,352.00	600.00	

**Spray Cost Detail**

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY REAR FENDER RH	378.00	0 <i>Xan</i>	
2	Main	TO RESPRAY TAIL GATE	378.00	0 <i>Xan</i>	
3	Main	TO RESPRAY TAILGATE OUTSIDE GARNISH	180.00	100	
4	Main	TO RESPRAY REAR SPARE TYRE PANEL	180.00	0 <i>Xan</i>	
5	Main	TO RESPRAY REAR BUMPER	378.00	200	
6	Main	TO RESPRAY REAR PANEL	180.00	100	
<b>Total:</b>			<b>1,674.00</b>	<b>400.00</b>	

**Other Cost Detail**

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO WASH AND VACUUM	60.00	0 <i>Xan</i>	
2	Main	TO REPLACE SUNDRY PARTS	120.00	0 <i>Xan</i>	
3	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	200.00	40	
4	Main	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	40	
5	Main	TO TRANSFER REAR TAILGATE MECHANISM	120.00	0 <i>Xan</i>	
6	Main	TO REMOVE AND REFIX REAR WINDSCREEN	120.00	0 <i>Xan</i>	
<b>Total:</b>			<b>740.00</b>	<b>80.00</b>	

**Summary**

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	6,364.07	1,644.97
Total Labour Cost	1,352.00	600.00
Total Spray Painting	1,674.00	400.00
Other	740.00	80.00
<b>Overall Total</b>	<b>10,130.07</b>	<b>2,724.97</b>
Lump Sum Repair Option		<input checked="" type="checkbox"/>
Lump Sum Total	10,150.00	2,700.00
Surveyor Approved Amount		2,700.00

Estimator Assessment(\$)

Surveyor Assessment(\$)

No of Repair Days

10

6

Remarks

LUMP SUM REPAIR / RESURVEY AFTER REPAIR

Surveyor Name

Rasul

Signature



Save

Clear

Survey Date

25/03/2022

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

# SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

Date of Submission	25/03/2022 09:56 (SGT)
Date of Accident	24/03/2022 15:15 (SGT)
Exact Location of Accident	CTE, Singapore
Additional Location Information	CTE TOWARDS AYE (BEFORE PIE CHANGI EXIT)
Country/State of Loss	Singapore

## DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHB5308A
INSURED/POLICYHOLDER	
Is company?	Yes
Name Of Registered Owner	Strides Taxi Pte Ltd
Company Reg No	1XXXXX369K
Email Address	AUTO-SVCS-TARC@SMRT.COM.SG
Mobile Phone No	(Phone) +65-68662671
Alternative Phone No	(Office) +65-68662672

## VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Prius
Variant	-
Exact purpose for which vehicle was being used at time of accident	-
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Taxi
Transmission	Auto
CC	1800

## INSURANCE COMPANY

Name of Insurance Company	MS First Capital Insurance Ltd
Type of Coverage	ThirdParty
Fleet Policy	Yes
Policy Number	D-21097466MFSH
Cover Note Number	-

## DRIVER

Name of Driver	LEONG WAI KIONG
NRIC No	SXXXX033C

Date Of Birth	30/12/1974
Occupation	Outdoor
Date Of Driving Pass	20/09/2011
Driving experience	10 YEARS AND 6 MONTHS
Gender	Male
Mobile Number	(Phone) +65-68662671
Alt. Phone Number	-
Email Address	AUTO-SVCS-TARC@SMRT.COM.SG
Address	11
Address complement	-
Postcode	-
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Hirer
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	2
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

PASSENGER 1

Name	UNKNOWN
Gender	Male

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

I WAS TRAVELLING ALONG CTE TOWARDS AYE (BEFORE CHANGI EXIT) WITH ONE PASSENGER (MALE CAUCASIAN) ON BOARD. VEHICLE INFRONT STOPPED AND I STOPPED TOO. AFTER WHICH I FELT AN IMPACT AT THE REAR OF MY TAXI. A VEHICLE GBB9271R HAD COLLIDED ONTO THE REAR OF MY TAXI.

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Reasons for not uploading a video of the accident	FILE TOO BIG
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBB9271R
Vehicle Manufacturer	-
Vehicle Model	-

Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Commercial vehicle
Name of Driver	POH WEE CHUAN
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-



SKETCH PLAN

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that :

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.



Policyholder's Signature / Date & Time


Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

*Leong* 24/03/22

*LM* 24.3.2022

**Sketch Plan**



> Back to OneMotoring

### Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Company
Owner ID:	369K
Vehicle No.:	SHB5308A
Vehicle to be Exported:	No
Intended Deregistration Date:	28 Mar 2022
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS HYBRID 1.8 CVT
Primary Colour:	Maroon
Manufacturing Year:	2017
Engine No.:	2ZRS108903
Chassis No.:	JTDKB3FUX03575400
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$29,007.00
Original Registration Date:	30 Nov 2017
First Registration Date:	30 Nov 2017
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Nov 2025
PARF Rebate Amount:	\$3,750.00
COE Expiry Date:	29 Nov 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$33,596.00
COE Rebate Amount:	\$15,409.00
Total Rebate Amount:	\$19,159.00

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 28 Mar 2022

OK