

**Section A - Accident Details**

Registration Number	SHB5308A
Case Reference Number	TAX/03/22/2051
Registration Date	30/11/2017
Company Type	Strides Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	LEONG WAI KIONG ( LIANG WEIQIANG )
Type of Accident	Head to Rear
Accident Date and Time	24/3/2022 3:15 PM
Accident Reported Date and Time	24/3/2022 4:21 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24114365
Special Instruction to ARC, if any	TP / REAR PORTION
Prepared Date and Time	24/3/2022 5:35 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

**Section B - Summary of Repair Estimates**

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,852.00	\$700.00
Total Spray Cost	\$2,232.00	\$600.00
Total Spare Part Cost	\$6,364.07	\$1,613.62
Total Other Cost	\$740.00	\$80.00
<b>TOTAL COST</b>	<b>\$11,188.07</b>	<b>\$2,993.62</b>
<b>Lump Sum Total</b>	<b>\$11,200.00</b>	<b>\$3,000.00 (L/S)</b>
Number of Repair Days	10.0	8.0
Prepared / Adjusted By	<b>Boon Chew Tay</b>	<b>Rasul (LKK) / ERGO</b>
ARC / Surveyor Sign Off Date	<b>30/03/2022 10:30 AM</b>	<b>30/03/2022 10:22 AM</b>
Signature		
Remarks	Total number of repair days = 8 days. SUP = + 2 days	LUMP SUM REPAIR / RESURVEY AFTER REPAIR

**Section C - Quotation and Accident Invoice Details**

<b>Quotation Number</b>	QN-2204-0339	<b>Invoice Number</b>	
<b>Quotation Date</b>	25.04.2022	<b>Invoice Date</b>	
<b>Invoice Amount</b>		<b>Prepared Date</b>	

**Section D - Details of Repair Estimates**

**Part 1 - Labour Works**

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR REAR SPARE TYRE PANEL	\$250.00	\$100.00
TO REPAIR REAR TAILGATE	\$250.00	\$0.00
TO REPAIR REAR PORTION	\$1,352.00	\$600.00
<b>Total Labour</b>	<b>\$1,852.00</b>	<b>\$700.00</b>

**Part 2 - Spray Painting & Panel Beating Related Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY TAIL GATE	\$378.00	\$100.00
TO RESPRAY REAR SPARE TYRE PANEL	\$180.00	\$100.00
TO RESPRAY REAR FENDER RH	\$378.00	\$0.00
TO RESPRAY TAIL GATE	\$378.00	\$0.00
TO RESPRAY TAILGATE OUTSIDE GARNISH	\$180.00	\$100.00
TO RESPRAY REAR SPARE TYRE PANEL	\$180.00	\$0.00
TO RESPRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY REAR PANEL	\$180.00	\$100.00
<b>Total Spray Painting &amp; Panel Beating</b>	<b>\$2,232.00</b>	<b>\$600.00</b>

**Part 3 - Other Costs - Accident and Accident Repair Related Expense**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO WASH AND VACUUM	\$60.00	\$0.00
TO REPLACE SUNDRY PARTS	\$120.00	\$0.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$200.00	\$40.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$40.00
TO TRANSFER REAR TAILGATE MECHANISM	\$120.00	\$0.00
TO REMOVE AND REFIX REAR WINDSCREEN	\$120.00	\$0.00
<b>Total Other Costs</b>	<b>\$740.00</b>	<b>\$80.00</b>

**Part 4 - Spare Parts / Material Usage**

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52159479 13	COVER, RR BUMPER ASSY	1.00	\$423.90	25.00	\$317.93	Replace	Replace
		52023470 30	REAR BUMPER REINFORCEMENT	1.00	\$318.80	25.00	\$239.10	Replace	Replace
		52462470 30	PAD, RR BUMPER, RH & LH , 1	2.00	\$3.80	25.00	\$5.70	Replace	Replace
		52462470 20	PAD, RR BUMPER, RH & LH , 2	2.00	\$3.80	25.00	\$5.70	Replace	Replace
		52462470 10	PAD, RR BUMPER, RH & LH , 3	2.00	\$3.80	25.00	\$5.70	Replace	Replace
		52461470 10	PAD, RR BUMPER, CTR	3.00	\$2.20	25.00	\$4.95	Replace	Replace
		52191470 30	SEAL, RR BUMPER ARM, RH & LH	2.00	\$11.00	25.00	\$16.50	Replace	Replace
		52599680 30	STOPPER, RR BUMPER, RH & LH	0.00	\$4.30	0.00	\$0.00	Replace	Not Given

✓  
✓  
✓  
✓  
✓  
✓  
✓  
✓  
X

**STRIDES Accident Vehicle Repair Estimates**

<b>STRIDES Automotive Services Pte Ltd</b>
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 28/04/2022

User ID PohSuan

	5257547040	RETAINER, RR BUMPER, RH	0.00	\$112.70	0.00	\$0.00	Replace	Not Given	X
	5257647040	RETAINER, RR BUMPER, LH	0.00	\$111.50	0.00	\$0.00	Replace	Not Given	X
	5259147050	SEAL, RR BUMPER , RH	0.00	\$85.20	0.00	\$0.00	Replace	Not Given	X
	5259247040	SEAL, RR BUMPER , LH	0.00	\$85.20	0.00	\$0.00	Replace	Not Given	X
	5216116010	CLIPS PIECE, FRT & RR BUMPER	10.00	\$1.50	25.00	\$11.25	Replace	Replace	√
	5245347010	GUARD, RR BUMPER, LOWER	1.00	\$558.30	25.00	\$418.73	Replace	Replace	√
	5256547900	FILLER, RR BUMPER , RH	1.00	\$119.90	25.00	\$89.93	Replace	Replace	√
	5256647900	FILLER, RR BUMPER , LH	1.00	\$119.90	25.00	\$89.93	Replace	Replace	√
	5216947020	COVER, GUARD RR BUMPER LOWER	1.00	\$14.80	25.00	\$11.10	Replace	Replace	√
		SENSOR REVERSE	1.00	\$180.00	0.00	\$180.00	Replace	Replace	√
	8999730100	ANTENNA, ELECTRICAL KEY	0.00	\$60.30	0.00	\$0.00	Replace	Not Given	X
	9018906029	REAR BUMPER GROMMET SCREW	2.00	\$2.20	25.00	\$3.30	Replace	Replace	√
	8155147281	LENS & BODY, REAR COMBINATION LAMP , RH	0.00	\$438.10	0.00	\$0.00	Replace	Not Given	X
	8156147151	LENS & BODY, REAR COMBINATION LAMP , LH	0.00	\$438.10	0.00	\$0.00	Replace	Not Given	X
	8158147010	LENS & BODY ASSY , RR BUMPER , RH	0.00	\$486.80	0.00	\$0.00	Replace	Not Given	X
	8159147010	LENS & BODY ASSY , RR BUMPER , LH	0.00	\$486.80	0.00	\$0.00	Replace	Not Given	X
	8149747020	COVER, REAR COMBINATION LAMP, RH	0.00	\$54.00	0.00	\$0.00	Replace	Not Given	X
	8149847020	COVER, REAR COMBINATION LAMP, LH	0.00	\$54.00	0.00	\$0.00	Replace	Not Given	X
	5839847050	COVER, REAR FLOOR UNDER , RH	0.00	\$169.50	0.00	\$0.00	Replace	Not Given	X
	5839947030	COVER, REAR FLOOR UNDER , LH	0.00	\$234.30	0.00	\$0.00	Replace	Not Given	X
	6625947010	COVER, REAR FLOOR UNDER CENTER	0.00	\$222.60	0.00	\$0.00	Replace	Check	X
	6160147150	PANEL SUB-ASSY, FENDER REAR RH	0.00	\$824.80	0.00	\$0.00	Replace	Not Given	X
	6563747060	LINER, REAR FENDER , RH	0.00	\$135.80	0.00	\$0.00	Replace	Not Given	X
	6700547440	TAIL GATE PANEL SUB-ASSY, BACK DOOR	0.00	\$929.60	0.00	\$0.00	Replace	Not Given	X
	6788147050	TAIL GATE WEATHERSTRIP, BACK DOOR	0.00	\$360.70	0.00	\$0.00	Replace	Not Given	X
	5611750140	TAIL GATE DAM, BACK DOOR GLASS UPPER	0.00	\$27.90	0.00	\$0.00	Replace	Not Given	X
	768014710A1	TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-	1.00	\$891.20	100.00	\$0.00	Replace	Repair	R
	7544147090	NAME PLATE (HYBRID) , LUGGAGE COMPARTMENT	1.00	\$52.30	25.00	\$39.23	Replace	Replace	√
	7544247130	NAME PLATE (PRIUS) , LUGGAGE COMPARTMENT	1.00	\$52.30	25.00	\$39.23	Replace	Replace	√
	7544247130	NAME PLATE (PRIUS) , LUGGAGE COMPARTMENT	0.00	\$52.30	25.00	\$0.00	Replace	Not Given	X
	6935047050	TAIL GATE LOCK ASSY, BACK DOOR	0.00	\$452.10	0.00	\$0.00	Replace	Not Given	X
	6932147010	TAIL GATE LOCK COVER , BACK DOOR	0.00	\$25.30	0.00	\$0.00	Replace	Not Given	X
	6943052050	TAIL GATE STRIKER ASSY, BACK DOOR	0.00	\$24.90	0.00	\$0.00	Replace	Not Given	X
		STRIDES LOGO	1.00	\$7.80	0.00	\$7.80	Replace	Replace	√
		STICKER DECAL 6555 8888	1.00	\$21.60	0.00	\$21.60	Replace	Replace	√
		NUMBER PLATE	0.00	\$35.00	0.00	\$0.00	Replace	Not Given	X
		NUMBER PLATE FRAME	0.00	\$25.00	0.00	\$0.00	Replace	Not Given	X
	5830747090	END PANEL SUB-ASSY, BODY LOWER BACK	1.00	\$629.80	25.00	\$472.35	Replace	Replace	√
	5831147130	SPARE TYRE PANEL , PAN, REAR FLOOR	0.00	\$564.80	0.00	\$0.00	Replace	Not Given	X
		SEALANT SIKAFLEX	1.00	\$37.00	0.00	\$37.00	Replace	Replace	√
<b>Total</b>				<b>\$9,957.50</b>		<b>\$2,017.03</b>			

**STRIDES Accident Vehicle Repair Estimates**

<b>STRIDES Automotive Services Pte Ltd</b>
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 28/04/2022

User ID : PohSuan

**Added Spare Parts / Material Usage After Surveyor Signed off**

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
<b>Total</b>									

	2,017.03	
	-20%	
	<u>1613.62</u>	
+	700.00	L/S \$3,000/-
+	<u>680.00</u>	
	2,993.62	