



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Co Reg No : 1977014696

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name KCV15727/TAN JUN XIANG Reg No/Reg Date SMT7929R / 17/07/202 Date In/Mileage 25/03/2022/ 0 Chassis No MMBSTA13AKH003402 Engine No 3A92UJB1591 Make/Model MIT/19MY ATTRAGE 1.2 CVT Colour/Trim P57 WINE RED PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	25/03/2022/ 10:56	BLK	282 / Kevin Leong	21923
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE REAR BUMPER PANEL, BOOT, END PANEL, BODY KIT & AFFECTED AREA REPAIR ON REAR, LH FENDER & FLOOR PANEL		5 x 450			2250 / 3150.00
E PNT98000 PAINT WORK ON REAR BUMPER, BOOT, BOTH REAR FENDER, END PANEL, FLOOR PANEL & BODY KIT		5 x 350			1750 / 2450.00
E PNT88000 REMOVE & INSTALL REAR PARKING ASSIST					80 / 120.00
E PNT88000 REMOVE & REPLACE BODY KIT					80.00 /
E PNT88000 REMOVE & INSTALL REAR BOOT COMPARTMENT FOR FACILITATE REPAIR					120.00 /
E PNT88000 TO TRANSFER BOOT ATTACHMENT TO NEW PANEL					120.00 /
M SUNDRY TO APPLY SEALNT ON AFFECTED AREA					40 / 80.00
M SUNDRY PERFORM RUST PREVENTION					40 / 80.00
A 54900099 CHECK WIIRNG & CHASSIS ELECTRICAL SYSTEM					30.00 /
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM					120.00 /
M SUNDRY TO SUPPLY C & C EMBLEM					40.00 /
M SUNDRY TO SUPPLY REAR NUMBER PLATE WITH FRAME					50.00 X
M SUNDRY TO SUPPLY REVERSE SENSOR SET					220.00 X
M SUNDRY SUNDRIES					20 50.00
M UNPAINTED BODYKITS / BR		1.00 net	1643.00	20.00	1314.40
M LAMP ASSY, COMB, RR LH / CRA		1.00	337.00	23.00	259.49
M LAMP ASSY, COMB, RR RH X MN		1.00	337.00	23.00	259.49

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name KCV15727/TAN JUN XIANG Reg No/Reg Date SMT7929R / 17/07/202 Date In/Mileage 25/03/2022/ 0 Chassis No MMBSTA13AKH003402 Engine No 3A92UJB1591 Make/Model MIT/19MY ATTRAGE 1.2 CVT Colour/Trim P57 WINE RED PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No	
KAX00008	Credit	25/03/2022/ 10:56	BLK	282 / Kevin Leong	21923	
Description of Goods / Services			Qty	Unit Price	Disc%	Amount
M	LAMP ASSY,LICENSE PLATE	X <i>nn</i>	1.00	51.00	23.00	39.27
M	BRACKET,RR BUMPER,LH	<i>BR</i>	1.00	28.00	23.00	21.56
M	BRACKET,RR BUMPER,RH	X <i>nn</i>	1.00	28.00	23.00	21.56
M	FACE,RR BUMPER	<i>DD</i>	1.00	751.00	23.00	578.27
M	PANEL,RR END	<i>DD</i>	1.00	427.00	23.00	328.79
M	PANEL,TRUNK LID	<i>DD</i>	1.00	795.00	23.00	612.15
M	WEATHERSTRIP,TRUNK LID	<i>CRU</i>	1.00	157.00	23.00	120.89
M	HINGE,TRUNK LID,LH	X <i>R</i>	1.00	203.00	23.00	156.31
M	HINGE,TRUNK LID,RH	X <i>R</i>	1.00	203.00	23.00	156.31
M	GARNISH,RR END PANEL	X <i>nn</i>	1.00	336.00	23.00	258.72
M	MARK,ATTRAGE	<i>ARC</i>	1.00	21.00	23.00	16.17
M	MARK,THREE-DIA	<i>ARC</i>	1.00	70.00	23.00	53.90
M	TRIM,RR END	<i>CRU</i>	1.00	66.00	23.00	50.82
M	BOARD,TRUNK ROOM FLOOR	<i>broken</i>	1.00	195.00	23.00	150.15
M	EMBLEM MIVEC TECHNOLOGY	<i>ARC</i>	1.00	30.00	00.00	30.00

Stew (LKK)
25/3/22, 2.30pm

00-AL AL
Excess-?
P/P

My BL
8 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Confirm & accepted by
Date:

7% GST on **Nett 11138.25**
Total Payable 11,917.93

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.