

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CTI22002773/VTY3E2

**Date:** 06/06/2022

### REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00241782100		
<b>Claimant Vehicle No :</b>	SMW5924B	<b>Insured Vehicle No :</b>	SJJ9449J		
Date of Loss:	22/03/2022	Nature of Claim:	TP	Claim No:	SNM22D202029/C02/CHEESC

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SMW5924B</b>		
Make & Model:	MERCEDES-BENZ GLB200, 1.3 PREMIUM AMG LINE 7-SEATER (A)	Engine No:	28291480305927
Reg. Date:	27/11/2020 (Man. Year: 2020)	Chassis No:	W1N2476872W031215
Colour:	Black	Odometer:	28312 km
Engine Capacity:	1332 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	235/50 R19	Rear Tyre Size:	235/50 R19
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,928.00	3,405.00	523.00	13.31
Miscellaneous Items	0.00	0.00	0.00	
Labour	369.60	155.40	214.20	57.95
Paintwork Labour	432.76	207.70	225.06	52.01
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>4,730.36</b>	<b>3,768.10</b>	<b>962.26</b>	<b>20.34</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,000.00</b>		
<b>(S\$)</b>	4,730.36	3,000.00	1,730.36	36.58
<b>+ GST 7.00/7.00% (S\$)</b>	331.13	210.00	121.13	36.58
<b>Nett Amount (S\$)</b>	<b>5,061.49</b>	<b>3,210.00</b>	<b>1,851.49</b>	<b>36.58</b>

### INSPECTION

Date of Assignment:	24/03/2022	Present Location:	Car City Auto Centre Pte Ltd (HQ)
Date Inspected:	28/03/2022	Inspected At:	Car City Auto Centre Pte Ltd (HQ) Blk 9006 #01-198, Tampines Street 93 Singapore 528840
Estimated Period of Repair:	3.0 days		

**Adjuster:** Thevan Thomas Karthikesavan

**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

<b>Part Source:</b> MRM-SG		Version: 1.0 (Last Synchronised: 06 Jun 2022)	
<b>Parts:</b>	M1-SUV	MERCEDES-BENZ GLB200 1.3 PREMIUM AMG LINE 7-SEATER (A) (Catalogue:Merimen Singapore 1.0)	
<b>Labour:</b>	Repairer's (Price-denominated Standard List)		
<b>Print Code:</b>	(Unsubmitted, no print-code for SMW5924B)		
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page		
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.		

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1	NA	*FRONT BUMPER TRIM	Cut	840.00 F	*840.00 F
2	1	NA	*FRONT CROSSMEMBER	Not Necessary	325.00 F	*- F
3	1	NA	*FRONT IMPACT DAMPER	Not Necessary	88.00 F	*- F
4	1	NA	*GRILLE	Scratched	550.00 F	*550.00 F
5	1	NA	*L/F BUMPER GRILLE	Scratched	70.00 F	*70.00 F
6	1	NA	*L/F BUMPER MOULDING	Necessary	85.00 F	*85.00 F
7	1	NA	*L/GRILLE BRACKET	Serviceable	95.00 F	*- F
8	1	NA	*LEFT HEADLAMP ASSY	Cracked	1,850.00 F	*1,850.00 F
9	1	NA	*SUNDRY PARTS	Necessary	0.00 F	*- F
10	1	NA	*CHECK WIRING CHECKING WIRING		25.00 F	*10.00 F
F=Franchise part.						
					Total Parts (S\$)	
					3,928.00	3,405.00

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Paintwork Labour</u></b>				
1	Total Paint Labour	New	285.60	117.60
2	Total Paint Materials	New	147.16	90.10
<b><u>Labour Items</u></b>				
3	Total Panel/Mechanical Labour	New	369.60	155.40
<b>Gross Labour Cost (\$\$)</b>			<b>802.36</b>	<b>363.10</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >