

Vin's

Vin's Motor Pte Ltd
160 Sin Ming Drive
#03-03 Sin Ming Autocity
Singapore 575722
Tel : 6453 2121 Fax : 6459 9795
GST Registration No. 199906067G

Estimated Cost of Repair

Attention To : ECICS LIMITED
7 Temasek Boulevard
#10-01 Suntec Tower One
Singapore 038987

Claim Details

Case Ref. No. : OD/032022/5312
Date : 25-03-2022
Accident Date : 24-03-2022

Vehicle Details

Make & Model : Honda SHUTTLE 1.5G CVT
SENSING

Chassis No : GK82103191

Registration No : SNB8713Y

| S/N | Description | Qty | Amount (\$) |
|-----|--|-------|-------------|
| 1 | FRONT BONNET / BUC | 1.00 | \$540.00 |
| 2 | FRONT BONNET RH HINGE = 4 BT | 1.00 | \$30.00 |
| 3 | FRONT BONNET LH HINGE | 1.00 | \$30.00 |
| 4 | FRONT BONNET RUBBER / Tui | 1.00 | \$25.00 |
| 5 | FRONT BONNET INSULATOR / TN | 1.00 | \$80.00 |
| 6 | FRONT BONNET LOWER LOCK / BT | 1.00 | \$90.00 |
| 7 | FRONT BONNET LOCK COVER / Re | 1.00 | \$50.00 |
| 8 | FRONT RH HEADLAMP / BR | 1.00 | \$1,100.00 |
| 9 | FRONT LH HEADLAMP / BR | 1.00 | \$1,100.00 |
| 10 | FRONT RH HEADLAMP LOWER BRACKET = } BR | 1.00 | \$30.00 |
| 11 | FRONT LH HEADLAMP LOWER BRACKET = } BR | 1.00 | \$30.00 |
| 12 | FRONT GRILLE BASE / BR | 1.00 | \$200.00 |
| 13 | FRONT GRILLE OUTER CHROME GARNISH / BR. | 1.00 | \$240.00 |
| 14 | FRONT GRILLE EMBLEM / CLA | 1.00 | \$230.00 |
| 15 | FRONT GRILLE EMBLEM HOUSING / Cut | 1.00 | \$20.00 |
| 16 | FRONT GRILLE LOWER CHROME MOULDING / BR. | 1.00 | \$140.00 |
| 17 | FRONT BUMPER / Re | 1.00 | \$730.00 |
| 18 | FRONT BUMPER TOWING COVER x nn | 1.00 | \$20.00 |
| 19 | FRONT BUMPER CENTRE LOWER GRILLE ? | 1.00 | \$80.00 |
| 20 | FRONT BUMPER RH SIDE GRILLE / Re | 1.00 | \$60.00 |
| 21 | FRONT BUMPER LH SIDE GRILLE ? | 1.00 | \$60.00 |
| 22 | FRONT BUMPER UNDER COVER ? | 1.00 | \$190.00 |
| 23 | FRONT BUMPER RH SIDE RETAINER = } Re | 1.00 | \$10.00 |
| 24 | FRONT BUMPER LH SIDE RETAINER = } Re | 1.00 | \$10.00 |
| 25 | FRONT BUMPER REINFORCEMENT / BT | 1.00 | \$250.00 |
| 26 | FRONT BUMPER CLIPS @ \$3.00 / nbc | 10.00 | \$30.00 |
| 27 | FRONT SUPPORT PANEL / BT | 1.00 | \$420.00 |
| 28 | FRONT SUPPORT PANEL TOP COVER / Cut | 1.00 | \$40.00 |
| 29 | FRONT SUPPORT PANEL AIR DUCT / CPA | 1.00 | \$40.00 |
| 30 | AIRCON CONDENSER ? | 1.00 | \$600.00 |

Vin's

Vin's Motor Pte Ltd
 160 Sin Ming Drive
 #03-03 Sin Ming Autocity
 Singapore 575722
 Tel : 6453 2121 Fax : 6459 9795
 GST Registration No. 199906067G

| | | | |
|----|---------------------------------------|------|------------|
| 31 | RADIATOR ? | 1.00 | \$750.00 |
| 32 | FRONT RADAR ? | 1.00 | \$1,050.00 |
| 33 | FRONT RADAR BRACKET ? | 1.00 | \$530.00 |
| 34 | BATTERY COVER (RED) / cut | 1.00 | \$10.00 |
| 35 | FRONT RH FENDER = 1/2 | 1.00 | \$180.00 |
| 36 | FRONT LH FENDER = 1/2 | 1.00 | \$180.00 |
| 37 | FRONT WINDSCREEN GLASS - cut | 1.00 | \$1,200.00 |
| 38 | FRONT WINDSCREEN GLASS MOULDING / cut | 1.00 | \$70.00 |
| 39 | FRONT WIPER GRILLE GARNISH / cut | 1.00 | \$160.00 |

\$10,605.00

Margin: 10%

\$1,060.50

\$11,665.50

| | | | |
|----|--------------------------------|------|--------------|
| 40 | FRONT NO. PLATE / BT | 1.00 | \$40.00 |
| 41 | FRONT WINDSCREEN GUM / dec | 1.00 | \$80.00 |
| 42 | TO REMOVE AND REFIX WINDSCREEN | 1.00 | \$150.00 120 |
| 43 | TO RESET HEADLAMP SYSTEM | 1.00 | \$250.00 80 |
| 44 | TO RESET RADAR SYSTEM | 1.00 | \$280.00 220 |
| 45 | TO REPAIR DAMAGES | 1.00 | \$780.00 700 |
| 46 | TO SPRAY PAINTING | 1.00 | \$980.00 900 |

Subtotal w/o GST:

\$14,225.50

7 Days.
 p/p
 before paint photos.
 Gme Ricard
 25/3/22.
 excess = 750
 Not Authorised.

LINK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a 'Without Prejudice' basis
- No illegal modifications are allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Issued by Raymond Teo

This is a computer-generated document. No signature is required.