

Vin's

Vin's Motor Pte Ltd
 160 Sin Ming Drive
 #03-03 Sin Ming Autocity
 Singapore 575722
 Tel : 6453 2121 Fax : 6459 9795
 GST Registration No. 199906067G

Estimated Cost of Repair

Attention To : ECICS LIMITED
 7 Temasek Boulevard
 #10-01 Suntec Tower One
 Singapore 038987

Claim Details

Case Ref. No. : OD/032022/5312
Date : 25-03-2022
Accident Date : 24-03-2022

Vehicle Details

Make & Model : Honda SHUTTLE 1.5G CVT
 SENSING

Chassis No : GK82103191

Registration No : SNB8713Y

S/N	Description	Qty	Amount (\$)	
1	FRONT BONNET / BUC	1.00	\$540.00	✓
2	FRONT BONNET RH HINGE = 4 BT	1.00	\$30.00	✓
3	FRONT BONNET LH HINGE	1.00	\$30.00	✓
4	FRONT BONNET RUBBER / Tui	1.00	\$25.00	✓
5	FRONT BONNET INSULATOR / TN	1.00	\$80.00	✓
6	FRONT BONNET LOWER LOCK / BT	1.00	\$90.00	✓
7	FRONT BONNET LOCK COVER / Re	1.00	\$50.00	✓
8	FRONT RH HEADLAMP / BR	1.00	\$1,100.00	✓
9	FRONT LH HEADLAMP / BR	1.00	\$1,100.00	✓
10	FRONT RH HEADLAMP LOWER BRACKET = } BR	1.00	\$30.00	✓
11	FRONT LH HEADLAMP LOWER BRACKET = } BR	1.00	\$30.00	✓
12	FRONT GRILLE BASE / BR	1.00	\$200.00	✓
13	FRONT GRILLE OUTER CHROME GARNISH / BR	1.00	\$240.00	✓
14	FRONT GRILLE EMBLEM / CLS	1.00	\$230.00	✓
15	FRONT GRILLE EMBLEM HOUSING / Cut	1.00	\$20.00	✓
16	FRONT GRILLE LOWER CHROME MOULDING / BR	1.00	\$140.00	✓
17	FRONT BUMPER / Re	1.00	\$730.00	✓
18	FRONT BUMPER TOWING COVER x nn	1.00	\$20.00	✓
19	FRONT BUMPER CENTRE LOWER GRILLE ✓ BR	1.00	\$80.00	✓
20	FRONT BUMPER RH SIDE GRILLE / Re	1.00	\$60.00	✓
21	FRONT BUMPER LH SIDE GRILLE ✓ BR	1.00	\$60.00	✓
22	FRONT BUMPER UNDER COVER ✓ BR	1.00	\$190.00	✓
23	FRONT BUMPER RH SIDE RETAINER = } Re	1.00	\$10.00	✓
24	FRONT BUMPER LH SIDE RETAINER = } Re	1.00	\$10.00	✓
25	FRONT BUMPER REINFORCEMENT / BT	1.00	\$250.00	✓
26	FRONT BUMPER CLIPS @ \$3.00 / nbc	10.00	\$30.00	✓
27	FRONT SUPPORT PANEL / BT	1.00	\$420.00	✓
28	FRONT SUPPORT PANEL TOP COVER / Cut	1.00	\$40.00	✓
29	FRONT SUPPORT PANEL AIR DUCT / CPA	1.00	\$40.00	✓
30	AIRCON CONDENSER ✓ CUT	1.00	\$600.00	✓

Vin's

Vin's Motor Pte Ltd
 160 Sin Ming Drive
 #03-03 Sin Ming Autocity
 Singapore 575722
 Tel : 6453 2121 Fax : 6459 9795
 GST Registration No. 199906067G

31	RADIATOR X NN	1.00	\$750.00	
32	FRONT RADAR ✓ BR	1.00	\$1,050.00	✓
33	FRONT RADAR BRACKET ✓ BT	1.00	\$530.00	✓
34	BATTERY COVER (RED) / cut	1.00	\$10.00	✓
35	FRONT RH FENDER = Same	1.00	\$180.00	✓
36	FRONT LH FENDER = Same	1.00	\$180.00	✓
37	FRONT WINDSCREEN GLASS - cut	1.00	\$1,200.00	✓
38	FRONT WINDSCREEN GLASS MOULDING / cut	1.00	\$70.00	✓
39	FRONT WIPER GRILLE GARNISH / cut	1.00	\$160.00	✓
			<hr/>	
			\$10,605.00	9835
			Margin: 10%	\$1,060.50
			<hr/>	
			\$11,665.50	10818.5
40	FRONT NO. PLATE / BT	1.00	\$40.00	✓
41	FRONT WINDSCREEN GUM / cut	1.00	\$80.00	40
42	TO REMOVE AND REFIX WINDSCREEN	1.00	\$150.00	120
43	TO RESET HEADLAMP SYSTEM	1.00	\$250.00	80
44	TO RESET RADAR SYSTEM	1.00	\$280.00	220
45	TO REPAIR DAMAGES	1.00	\$780.00	700
46	TO SPRAY PAINTING	1.00	\$980.00	900
				2100
			<hr/>	
			Subtotal w/o GST:	\$14,225.50
				12918.5

7 Days.
 p/p
 before paint photos.
 Gme Q:ary
 25/3/22.
 excess = 750
 Not Anthony'sel.

LINK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a 'Without Prejudice' basis
- No illegal modifications are allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Issued by Raymond Teo

This is a computer-generated document. No signature is required.