

Thiam Heng Huat Pte Ltd

176 Sin Ming Drive #05-14 Sin Ming Autocare Singapore 575721

Mobile: 82636295 Email: thiamhenghuat@gmail.com

Make/Model: BMW 525i

Date: 28/03/2022


Engine/Chassis No.: WBANU52010CZ89717

Claim Type: TP

Date of accident:

VRN: EX89J

Damaged area: Rear



List items				
S/N	Parts description	QTY	UNIT PRICE	AMOUNT
1	Taillamp	2	\$ 954.00	\$ 1,908.00
2	Taillamp weatherseal	2	\$ 46.00	\$ 92.00
3	Taillamp panel	2	\$ 241.00	\$ 482.00
4	Rear bumper	1	\$ 1,295.00	\$ 1,295.00
5	Rear bumper tow hook cover	1	\$ 59.00	\$ 59.00
6	Rear bumper side carrier	2	\$ 285.00	\$ 570.00
7	Rear bumper reinforcement	1	\$ 915.00	\$ 915.00
8	Rear bumper reinforcement bracket	2	\$ 211.00	\$ 422.00
9	Rear bumper upper carrier bracket	1	\$ 382.00	\$ 382.00
10	Rear bumper lower carrier bracket	1	\$ 449.00	\$ 449.00
11	Bootlid	1	\$ 1,398.00	\$ 1,398.00
12	Bootlid lock	1	\$ 417.00	\$ 417.00
13	Exhaust pipe	2	\$ 1,045.00	\$ 2,090.00
14	Exhaust pipe chrome tip	4	\$ 285.00	\$ 1,140.00
15	Exhaust pipe holder	2	\$ 48.00	\$ 96.00
16	Exhaust pipe heatshield	2	\$ 138.00	\$ 276.00
17	End panel top garnish	1	\$ 323.00	\$ 323.00
18	End panel	1	\$ 899.00	\$ 899.00
19	Bootlid logo	1	\$ 109.00	\$ 109.00
20	Bootlid "525i" emblem	1	\$ 75.00	\$ 75.00
Subtotal				\$ 13,397.00
List discount				5.00%
Total				\$ 12,727.15

Special nett items				
No.	Parts description	QTY	UNIT PRICE	AMOUNT
1	Reverse sensor holder	2	\$ 18.00	\$ 36.00
2	Reverse sensor (Factory Original)	2	\$ 380.00	\$ 760.00
3	Rear bumper diffuser	1	\$ 800.00	\$ 800.00
4	Rear bumper clips	12	\$ 5.50	\$ 66.00

Repair Estimate

5	End panel top garnish clips	6	\$ 5.50	\$ 33.00
6	End panel sealant	1	\$ 120.00	\$ 120.00
7	Sundries	1	\$ 50.00	\$ 50.00
Total				\$ 1,865.00

Labour			
No.	Description	Work unit	Amount
1	To dismantle / renew accident damaged portion. To panel beat, reshape, straighten, orientate and align repair / replacement parts.	6	\$ 1,200.00
2	To disconnect rear wire harness of electrical components to facilitate repairs, reconnect and check functions including taillamp lightings.	0.5	\$ 100.00
3	Supply spray paint material and necessary items to respray affected area / panel.	5	\$ 1,000.00
4	To rust proof all affected portions after repair.	0.5	\$ 100.00
Total labour			\$ 2,400.00

Estimate Grand Total	\$ 16,992.15
-----------------------------	---------------------