

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance
(Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Irene Tay Hui Ping

Date: 01 Apr 2022

Preliminary Advice

| | | | |
|--------------------|--|-------------------------|-------------------------|
| Vehicle No | : SLT2156Z | Accident Date | : 21/03/2022 |
| Make | : HYUNDAI ELANTRA | Policy No. | : DMPCSNW00210242100 |
| Assignment Date | : 25/03/2022 | Excess | : S\$0.00 |
| Date of Inspection | : 29/03/2022 | Est. Duration of Repair | : 10 |
| Inspection At | : AUTO INSURE PTE LTD (HQ) (WOODLANDS) 6 MARSILING LANE SINGAPORE 739145 | | |

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

| | |
|-----------------------------|----------------|
| Repairer's Estimate (Gross) | :S\$ 17,111.79 |
| Revised Amount | :S\$ 14,066.79 |
| Check Items (Estimated) | :S\$ 2,705.00 |
| Total | :S\$ 16,771.79 |

Lump Sum Repair :S\$

Total Loss Consideration

| | |
|--------------------|----------------|
| New for Old Value | :S\$ |
| Pre-Accident Value | :S\$ 60,000.00 |
| COE / PARF Rebate | :S\$ 32,977.00 |

| | |
|-------------------|----------------|
| Salvage Value | :S\$ |
| Margin for Repair | :S\$ 27,023.00 |

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.