

**Automotive Repair Centre Pte Ltd**CO. Reg. No. : 201312913C
GST Reg. No. : 201312913C**Estimate**

48 Toh Guan Road East (Enterprise Hub)

#02-146, Singapore 608586

Tel: 64688834 Fax: 67228585

E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2203-162-TG

DATE : 25-Mar-2022

POLICY NO. :

VEHICLE REG. NO. : **SMJ3951D**

VEHICLE MAKE : Honda Civic 2.0 2007

TO Motor Claim Department

China Taiping Insurance (Singapore) Pte. Ltd

3 Anson Road, #15-00 Springleaf Tower

Singapore 079909

Tel: 6389 6116, Fax: 6222 1033

FOR SURVEYOR

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
SPARE PARTS				
1	Front Bumper <i>BR</i>	1	\$ 1,100.00	\$ 1,100.00
2	Front Bumper Clip <i>MC</i>	10	\$ 6.00	\$ 60.00 <i>30</i>
3	Front Bumper Retainer RH <i>BR</i>	1	\$ 90.00	\$ 90.00
4	Front Bumper Retainer LH <i>BR</i>	1	\$ 90.00	\$ 90.00
5	HeadLamp RH <i>BR</i>	1	\$ 1,250.00	\$ 1,250.00
6	HeadLamp Bracket RH <i>X R</i>	1	\$ 90.00	\$ 90.00
7	Front Grille Base <i>X</i>	1	\$ 120.00	\$ 120.00
8	Front Grille Moulding <i>X</i>	1	\$ 280.00	\$ 280.00
9	Front Emblem <i>X</i>	1	\$ 70.00	\$ 70.00
10	Front FogLamp RH <i>X</i>	1	\$ 650.00	\$ 650.00
11	Front FogLamp Ganish RH <i>X</i>	1	\$ 80.00	\$ 80.00
12	Front Fender RH <i>DO</i>	1	\$ 900.00	\$ 900.00
13	Front Fendershield RH <i>CR4</i>	1	\$ 230.00	\$ 230.00
14	Front Fendershield LH <i>X</i>	1	\$ 230.00	\$ 230.00
15	Front Fender Clips <i>MC</i>	10	\$ 6.00	\$ 60.00 <i>90</i>
Parts List Price Minus 20%				\$ (1,060.00)
Total Spare Parts				\$ 4,240.00
SPECIAL NETT				
Total Special Nett				\$ -
LABOUR				
16	Spray Paint (Front Bumper, Front Fender LH & RH)	1	\$ 800.00	\$ 800.00 <i>400</i>
17	Remove, Replace, Repair and Refit Accident Affected Parts	1	\$ 500.00	\$ 300.00
18	Repair Front Rim RH	1	\$ 100.00	\$ 100.00 <i>80</i>
19	Wheel Alignment - Customer's concern	1	\$ 100.00	\$ 100.00
20	Check and Rectify Electrical Wiring	1	\$ 30.00	\$ 30.00

Estimate prepared by: RAZALI

Total Labour \$ 1,330.00

Amount Before Excess \$ 5,570.00

Add GST @ 7% 389.90

Total Amount Payable \$ 5,959.90

The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on