

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: ECICS Limited
10 Eunos Road 8
#09-04A Singapore Post Centre
Singapore 408600

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 23 May 2022

Preliminary Advice

Insured : SNB8713Y

Vehicle No

TP Vehicle : GBD6267M
No

Accident Date : 24/03/2022

Make : TOYOTA HIACE VAN
TURBO 5 DR MANUAL

Assignment Date : 25/03/2022

Date of : 26/03/2022
Inspection

Est. Duration of : 6
Repair

Inspection At : KS AUTOMOBILE (HQ)
60 JALAN LAM HUAT, CARROS CENTRE, #05-68
SINGAPORE 737869

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross) :S\$ 17,522.20

Revised Amount :S\$ 6,841.58

Check Items (Estimated) :S\$ 0.00

Total :S\$ 6,841.58

Lump Sum Repair :S\$ 5,400.00

Total Loss Consideration

New for Old Value :S\$

Pre-Accident Value :S\$

COE / PARF Rebate :S\$

Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.