



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. PC 9644C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT BUMPER	DAMAGED	721.50	673.45
1	FRONT BUMPER FOG LAMP GARNISH LH	SERVICEABLE	98.50	-
1	FRONT BUMPER LOWER GRILLE	BROKEN	235.00	235.00
1	FRONT BUMPER TOW HOOK COVER	MISSING	38.90	38.90
1	FRONT BUMPER REINFORCEMENT	BENT	412.00	412.00
1	FRONT BUMPER SIDE RETAINER LH	NECESSARY	42.00	42.00
1	HEADLAMP LH	BROKEN	1,224.00	1,224.00
1	HEADLAMP BRACKET LH	BROKEN	55.00	55.00
1	FRONT DOOR LH	TO REPAIR SEE LABOUR	1,658.00	-
1	FRONT DOOR STEP GARNISH LH	TO REPAIR SEE LABOUR	239.80	-
1	FRONT RADIATOR GRILLE ASSY	MISSING	711.00	711.00
	LESS 25% DISCOUNT		-1,358.93	-847.84
			4,076.77	2,543.51
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	45.00	30.00
			45.00	30.00
	<b><u>LABOUR</u></b>			
	TO DISMANTLE, REPLACE, CUT, WELD, KNOCK OUT DENTS TO STRAIGHTEN ACCIDENT PARTS AS-MENTIONED ON THE 'PARTS REPAIR' COLUMN INCLUSIVE OF REPLACEMENT PARTS. INCLUSIVE OF THE REPAIR OF FRONT DOOR LH AND FRONT DOOR STEP GARNISH LH.		855.00	300.00
	PUTTY & SPRAY PAINTING TO ADJACENT PANELS. JOB ALLOWANCE. PAINT / MATERIAL.		850.00	400.00
	APPLY RUST PROOFING ON THE ADJACENT PANELS.		50.00	30.00
	WIRING / BULB CHECKING (INCLUSIVE OF RE-FOCUS / RE-ADJUST ON ANGLE OF LIGHT INTENSITY).		45.00	30.00
			1,800.00	760.00
	<b>GRAND TOTAL</b>		<b>5,921.77</b>	<b>3,333.51</b>

Report Ref No. CS3/LPC21012182/Vty3e2-1



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,650.00
---	--	--	----------

Report Ref No. CS3/LPC21012182/Vty3e2-1

THEVAN THOMAS KARTHIKESAVAN

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.