



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CS3/LPC21012182/Vty3e2-1 Date: 10/06/2022 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YM 6773Z	Veh. Inspected	PC 9644C	
Policy No.	Z/21/VC00/111621	Coverage (\$)	0.00	
Claim No.	21/21/21/VC00/025205	Excess (\$)	0.00	
Assign From	GERALD POH	Assign Date	25/03/2022	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA HIACE COMMUTER GL	c.c	2754	
Engine No.	HIDDEN	Year of Reg.	2021	
Chassis No.	GDH2232001418	Colour	WHITE	
Odometer	3896 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	196/80 R15	BRIDGESTONE	6 mm	
L/H Front Tyre	196/80 R15	BRIDGESTONE	6 mm	
R/H Rear Tyre	196/80 R15	BRIDGESTONE	6 mm	
L/H Rear Tyre	196/80 R15	BRIDGESTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	30/11/2021	Inspection Date	02/12/2021	
Survey held at	GARAGE 13 PTE LTD 8 KAKI BUKIT AVE 4 #03-46 PREMIER SINGAPORE 415875			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	