



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0231/2022/JT
DATE : 24-Mar-22
WIP : 16988

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 25/3/22

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Adrian

4 days - ok - Johnny Boo

22-Jun-22

OWNER'S NAME : MR RAMESH THIYAGARAJAN
ADDRESS : 166 LENTOR LOOP
#14-02
SINGAPORE 789097
TELEPHONE : HP +65 81273354
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1900139775-02
VEHICLE NO : **SLV 2711 K**
MODEL CODE : AUDI A3 SEDAN 1.0 TFSI
MODEL YEAR : 26/7/2019
ENGINE NO : CHZ C30753
CHASSIS NO : WAUZZZ8VKA089311
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 23-Mar-22
PLACE OF ACCIDENT : LOYANG WAY

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLV 2711 K

S/N	NATURE OF JOBS		ESTIMATED CHARGES		SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$	360.00		
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	350.00	\$	250.00
3	TO REMOVE AND REINSTALL AIRCON CONDENSER, ADDITIONAL RADIATORE AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. TO CARRY OUT PRESSURISE, VACUUM AND REGAS.	S/N \$	1,400.00		
4	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND RHS HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSTION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	4,000.00	\$	1,000.00
5	TO RESPRAY FRONT BUMPER, BONNET HINGES AND RHS UPPER A-PILLAR.	\$	3,000.00	\$	1,100.00
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	\$	192.00
TOTAL LABOUR CHARGES		:	\$ 9,302.00	\$	<u>2,542.00</u>

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLV 2711 K

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER	1	\$ 2,432.00	
2	FRONT BUMPER FIXING PARTS	1	\$ 195.00	
3	FRONT BUMPER GRILLE - CENTER	1	\$ 179.00	
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTER	1	\$ 571.00	
5	FRONT BUMPER CLOSING ELEMENT - RH	1	\$ 318.00	
6	FRONT BUMPER TRIM COVER - RH	1	\$ 182.00	
7	FRONT BUMPER ADAPTER - RH	1	\$ 42.00	
8	RADIATOR GRILLE	1	\$ 1,578.00	\$ 1,262.40
9	RADIATOR GRILLE CLOSING ELEMENT	1	\$ 210.00	\$ 168.00
10	AIR COND STICKER	1	\$ 9.00	\$ 6.64
11	CAUTION STICKER	1	\$ 16.00	\$ 12.40
12	FRONT BUMPER AIR GUIDE GRILLE - RH	1	\$ 210.00	
13	FRONT BUMPER FOAM FILLER PIECE	1	\$ 211.00	
14	FRONT BUMPER REINFORCEMENT BEAM	1	\$ 847.00	
15	FRONT BUMPER REINFORCEMENT BEAM COVER	1	\$ 136.00	
16	BONNET	1	\$ 3,348.00	\$ 2,678.40
17	BONNET ATTACHMENT PARTS	1	\$ 172.00	
18	BONNET HINGE - LH / RH	2	\$ 136.00	\$ 108.48
19	BONNET CATCH HOOK	1	\$ 100.00	
20	BONNET STRIKER - RH	1	\$ 123.00	
SUB TOTAL SPARE PARTS			\$ 11,015.00	\$ 4,236.32

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLV 2711 K

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
		c/f		\$ 4,236.32
21	BONNET EDGE PROTECTION	1	\$ 31.00	\$ 24.72
22	BONNET LOCK MICRO-SWITCH	1	228.00	
23	BONNET BOWDEN CABLE - CENTER	1	64.00	
24	BONNET RELEASE CABLE COVER	1	11.00	
25	BONNET SOUND ABSORBER	1	244.00	
26	BONNET CATCH HOOK LOWER	1	71.00	
27	HEADLIGHT - RH	1	5,879.00	\$ 4,703.20
28	LIFT CYLINDER - RH	1	156.00	
29	LIFT CYLINDER HOSE	1	78.00	
30	OUTSIDE TEMPERATURE SENSOR BRACKET	1	21.00	
31	RADIATOR AIR GUIDE - RH	1	28.00	
32	RADIATOR SEAL - RH OUTER	1	9.00	
33	RADIATOR AIR GUIDE - LH	1	28.00	
34	RADIATOR AIR GUIDE - UPPER CENTER	1	14.00	
35	LOCK CARRIER	1	806.00	
36	RADIATOR COOLANT	6	282.00	
37	INTAKE AIR GUIDE	1	59.00	
38	INTAKE AIR GUIDE COVER	1	30.00	
39	INTAKE AIR GUIDE OUTER	1	21.00	
40	INTAKE AIR GUIDE HOSE	1	69.00	
41	FRONT NO PLATE	S/N	\$ 60.00	\$ 60.00
42	SUNDRIES		\$ 350.00	
TOTAL SPARE PARTS			\$ 19,554.00	\$ 9,024.24
TOTAL LABOUR CHARGES			\$ 9,302.00	\$ 2,542.00
GRAND TOTAL			\$ 28,856.00	\$ 11,566.24

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.
 bl-27/05/22



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT