

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22002795/AQCN2**Date:** 28/06/2022**REFERENCE**

Insured/Claimant: RAMESH THIYAGARAJAN Policy No: 1900139775-02
Date of Loss: 19/03/2022 Nature of Claim: OD Claim No: 3023073591SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLV2711K**
Make & Model: AUDI A3, 999cc SEDAN TFSI S TRONIC (LED) (A) Engine No: CHZC30753
Reg. Date: 26/07/2019 (Man. Year: 2019) Chassis No: WAUZZZ8V4KA089311
Colour: Black Odometer: 42681 km
Engine Capacity: 999 cc
Market Value/New Car Price: S\$102,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 205/55R16 Rear Tyre Size: 205/55R16
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,649.00	3,242.40	1,406.60	30.26
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,792.00	3,917.00	1,875.00	32.37
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,441.00	7,159.40	3,281.60	31.43
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	9,841.00	6,559.40	3,281.60	33.35
+ GST 7.00/7.00% (S\$)	688.87	459.16	229.71	33.35
Nett Amount (S\$)	10,529.87	7,018.56	3,511.31	33.35

INSPECTION

Date of Assignment: 28/03/2022
Date Inspected: 25/03/2022 Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699
Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*CD PILLAR-LH	Dented	3,078.00 FS	*2,462.40 FS
2	1		*REAR WHEEL SPOILER-LH	Not Necessary	39.00 FS	*- FS
3	1		*D PILLAR COVER-LH	Not Necessary	4.00 FS	*- FS
4	1		*REAR WHEEL HOUSING LINER-LH	Not Necessary	260.00 FS	*- FS
5	1		*UNDERBODY TRIM-LH	Not Necessary	188.00 FS	*- FS
6	1		*ARYLIC SEALANT	Necessary	180.00 FS	*180.00 FS
7	1		*CAVITY WAX	Necessary	140.00 FS	*140.00 FS
8	1		*STONE CHIP	Necessary	180.00 FS	*180.00 FS
9	1		*METAL FILLER POWDER	Necessary	280.00 FS	*280.00 FS
10	1		*SUNDRIES	Not Necessary	300.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	4,649.00	3,242.40
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REINSTALL REAR SEAT,BACK REST,HAT TRAY,CD PILLAR TRIMS,LUGGAGE COMPARTMENT TRIMS.DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC	New	1,400.00	1,400.00
2	TO CUT OUT AND WELD LHS SILL PANEL	New	2,800.00	1,500.00
3	TO RESPRAY LHS SILL PANEL AND DOOR ENTRANCE	New	1,400.00	825.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
			Gross Labour Cost (\$)	5,792.00
				3,917.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >