

STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number: 63685592

Estimator Telephone Number : 68662623 Accident Reporting Number : 68662672

User ID PohSuan

	Section A - Accident Details
Registration Number	SHF373Y
Case Reference Number	TAX/03/22/2056
Registration Date	19/12/2017
Company Type	Strides Taxi Pte Ltd
Make	ТОУОТА
Model	PRIUS4
Name of Driver	AMIR BIN OSMAN
Type of Accident	Head to Rear
Accident Date and Time	25/3/2022 8:29 AM
Accident Reported Date and Time	25/3/2022 10:59 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24114375
Special Instruction to ARC,if	TP/ REAR PORTION
Prepared Date and Time	25/3/2022 2:02 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates							
Summary of Repair Estimate	es es						
	Quotation from ARC	Adjusted by Surveyor, if applicable					
Total Labour Cost	\$1,602.00	\$400.00					
Total Spray Cost	\$1,924.00	\$500.00					
Total Spare Part Cost	\$8,144.23	\$1,796.45					
Total Other Cost	\$380.00	(\$546.45)					
TOTAL COST	\$12,050.23	\$2,150.00 (L/S)					
Lump Sum Total	\$0.00	\$0.00					
Number of Repair Days	7.0	4.0					
Prepared / Adjusted By	Boon Chew Tay	RASUL (LKK) / NTUC					
ARC / Surveyor Sign Off Date	31/03/2022 3:56 PM	31/03/2022 9:27 AM					
Signature		Rasul					
Remarks	Total number of repair days = 4 days. SUP = + 1 day.	LUMP SUM REPAIR / RESURVEY AFTER REPAIR					



STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number: 63685592

Estimator Telephone Number : 68662623 Accident Reporting Number : 68662672

User ID PohSuan

	Section C - Quota	tion and Accident Invoice Details	
Quotation Number	QN-2204-0337	Invoice Number	
Quotation Date	25.04.2022	Invoice Date	
Invoice Amount		Prepared Date	

	Section D - Details of Repair Estimates	
Part 1 - Labour Works		
Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR REAR END PANEL	\$250.00	\$100.00
TO REPAIR REAR PORTION	\$1,352.00	\$300.00
Total Labour	\$1,602.00	\$400.00

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR SPOILER	\$250.00	\$100.00
TO RESPRAY REAR PANEL	\$180.00	\$100.00
TO RESPRAY TAIL GATE	\$378.00	\$0.00
TO RESPRAY TAILGATE OUTSIDE GARNISH	\$378.00	\$100.00
TO RESPRAY REAR SPARE TYRE PANEL	\$180.00	\$0.00
O RESPRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY REAR PANEL	\$180.00	\$0.00
Fotal Spray Painting & Panel Beating	\$1,924.00	\$500.00

lob Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
O WASH AND VACUUM	\$60.00	\$0.00
O REPLACE SUNDRY PARTS	\$100.00	\$0.00
O APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$0.00
O TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$0.00
ump Sum Adjustment by Surveyor	\$0.00	(\$546.45)
Fotal Other Costs	\$380.00	(\$546.45)

Part	Portion	Stock	Part Name	Quantity	List Price	Discount	Final Price	Estimator	Surveyor
Number		Number			(\$)	(%)	(\$)	Approved	Approved
		52159479 13	COVER, RR BUMPER ASSY	1.00	\$423.90	100.00	\$0.00	Replace	Repair
		52023470	REAR BUMPER	0.00	\$318.80	0.00	\$0.00	Replace	Not Given
		30	REINFORCEMENT						
		52462470 30	PAD, RR BUMPER, RH & LH,	0.00	\$3.80	0.00	\$0.00	Replace	Not Given
		52462470 20	PAD, RR BUMPER, RH & LH, 2	0.00	\$3.80	0.00	\$0.00	Replace	Not Given
		52462470 10	PAD, RR BUMPER, RH & LH ,	0.00	\$3.80	0.00	\$0.00	Replace	Not Given
		52461470 10	PAD, RR BUMPER, CTR	0.00	\$2.20	0.00	\$0.00	Replace	Not Given
		52191470 30	SEAL, RR BUMPER ARM, RH & LH	0.00	\$11.00	0.00	\$0.00	Replace	Not Given
		52599680 30	STOPPER, RR BUMPER, RH & LH	0.00	\$4.30	0.00	\$0.00	Replace	Not Given
		52575470 40	RETAINER, RR BUMPER, RH	0.00	\$112.70	0.00	\$0.00	Replace	Not Given
		52576470 40	RETAINER, RR BUMPER, LH	0.00	\$111.50	0.00	\$0.00	Replace	Not Given
		52591470 50	SEAL, RR BUMPER , RH	0.00	\$85.20	0.00	\$0.00	Replace	Not Given



STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd 60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 26/04/2022 User ID PohSuan

	re Parts / I	10 69430520 50 58307470 90 58311471 30	TAIL GATE LOCK COVER , BACK DOOR TAIL GATE STRIKER ASSY, BACK DOOR STRIDES LOGO STICKER DECAL 6555 8888 END PANEL SUB-ASSY, BODY LOWER BACK SPARE TYRE PANEL , PAN, REAR FLOOR SEALANT SIKAFLEX	0.00 1.00 1.00 0.00 0.00	\$25.30 \$24.90 \$7.80 \$21.60 \$629.80 \$564.80 \$37.00 \$8,616.70	0.00 0.00 0.00 0.00 0.00 0.00	\$0.00 \$0.00 \$7.80 \$21.60 \$0.00 \$0.00 \$565.82	Replace Replace Replace Replace Replace Replace Replace	Not Given Not Given Replace Replace Not Given Not Given Not Given
		58307470 90 58311471	BACK DOOR TAIL GATE STRIKER ASSY, BACK DOOR STRIDES LOGO STICKER DECAL 6555 8888 END PANEL SUB-ASSY, BODY LOWER BACK SPARE TYRE PANEL, PAN, REAR FLOOR SEALANT SIKAFLEX	0.00 1.00 1.00 0.00	\$24.90 \$7.80 \$21.60 \$629.80 \$564.80 \$37.00	0.00 0.00 0.00 0.00 0.00	\$0.00 \$7.80 \$21.60 \$0.00 \$0.00	Replace Replace Replace Replace Replace	Not Given Replace Replace Not Given Not Given
otal		58307470 90 58311471	BACK DOOR TAIL GATE STRIKER ASSY, BACK DOOR STRIDES LOGO STICKER DECAL 6555 8888 END PANEL SUB-ASSY, BODY LOWER BACK SPARE TYRE PANEL, PAN, REAR FLOOR	0.00 1.00 1.00 0.00	\$24.90 \$7.80 \$21.60 \$629.80 \$564.80 \$37.00	0.00 0.00 0.00 0.00 0.00	\$0.00 \$7.80 \$21.60 \$0.00 \$0.00	Replace Replace Replace Replace Replace	Not Given Replace Replace Not Given Not Given
		58307470 90 58311471	BACK DOOR TAIL GATE STRIKER ASSY, BACK DOOR STRIDES LOGO STICKER DECAL 6555 8888 END PANEL SUB-ASSY, BODY LOWER BACK SPARE TYRE PANEL, PAN, REAR FLOOR	0.00 1.00 1.00 0.00	\$24.90 \$7.80 \$21.60 \$629.80 \$564.80 \$37.00	0.00 0.00 0.00 0.00 0.00	\$0.00 \$7.80 \$21.60 \$0.00 \$0.00	Replace Replace Replace Replace Replace	Not Given Replace Replace Not Given Not Given
		58307470 90 58311471	BACK DOOR TAIL GATE STRIKER ASSY, BACK DOOR STRIDES LOGO STICKER DECAL 6555 8888 END PANEL SUB-ASSY, BODY LOWER BACK SPARE TYRE PANEL, PAN, REAR FLOOR	0.00 1.00 1.00 0.00	\$24.90 \$7.80 \$21.60 \$629.80 \$564.80	0.00 0.00 0.00 0.00 0.00	\$0.00 \$7.80 \$21.60 \$0.00	Replace Replace Replace Replace Replace	Not Given Replace Replace Not Given Not Given
		58307470 90 58311471	BACK DOOR TAIL GATE STRIKER ASSY, BACK DOOR STRIDES LOGO STICKER DECAL 6555 8888 END PANEL SUB-ASSY, BODY LOWER BACK SPARE TYRE PANEL, PAN,	0.00 1.00 1.00 0.00	\$24.90 \$7.80 \$21.60 \$629.80	0.00 0.00 0.00 0.00	\$0.00 \$7.80 \$21.60 \$0.00	Replace Replace Replace Replace	Not Given Replace Replace Not Given
		10 69430520 50 58307470	BACK DOOR TAIL GATE STRIKER ASSY, BACK DOOR STRIDES LOGO STICKER DECAL 6555 8888 END PANEL SUB-ASSY,	0.00 1.00	\$24.90 \$7.80 \$21.60	0.00	\$0.00 \$7.80 \$21.60	Replace Replace	Not Given Replace Replace
		10 69430520 50	BACK DOOR TAIL GATE STRIKER ASSY, BACK DOOR STRIDES LOGO STICKER DECAL 6555 8888	0.00 1.00	\$24.90 \$7.80 \$21.60	0.00	\$0.00 \$7.80 \$21.60	Replace Replace	Not Given Replace Replace
		10 69430520	BACK DOOR TAIL GATE STRIKER ASSY, BACK DOOR STRIDES LOGO	0.00	\$24.90 \$7.80	0.00	\$0.00 \$7.80	Replace Replace	Not Given Replace
		10 69430520	BACK DOOR TAIL GATE STRIKER ASSY, BACK DOOR	0.00	\$24.90	0.00	\$0.00	Replace	Not Given
		10 69430520	BACK DOOR TAIL GATE STRIKER ASSY, BACK DOOR		\$24.90		<u> </u>	· ·	
		10	BACK DOOR				<u> </u>	· ·	
				0.00	\$25.30	0.00	\$0.00	Replace	Not Given
						+	+	1	NI de Oissess
		50	BACK DOOR	0.00	ψ402.10	0.00	ψυ.υυ	Tehlace	Not Given
		30 69350470	LUGGAGE COMPARTMENT TAIL GATE LOCK ASSY,	0.00	\$452.10	0.00	\$0.00	Replace	Not Given
		1	NAME PLATE (PRIUS) ,	1.00	\$52.30	25.00	\$39.23	Replace	Replace
		30	LUGGAGE COMPARTMENT	1.00	ψυ2.υ0	25.00	ψυσ.Δυ	Tehlace	Teplace
		90 75442471	NAME PLATE (PRIUS) ,	1.00	\$52.30	25.00	\$39.23	Replace	Replace
		1	NAME PLATE (HYBRID) ,	1.00	\$52.30	25.00	\$39.23	Replace	Replace
		10A1	OUTSIDE GARNISH SUB-		1.20		J0.00	. topiaoc	. topan
		76801471	BACK DOOR TAIL GATE BACK DOOR	1.00	\$891.20	100.00	\$0.00	Replace	Repair
			TAIL GATE WEATHERSTRIP,	0.00	\$360.70	0.00	\$0.00	Replace	Not Given
		40	ASSY, BACK DOOR				<u> </u>		
		10 67005474	TAIL GATE PANEL SUB-	0.00	\$929.60	0.00	\$0.00	Replace	Not Given
		66259470	COVER, REAR FLOOR	0.00	\$222.60	0.00	\$0.00	Replace	Not Given
		30	UNDER , LH	0.00	0000 00	0.00	00.00	<u>_</u>	
		58399470	COVER, REAR FLOOR	0.00	\$234.30	0.00	\$0.00	Replace	Not Given
		10	BUMPER, LH	0.00	ψ400.00	0.00	φυ.υυ	Replace	NOT GIVE!!
		81501470	BUMPER , RH LENS & BODY ASSY , RR	0.00	\$486.80	0.00	\$0.00	Replace	Not Given
		1	LENS & BODY ASSY , RR	0.00	\$486.80	0.00	\$0.00	Replace	Not Given
		51	COMBINATION LAMP, LH						
		81 81561471	COMBINATION LAMP, RH LENS & BODY, REAR	0.00	\$438.10	0.00	\$0.00	Replace	Not Given
			LENS & BODY, REAR	0.00	\$438.10	0.00	\$0.00	Replace	Not Given
		29	SCREW		·		<u> </u>	,	
			REAR BUMPER GROMMET	0.00	\$2.20	0.00	\$0.00	Replace	Not Given
		89997301 00	ANTENNA, ELECTRICAL KEY	0.00	\$60.30	0.00	\$0.00	Replace	Not Given
		0000=00	ANTENNA ELECTRICA CONTRA	0.00	000.00	0.00	00.00		N / 0:
			SENSOR REVERSE	0.00	\$180.00	0.00	\$0.00	Replace	Not Given
		00	FILLER, RR BUMPER , LH	0.00	\$119.90	0.00	\$0.00	Replace	Not Given
		00	CILLED DD BLIMDED 111	0.00	¢110.00	0.00	¢0.00	Donland	Not Civen
		52565479	FILLER, RR BUMPER, RH	0.00	\$119.90	0.00	\$0.00	Replace	Not Given
		10	LOWER	1.00	φυυσ.ου	23.00	φ410.73	Replace	Tehlace
		10 52453470	BUMPER GUARD, RR BUMPER,	1.00	\$558.30	25.00	\$418.73	Panlaca	Replace
		1	CLIPS PIECE, FRT & RR	0.00	\$1.50	0.00	\$0.00	Replace	Not Given
		40	SEAL, RR BUMPER , LH	0.00	\$85.20	0.00	\$0.00	Replace	Not Given

(%)

25.00

25.00

\$318.80

\$1,322.10

1,640.90

(\$) \$239.10

\$991.58

1,230.68

Check

Replace

Replace

Check

Replace

Replace

1,796.50

Number 52023470 REAR BUMPER

16

+ 400.00

500.00 L/S \$2,150/-

1.00

1.00

2,696.50 -20% 2,157.20

Number

Total