



Case Details

Case Reference Number :
TAX/03/22/2055

Type of Repair : Accident Repair

Vehicle Registration Number : SHB1566Y

Company Type : Strides Taxi Pte Ltd

Estimation ID : EST-17816-ID

Assigned By : Taxi Claims Manager Team

Insurance Company Name : NTUC Income Insurance Co-operative Ltd

Accident Date and Time : 24/03/2022 09:00 AM

Vehicle Age(In Months) : -

Documents / Photographs

View Documents / Photographs

Total Documents: 0

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
Standard	Main			SENSOR-RR PARK DIST CONT	3	65.00	195.00	10.00	175.50	Replace	0	0	Not Give ▾	X _{an}
Standard	Main			FASCIA-RR BPR	1	758.47	758.47	10.00	682.62	Replace	0	0	Not Give ▾	X _{an}
Standard	Main			FASCIA-RR BPR LWR	1	230.68	230.68	10.00	207.61	Replace	0	0	Not Give ▾	X _{an}
Standard	Main			FINISHER-RR BPR - RH	1	47.42	47.42	10.00	42.68	Replace	0	0	Not Give ▾	X _{an}
Standard	Main			BRACKET ASM-RR BPR FASCIA SI - RH	1	29.84	29.84	10.00	26.86	Replace	0	0	Not Give ▾	X _{an}
Standard	Main			BRACKET-RR BPR FASCIA LWR MTG	1	12.79	12.79	10.00	11.51	Replace	0	0	Not Give ▾	X _{an}
Standard	Main			BAR ASM-RR BPR IMP	1	339.76	339.76	10.00	305.78	Replace	0	0	Not Give ▾	X _{an}
Standard	Main			LINER ASM-RR W/H PNL - R	1	85.49	85.49	10.00	76.94	Replace	0	0	Not Give ▾	X _{an}
Standard	Main			PANEL-BODY SI OTR-R	1	1,434.89	1,434.89	10.00	1,291.40	Replace	1	0	Repair ▾	R
Standard	Main			WINDOW ASM-QTR - RH	1	251.48	251.48	10.00	226.33	Replace	0	0	Not Give ▾	X _{an}
Standard	Main			SEALANT SIKAFLEX	1	37.00	37.00	0.00	37.00	Replace	0	0	Not Give ▾	X _{an}
Total Spare Part Cost									3,084.23	Surveyor Total		0.00		
Lump Sum Discount (%)									0.00	Lump Sum Dis (%)		0		
Final Spare Part Cost									3,084.23	Final Sur Total		0.00		

Labour's Cost Detail

4:16 PM

https://vacswed.smrt.com.sg/estimation.aspx

No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR REAR RHS PORTION	1,800.00	0 X _{nn}	
Total:			1,800.00	0.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY REAR BUMPER	428.00	0 X _{nn}	
2	Main	TO RESPRAY REAR FENDER RH	428.00	200	
Total:			856.00	200.00	

Other Cost Detail


S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO WASH AND VACUUM	60.00	0 X _{nn}	
2	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	120.00	0 X _{nn}	
3	Main	TO REPLACE SUNDRY PARTS	120.00	0 X _{nn}	
4	Main	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0 X _{nn}	
5	Main	TO CHECK & RESET SYSTEM FUNCTION	350.00	0 X _{nn}	
6	Main	ISOLATED OF (EV) (NET)	150.00	0 X _{nn}	
7	Main	TO REMOVE & REFIT REAR QUARTER GLASS RH	120.00	0 X _{nn}	
Total:			1,040.00	0.00	

Summary

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Total Spare Part Detail	3,084.23	0.00
Total Labour Cost	1,800.00	0.00
Total Spray Painting	856.00	200.00
Other	1,040.00	0.00
Overall Total	6,780.23	200.00
Lump Sum Repair Option		☐
Lump Sum Total	0.00	200.00

2, 4:18 PM

<https://vacswep.smrt.com.sg/Estimation.aspx>

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Surveyor Approved Amount		200.00
No of Repair Days*	6	2
Remarks	-	PART BY PART REPAIR / RESURVEY AFTER REPAIR
Surveyor Name		Rasul
Signature		
Survey Date	25/03/2022	

Save Clear

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: