

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC6/AIG22002801/UGA3Q2**Date:** 15/06/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700042949
<b>Claimant Vehicle No :</b>	GW448M	<b>Insured Vehicle No :</b>	GBG5090X
Date of Loss:	05/03/2022	Nature of Claim:	TP
		Claim No:	6326482028SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>GW448M</b>	Engine No:	4JG2928030
Make & Model:	ISUZU TFR69H, 3.1 D (M)	Chassis No:	JAATFR69H37100794
Reg. Date:	20/02/2003 (Man. Year: 2003)	Odometer:	459005 km
Colour:	Silver		
Engine Capacity:	3059 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R14	Rear Tyre Size:	195 R14
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	3,316.39	2,345.93	970.46	29.26
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,800.00	1,230.00	570.00	31.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>5,116.39</b>	<b>3,575.93</b>	<b>1,540.46</b>	<b>30.11</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,850.00</b>		
<b>(S\$)</b>	5,116.39	2,850.00	2,266.39	44.30
<b>+ GST 7.00/7.00% (S\$)</b>	358.15	199.50	158.65	44.30
<b>Nett Amount (S\$)</b>	<b>5,474.54</b>	<b>3,049.50</b>	<b>2,425.04</b>	<b>44.30</b>
<b>+ Loss of Use (3.0 x S\$100.00/day) (S\$)</b>		300.00		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>3,351.50</b>		

INSPECTION

Date of Assignment:	28/03/2022		
Date Inspected:	28/03/2022	Inspected At:	Tan Lim Motor Pte Ltd (Defu) 1 Defu Lane 6 Singapore 539365
Estimated Period of Repair:	3.0 days		

**Adjuster:** MARCUS CHUA**Manager:** Chong Pui Lin*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and*

*ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted	1,291.60 FL	*1,291.60 FL
2	9		*REAR BUMPER CHROEM BOLTS	Not Necessary	135.00 FL	*- FL
3	2		*REAR BUMPER BRACKET	Repair	294.60 FL	*- FL
4	1		*REAR BUMPER TOP SKID PLATE	Bent	455.00 FL	*455.00 FL
5	2		*REAR LICENCE PLATE LAMP	Not Necessary	98.20 FL	*- FL
6	1		*TAILGATE LID	Dented	1,283.30 FL	*1,283.30 FL
7	2		*TAILGATE LID SIDE LOCK	Not Necessary	180.00 FL	*- FL
8	1		*O/S TAILLAMP	Cracked	250.00 FL	*250.00 FL
9	1		*REAR END PANEL	Repair	650.00 FL	*- FL
10	1		*REAR LICENCE PLATE	Cracked	50.00 FS	*40.00 FS
11	1		*TAILGATE LID 70KM/H STICKER	Necessary	20.00 FS	*10.00 FS
					<b>Sub Total (\$\$)</b>	<b>4,707.70      3,329.90</b>
					<b>- List Item Discount on L Items 30.00/30.00% (\$\$)</b>	<b>1,391.31      983.97</b>
					<b>Total Parts (\$\$)</b>	<b>3,316.39      2,345.93</b>

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	60.00	20.00
2	TO RUST-PROOFING OF THE AFFECTED AREAS	New	120.00	30.00
3	TO TRANSFER OF TAILGATE FITTINGS ,FIXTURE AND PERFORM WATERSEEPAGE TEST	New	120.00	0.00
4	PANEL BEATING ,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION ,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	700.00	580.00
5	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	800.00	600.00
<b>Gross Labour Cost (\$)</b>			<b>1,800.00</b>	<b>1,230.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >