



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

AIGAsia Insured's Veh No : GBG5090X
Date of Accident : 05 March 2022

1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

Messrs Sam Lain Equipment Services Pte Ltd

Date : 09 March 2022

Estimate To Repair GW448M - Isuzu TFR69H-29 (T)
Chassis No : JAATFR69H37100794

S/No	Quantity	Description	Amount
		<u>LIST ITEMS</u>	
01	1 pc	rear bumper	\$ 1,291.60
02	9 ps	rear bumper chrome bolts @ \$15.00	\$ 135.00
03	2 ps	rear bumper bracket @ \$147.30	\$ 294.60
04	1 pc	rear bumper top skid plate	\$ 455.00
05	2 ps	rear licence plate lamp @ \$49.10	\$ 98.20
06	1 pc	tailgate lid	\$ 1,283.30
07	2 ps	tailgate lid side lock @ \$90.00	\$ 180.00
08	1 pc	tail lamp	\$ 250.00
09	1 pc	rear end panel	\$ 650.00
			\$ 4,637.70
		Less 30 %	\$ 1,391.31
			\$ 3,246.39
		<u>SPECIAL NETT ITEMS</u>	
10	1 pc	rear licence plate	\$ 50.00
11	1 pc	tailgate lid 70 Km/h sticker	\$ 20.00
			\$ 70.00
		<u>LABOUR & MISC. CHARGES</u>	
01		To check electrical lighting concerned.	\$ 60.00
02		To rust-proofing of the affected areas.	\$ 120.00
03		To transfer of tailgate fittings, fixture and perform waterseepage test.	\$ 120.00
04		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 700.00
05		Putty and spray painting of the affected portion.	\$ 800.00
			\$ 1,800.00
		Total	\$ 5,116.39

the Repairs of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

not Authorised
Date : 28/3/22
2/5 28/3/22
3 days. Take 2H. After rep.

1,291.60
135.00
294.60
455.00
98.20
1,283.30
180.00
250.00
650.00
3,246.39
50.00
20.00
70.00
60.00
120.00
120.00
700.00
800.00
1,800.00
5,116.39
20%
7,860.74