

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG22002803/EEA3Q2**Date:** 19/04/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100480447
Claimant Vehicle No :	SKT6372B	Insured Vehicle No :	SGB831A
Date of Loss:	02/01/2022	Nature of Claim:	TP
		Claim No:	2417258254SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKT6372B	Engine No:	G4FGFH768344
Make & Model:	KIA FORTE K3, 1.6 (A)	Chassis No:	KNAFZ411MF5404925
Reg. Date:	18/06/2015 (Man. Year: 2015)	Odometer:	135822 km
Colour:	White		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/45 R17	Rear Tyre Size:	215/45 R17
Front Left Side:	Yokohama 4 mm	Rear Left Side:	Yokohama 4 mm
Front Right Side:	Yokohama 4 mm	Rear Right Side:	Yokohama 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,272.40	848.80	1,423.60	62.65
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,080.00	980.00	2,100.00	68.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,352.40	1,828.80	3,523.60	65.83
+ GST 7.00/7.00% (S\$)	374.67	128.02	246.65	65.83
Nett Amount (S\$)	5,727.07	1,956.82	3,770.25	65.83
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment:	28/03/2022	
Date Inspected:	28/03/2022	Inspected At: Cycle & Carriage KIA Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	3.0 days	

Adjuster: CHEN TSUE YEE**Manager:** Asher Sng Rong Yi*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*C&C BADGE	Not Necessary	50.00 FS	*- FS
2	1		*SUNDRIES	Necessary	20.00 FS	*20.00 FS
3	1		*COVER -RR BUMPER	Broken	632.80 FS	*632.80 FS
4	1		*COVER -RR BUMPER ,UPR	Cut	196.00 FS	*196.00 FS
5	1		*COVER -RR BPR UNDER	Not Necessary	33.60 FS	*- FS
6	1		*WIRING HARNESS -BWS ,EXT	Not Necessary	138.40 FS	*- FS
7	1		*BEAM -RR BUMPER	Not Necessary	292.00 FS	*- FS
8	1		*STAY -RR BUMPER LH	Not Necessary	60.00 FS	*- FS
9	1		*STAY -RR BUMPER RH	Not Necessary	60.00 FS	*- FS
10	1		*ANTENNA ASSY -SMARTKEY	Not Necessary	55.20 FS	*- FS
11	1		*GUARD -BUMPER REAR ,RH	Not Necessary	13.60 FS	*- FS
12	1		*BRACKET -RR BUMPER SIDE MTG ,LH	Not Necessary	26.40 FS	*- FS
13	1		*BRACKET -RR BUMPER SIDE MTG ,RH	Not Necessary	26.40 FS	*- FS
14	4		*ULTRASONIC SENSOR ASSY -FBWS	Not Necessary	598.40 FS	*- FS
15	1		*LOGO ASSY -KIA SUB	Not Necessary	29.60 FS	*- FS
16	1		*EMBLEM -CERATO	Not Necessary	28.00 FS	*- FS
17	1		*EMBLEM K3	Not Necessary	12.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$) **2,272.40** **848.80**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW RR BUMPER REPAIR RR END PNL & BOOTLID	New	1,600.00	400.00
2	RESPRAY RR BUMPER ,RR END PNL & BOOTLID	New	1,050.00	350.00
3	REMOVE & REFIT RR FLR BOARD ,TRIM & CARPET	New	120.00	0.00
4	CHECK WIRING ELECTRICAL SYSTEM	New	30.00	30.00
5	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM	New	120.00	120.00
6	REMOVE & REFIT REVERSE SENSOR	New	80.00	80.00
7	APPLY ANTI CORROSION ON AFFECTED AREAS	New	80.00	0.00
			Gross Labour Cost (\$)	3,080.00
				980.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >