





## ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name	LCV16158/Kong Chow Hook
	Reg No/Reg Date	SKT6372B*# / 18/06/201
	Date In/Mileage	/ 0
	Chassis No	KNAFZ411MF5404925
	Engine No	G4FGFH768344
	Make/Model	KIA/15MY F K3 1.6 A SX 690 BLACK
	Colour/Trim	SWP / WK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	03/01/2022/ 14:54	TLE	261 / Edwin Caina	45014

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW RR BUMPER REPAIR RR END PNL & BOOTLID				1600.00
E PNT98000 RESPRAY RR BUMPER , RR END PNL & BOOTLID				1050.00
E PNT88000 REMOVE & REFIT RR FLR BOARD , TRIM & CARPET				120.00
A 54900099 CHECK WIRING ELETRICAL SYSTEM				30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM				120.00
E PNT88000 REMOVE & REFIT REVERSE SENSOR				80.00
M SUNDRY APPLY ANTI CORROSION ON AFFECTED AREAS				80.00
M SUNDRY SUPPLY C&C BADGE				50.00
M SUNDRY Sundries				20.00
M COVER-RR BUMPER	1.00	791.00	20.00	632.80
M COVER-RR BUMPER,UPR	1.00	245.00	20.00	196.00
M COVER-RR BPR UNDER	1.00	42.00	20.00	33.60
M WIRING HARNESS-BWS EXT	1.00	173.00	20.00	138.40
M BEAM-RR BUMPER	1.00	365.00	20.00	292.00
M STAY-RR BUMPER LH	1.00	75.00	20.00	60.00
M STAY-RR BUMPER RH	1.00	75.00	20.00	60.00
M ANTENNA ASSY-SMARTKEY	1.00	69.00	20.00	55.20
M GUARD-BUMPER REAR,RH	1.00	17.00	20.00	13.60
M BRACKET-RR BUMPER SIDE MTG,LH	1.00	33.00	20.00	26.40
M BRACKET-RR BUMPER SIDE MTG,RH	1.00	33.00	20.00	26.40
M ULTRASONIC SENSOR ASSY-FBWS	4.00	187.00	20.00	598.40
M LOGO ASSY-KIA SUB	1.00	37.00	20.00	29.60
M EMBLEM-CERATO	1.00	35.00	20.00	28.00

# Estimate

**Confirm & accepted by**

- LKKA Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
  - To display damaged part(s) during resurvey
  - Parts prices are subject to confirmation
  - Third party survey is on a "Without Prejudice" basis
  - No illegal modification(s) is allowed

**Authorized signatory and company stamp**

Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



## ESTIMATE

GST Reg No : MR-8500111-X

Reg No : 199405410K

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name	LCV16158/Kong Chow Hook
	Reg No/Reg Date	SKT6372B*# / 18/06/201
	Date In/Mileage	/ 0
	Chassis No	KNAFZ411MF5404925
	Engine No	G4FGFH768344
	Make/Model	KIA/15MY F K3 1.6 A SX 690 BLACK
Colour/Trim	SWP / WK	

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	03/01/2022/ 14:54	TLE	261 / Edwin Caina	45014

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M EMBLEM K3 X	1.00	15.00	20.00	12.00
<h1>Estimate</h1>				
SURVEYOR NAME: <u>Steve (LKK) 28/3/22, 1:30 PM</u> SURVEYOR SIGNATURE: _____ <i>m PL</i> DATE: _____ <i>PIP</i> REMARKS: _____ <i>by BEL H</i> _____ <i>3 d/s</i>				

Confirm & accepted by			
	7% GST on	5352.40	374.67
		Nett	5,352.40
		<b>Total Payable</b>	<b>5,727.07</b>
Authorized signatory and company stamp			

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.