

## Vehicle Damage Assessment Report for [SHC8613T]

Estimate Created: 28/03/2022 06:52 by LKK\_admin-a  
(LKK\_Auto\_Consultants\_Pte\_Ltd)

Owned: 12/10/2022 15:24 by LKK\_cs-a (LKK\_Auto\_Consultants\_Pte\_Ltd)

### General Information

|                   |                              |                  |
|-------------------|------------------------------|------------------|
| Insurance Company | III                          | Claim Number     |
| Claim Type        | TP                           |                  |
| Workshop          | LKK_Auto_Consultants_Pte_Ltd | Reference Number |

### Vehicle Information

|                      |          |                    |       |
|----------------------|----------|--------------------|-------|
| Brand                | Hyundai  | Model              | Ioniq |
| Engine Type          |          |                    |       |
| License Plate Number | SHC8613T | VIN (or Chassis #) |       |

### Vehicle Condition

|                 |                 |         |
|-----------------|-----------------|---------|
| Damaged Diagram | Odometer        | 0.00 Km |
|                 | Tyres Condition |         |
|                 | Front Left      | mm      |
|                 | Front Right     | mm      |
|                 | Rear Left       | mm      |
|                 | Rear Right      | mm      |

### Comments

- Final review based on information provided by BIFORST AUTO PTE LTD:  
Concluded lump sum repair cost of \$28900 with 12 working days.

Insurlogic 4 (12/10/2022 15:23)

**Parts**

| Description                              | Number/Type | Qty | Cost    | Markup/Disc. % | Sum      |
|------------------------------------------|-------------|-----|---------|----------------|----------|
| BONNET                                   |             | 1   | 2253.80 | -20.00 %       | 1,803.04 |
| BONNET HINGE(RH)                         |             | 1   | 118.70  | -20.00 %       | 94.96    |
| RADIATOR GRILLE                          |             | 1   | 1568.60 | -20.00 %       | 1,254.88 |
| FLAP ASSY ACTIVE<br>AIR UPPER            |             | 1   | 1649.20 | -20.00 %       | 1,319.36 |
| FRONT NUMBER<br>PLATE GARNISH            |             | 1   | 188.00  | -20.00 %       | 150.40   |
| FRONT BUMPER<br>COVER                    |             | 1   | 418.30  | -20.00 %       | 334.64   |
| FRONT BUMPER<br>SPONGE                   |             | 1   | 186.90  | -20.00 %       | 149.52   |
| FRONT BUMPER<br>REINFORCEMENT            |             | 1   | 1075.10 | -20.00 %       | 860.08   |
| FRONT BUMPER<br>TOWING COVER             |             | 1   | 29.00   | -20.00 %       | 23.20    |
| FRONT BUMPER<br>MOULDING CENTRE<br>UPPER |             | 1   | 368.50  | -20.00 %       | 294.80   |
| FRONT BUMPER<br>LOWER STIFFNER           |             | 1   | 285.10  | -20.00 %       | 228.08   |
| FRONT BUMPER<br>LOWER GRILLE             |             | 1   | 365.30  | -20.00 %       | 292.24   |
| FRONT BUMPER<br>LOWER GRILLE<br>MOULDING |             | 1   | 127.60  | -20.00 %       | 102.08   |
| FRONT BUMPER<br>BRACKET LH/RH            |             | 1   | 70.00   | -20.00 %       | 56.00    |
| FRONT BUMPER<br>BRACKET                  |             | 1   | 56.00   | -20.00 %       | 44.80    |
| FRONT BUMPER<br>CLIPS                    |             | 1   | 25.00   | -20.00 %       | 20.00    |
| FRONT BUMPER<br>GRILLE                   |             | 1   | 373.80  | -20.00 %       | 299.04   |
| FRONT BUMPER AIR<br>DUCT                 |             | 1   | 307.60  | -20.00 %       | 246.08   |
| DAY LIGHT RH                             |             | 1   | 642.50  | -20.00 %       | 514.00   |
| HEADLIGHT SUPPORT<br>PANEL ASSY          |             | 1   | 949.30  | -20.00 %       | 759.44   |
| HEADLAMP OS                              |             | 1   | 4220.60 | -20.00 %       | 3,376.48 |
| RADIATOR INVERTER                        |             | 1   | 884.80  | -20.00 %       | 707.84   |
| RADIATOR                                 |             | 1   | 710.50  | -20.00 %       | 568.40   |
| RADIATOR FAN<br>BLOWER MOTOR<br>ASSY     |             | 1   | 1226.60 | -20.00 %       | 981.28   |
| FRONT FENDER RH                          |             | 1   | 490.70  | -20.00 %       | 392.56   |
| FRONT FENDER<br>SHIELD RH                |             | 1   | 164.70  | -20.00 %       | 131.76   |
| AIRCON CONDENSER                         |             | 1   | 663.60  | -20.00 %       | 530.88   |

|                                  |   |         |          |          |
|----------------------------------|---|---------|----------|----------|
| ROCKER PANEL<br>OUTER GARNISH    | 1 | 715.60  | -20.00 % | 572.48   |
| ROCKER PANEL OUT<br>GARNISH CLIP | 1 | 65.00   | -20.00 % | 52.00    |
| FRONT WHEEL RIM<br>(RH)          | 1 | 1124.20 | -20.00 % | 899.36   |
| FRONT WHEEL HUB<br>ASSY (RH)     | 1 | 678.50  | -20.00 % | 542.80   |
| FRONT WHEEL HUB<br>CAP           | 1 | 346.40  | -20.00 % | 277.12   |
| FRONT SHOCK<br>ABSORBER          | 1 | 372.50  | -20.00 % | 298.00   |
| FRONT DRIVESHAFT<br>RH           | 1 | 1136.70 | -20.00 % | 909.36   |
| FRONT DRIVESHAFT<br>EXTENSION    | 1 | 1125.80 | -20.00 % | 900.64   |
| RACK & PINION ASSY               | 1 | 2387.40 | -20.00 % | 1,909.92 |
| STG TIE END                      | 1 | 94.70   | -20.00 % | 75.76    |
| STABILIZER BAR                   | 1 | 326.80  | -20.00 % | 261.44   |
| STABILIZER BAR<br>LINK           | 1 | 92.10   | -20.00 % | 73.68    |
| FRONT SUSPENSION<br>LOWER ARM RH | 1 | 596.80  | -20.00 % | 477.44   |
| KNUCKLE ARM RH                   | 1 | 663.60  | -20.00 % | 530.88   |
| ABS SENSOR                       | 1 | 290.00  | -20.00 % | 232.00   |
| BRAKE HOSE RH                    | 1 | 234.60  | -20.00 % | 187.68   |
| ENGINE UNDER<br>COVER            | 1 | 469.40  | -20.00 % | 375.52   |
| ENGINE<br>CROSSMEMBER            | 1 | 1803.90 | -20.00 % | 1,443.12 |
| FRONT PANEL<br>SPEAKER           | 1 | 584.20  | -20.00 % | 467.36   |
| WIPER CONTAINER                  | 1 | 385.40  | -20.00 % | 308.32   |
| ELECTRONIC CLUTCH<br>PUMP        | 1 | 4386.50 | -20.00 % | 3,509.20 |

Parts Subtotal 29,839.92

### Materials

| Description                      | Number/Type | Qty | Cost   | Markup/Disc.% | Sum    |
|----------------------------------|-------------|-----|--------|---------------|--------|
| FRONT NUMBER<br>PLATE            |             | 1.0 | 20.00  | 0.00 %        | 20.00  |
| FRONT NUMBER<br>PLATE TRIM COVER |             | 1.0 | 25.00  | 0.00 %        | 25.00  |
| FRONT DOOR<br>COMFORT LOGO RH    |             | 1.0 | 75.00  | 0.00 %        | 75.00  |
| FRONT TYRE RH                    |             | 1.0 | 108.00 | 0.00 %        | 108.00 |

Materials Subtotal 228.00

**Labor**Replace/RnR

| Description                                               | Type | Cost    | Markup/Disc % | Price    |
|-----------------------------------------------------------|------|---------|---------------|----------|
| PANEL BEATING                                             | RnR  | 1000.00 | 0.00 %        | 1,000.00 |
| WIRING CHARGE                                             | RnR  | 30.00   | 0.00 %        | 30.00    |
| TUFF KOTE                                                 | RnR  | 40.00   | 0.00 %        | 40.00    |
| WHEEL ALIGNMENT                                           | RnR  | 60.00   | 0.00 %        | 60.00    |
| REMOVE AND REFIX UNDERCARRIAGE                            | RnR  | 150.00  | 0.00 %        | 150.00   |
| REMOVE AND REFIX RADIATOR                                 | RnR  | 50.00   | 0.00 %        | 50.00    |
| REMOVE AND REFIX AIRCON & GAS                             | RnR  | 80.00   | 0.00 %        | 80.00    |
| DIAGNOSTIC AND RESETTING FAULT CODE & ADAS OPTICAL SENSOR | RnR  | 150.00  | 0.00 %        | 150.00   |

Paint

| Description | Paint Type | Cost   | Markup/Disc % | Price  |
|-------------|------------|--------|---------------|--------|
| SPRAY PAINT | Full spray | 800.00 | 0.00 %        | 800.00 |

Labor Rate      S\$ 50 / Hour

General Labor Subtotal      1,560.00

Paint Labor Subtotal      800.00

Labor Subtotal      2,360.00

**Summary**

Repair Cost      32,427.92

Discount(11 %)      (3,527.92)

28,900.00

Excess      (0.00)

GST(0.00 %)      0.00

Grand Subtotal      28,900.00