

Jin Auto Services Pte Ltd

Blk 14 Defu Lane 10 #01-412

Singapore 539195

Tel: 62898126 Fax : 62870590

Email: Jin@jinauto.com.sg

Company Reg No:200704370C GST Reg No :200704370C

not Admnd
LUC
4/4/22
2/s \$2300/
3 days.
The photo after repair

28/3/2022

M/S AIG

DEAR SIR/MADAM

ESTIMATE REPAIR COST FOR TOYOTA ESTIMA - SND5439Z

DOA : 25/03/2022

S/N	QTY	DESCRIPTION			
1	1 PC	FRONT RH DOOR PROTECTOR	R	\$	1250.00 X
2	1 PC	FRONT RH DOOR PROTECTOR CHROME MLD	11	\$	115.00 X
3	1 PC	REAR RH DOOR	R	\$	REPAIR X
4	1 PC	REAR RH DOOR PROTECTOR	de bumper	\$ 1250	1350.00 /
5	1 PC	REAR RH DOOR PROTECTOR CHROME MLD	scr	\$	135.00 /
6	1 PC	REAR RH FENDER	R	\$	REPAIR X
7	1 PC	REAR RH FENDER PROTECTOR	R	\$	235.00 X
8	1 PC	REAR BUMPER	de	\$	604.90 /
9	1 PC	REAR RH RIM	R	\$	1810.00 X
				\$	5499.90
			Disc - 25%	\$	-1374.98
				\$	4124.92
10		SPRAY PAINTING (PEARL WHITE)		\$	1100.00 1050
11		LABOUR CHARGE		\$	480.00 300
			Total	\$	5704.92
12.		wiring (transfer door mechanism)	2 wiring	\$1801=	11 X

13. check alignment - \$80.00 - 60

14. Tuff kote - \$120.00 - 11 X

Click Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-1989.9
202
P-1492.42
L-1410
2902.42
202
2321