

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: SJS 4557D  
 at Workshop m/s Ry.  
 of \_\_\_\_\_  
 Insured: SHC 32675  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

Veh No: SJS 4557D Yr Regn: 12/09/08  
 Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or CA / RST  
 Make: Honda Stream c.c. 1799  
 Colour: Brown A/C: Insured / Std / NI / NA  
 Sp. Reading: 263065 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: RN 6 108 3298  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: In order / Jammed / Leaked / Burnt or  
 Brake: In order / Jammed / Leaked / Burnt or  
 Modi: Nil / S/Rim / STD A/Rim or

(Policy Condition)  
 Remark: The veh had commenced its  
 repair at the time of inspection.

|     |     |
|-----|-----|
|     |     |
| N/S | O/S |
|     |     |

Tyre Size: F: \_\_\_\_\_ R: 205/55 R17  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PR / SUMI /  
 TOYO / YOKO or \_\_\_\_\_  
 Front 6 mm Rear 6 mm  
 R/Bal. \_\_\_\_\_ mm R/Bal. \_\_\_\_\_ mm  
 L/Bal. 6 mm L/Bal. 6 mm  
 D.O.A. 25/3/22 D.O.I. 28/3/22  
 Survey held at \_\_\_\_\_

Bal. or Market Value: 12k.  
 IDAC Accident Rport: \_\_\_\_\_ Consistent?: Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No  
 Est. Repairs: 4 days Res.: Yes or No  
 Lum Sum: 20 % 3 Val.: Yes or No  
 CA / REV / REP. / 24 HRS 3 660k  
 Vehicle: IN / OUT  
 Date: \_\_\_\_\_ Person Contacted: L7A8 4857

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
Rear  
 The U/C / Chassis frame / Body Structure affected due to collision.

| Date / Time    | Action / Instruction                      |
|----------------|---|
|                | <u>coe until 11-09-2023 del lyes smth</u> |
|                | <u>not 7143 have cost</u>                 |
| <u>31/3/22</u> | <u>M/S 4500 insured Alan</u>              |

Date/Time, File Pass to?  : Prel. Report  
 : Final Report

Days Of Repair: \_\_\_\_\_

1) \_\_\_\_\_  
 Date/Time, File Return to?

Resurvey No. of Trip: \_\_\_\_\_

|                       |  |
|-----------------------|--|
| Survey Fee:           |  |
| Transportation:       |  |
| _____ S + RS _____ SI |  |
| Photos                |  |
| Others                |  |
| TOTAL                 |  |

Report Format : \_\_\_\_\_

Add Fee:  Site Insp (\$ )  
 Interview (\$ )  
 Tech. Invs (\$ )  
 Weekend (\$ )

Lump Sum / I.B.I. (\$) \_\_\_\_\_ )

Ashur

**FASTECH AUTO PTE LTD**

**1 Kaki Bukit Ave 6 #01-48 Autobay**

**Singapore 417883**

**Tel No: 67452063/ 67467158 Fax No: 67458520**

**Tax Reg No : 200006262D**

2/5 \$4500

4 days

28/3/22

VEHICLE No: SJJ 4551D

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

|      |                                     |               |        |            |     |
|------|-------------------------------------|---------------|--------|------------|-----|
| 1PC  | REAR WINDSCREEN MOULDING            | 1pc           | 66.80  | \$118.00   | ✓   |
| 1PC  | TAILGATE                            | DD            | 987.20 | \$945.20   | ✓   |
| 1PC  | TAILGATE 'STREAM' EMBLEM            | 1pc           | 38.00  | \$48.50    | ✓   |
| 1PC  | TAILGATE 'RSZ' EMBLEM               | 1pc           | 52.00  | \$60.00    | ✓   |
| 1PC  | TAILGATE INNER LOCK                 | Damaged       | 180.50 | \$195.20   | ✓   |
| 1PC  | TAILGATE INNER TRIM BOARD           | Del/Torn      | 315.30 | \$341.50   | ✓   |
| 1SET | TAILGATE INNER TRIM BOARD CLIPS     | 1pc           |        | \$45.00    | ✓   |
| 1PC  | TAILGATE WEATHERSTRIP               | 1pc           | 188.20 | \$268.30   | ✓   |
| 1PC  | REAR BUMPER                         | DD            | 654.00 | \$898.30   | ✓   |
| 2PCS | REAR BUMPER SIDE RETAINERS @\$25.00 | 17            |        | \$50.00    | X   |
| 2PCS | REAR BUMPER LOWER BRACKETS @\$35.00 | ant 1U        |        | \$70.00    | 1pc |
| 1SET | REAR BUMPER CLIPS                   | 1pc           | 40.00  | \$50.00    | ✓   |
| 1PC  | REAR BUMPER TOW COVER               | Torn          |        | \$28.00    | ✓   |
| 1SET | REAR BUMPER REVERSE SENSOR          | Shield        |        | \$250.00   | ✓   |
| 1PC  | REAR END PANEL                      | DD            |        | \$426.60   | ✓   |
| 1PC  | REAR END LOWER MEMBER               | R             |        | \$184.00   | X   |
| 1PC  | REAR END PANEL TOP GARNISH          | 1pc           |        | \$248.10   | ✓   |
| 1PC  | REAR WINDSCREEN SEALANT             | 1pc           |        | \$50.00    | ✓   |
| 1PC  | REAR WINDSCREEN INNER SEAL          | 1pc           |        | \$50.00    | ✓   |
| 2PCS | TAILLAMPS @\$488.00                 | 1 screw 1/2sm | 390.50 | \$976.00   | 1pc |
| 2PCS | TAILLAMP HOUSING PANELS @\$390.00   | R             |        | \$780.00   | X   |
| 1PC  | REAR FENDER N/S                     | R             |        | \$975.20   | X   |
| 1PC  | REAR FENDER INNER TRIM BOARD N/S    | Del/Torn      | 415.20 | \$455.20   | ✓   |
|      |                                     |               |        | \$7,513.10 |     |

|   |                    |     |
|---|--------------------|-----|
| TO CHECK WIRING                           | \$50.00            | 20  |
| TO DISMANTLE & REPLACED REVERSE SENSOR    | \$80.00            | 50  |
| TO DISMANTLE & REFIX REAR WINDSCREEN      | \$150.00           | 120 |
| TO DISMANTLE & REFIX CUSHION UPHOLSTERY   | \$120.00           | 80  |
| TO DISMANTLE & REFIX TAILGATE MECHANISM   | \$100.00           | 60  |
| TO SPRAY RUST PROOFING                    | \$100.00           | 80  |
| LABOUR FOR PANEL BEATING & REPLACED PARTS | \$1,200.00         | 800 |
| TO PUTTY & SPRAY PAINTING                 | \$1,500.00         | 880 |
| <b>TOTAL</b>                              | <b>\$10,813.10</b> |     |

P-4460-40  
202  
356832  
2070