



Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no. : 6631 1188

ESTIMATE

Account Details	Account No.	Customer Details
THIRD PARTY CLAIM	S1000020 / TPCLAIM	M/S Tak Products & Services Pte Ltd
	Document No. 0	41 Sungei Kadut Avenue
	Document Date 22/03/2022	Singapore 729665 Mobile: 88208025

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2018	KDH201R	SBMDY S5	25/10/2018	GY9500A	0	14007	65DS/GY9500A

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTFHT02P700245552	1KD2827794	60	Francis Cher T S	--/--/----	0.00 --/--/---- 0.00

Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1 Z	BP-SUNDRY SUNDRIES T/P INS. : China Taiping. T/P VEH. : SMV1067G ACC DATE : 21.03.22 BY :				100.00 50/
Z	BP-SLANT SUPPLY SEALANT (NETT)				100.00
S	BP-SUBLET RESET AND REPROGRAMME ECU.				180.00
B	BP-LAB2 CHK REAR WIRING SYSTEM AND CONDUCT WATER TEST.				180.00
B	BP-LAB2 DRILL HOLE TO INSTALL REVERSE SENSOR.				180.00
B	BP-LAB2 REMOVE TAIL-GATE COMPONENTS TO TRANSFER ONTO NEW DOOR.				328.00
B	BP-LAB2 REPLACE REAR W/SCREEN GLASS TO ASSIST REPAIR.				450.00
S	BP-SUBLET REMOVE BOOT INTERIOR UPHOLSTERY TO ASSIST REPAIR.				360 728.00
S	BP-SUBLET INSTALL TAIL-GATE COMPANY LOGO.				XM? 400.00
Z	BP-SUNDRY SUPPLY AND INSTALL 70KM.H AND 5 PAX STICKER.				30.00

on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less Amount Due



Inchcape

Co. Reg No. : 196700086Z
 GST Reg No. : MR-8500000-9
 No. 2 PANDAN CRESCENT
 SINGAPORE 128462, Tel no.: 6631 1188

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from the Company

ESTIMATE

Account Details		Account No.		Customer Details	
THIRD PARTY CLAIM		S1000020 / TPCLAIM		Acknowledged by Resurvey	
		Document No.		M/S Tak Products & Services Pte Ltd	
		0		Signature:	
		Document Date		41 Sungei Kadut Avenue	
		22/03/2022		Date:	
				Singapore 729665	
				Mobile: 88208025	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2018	KDH201R	SBMDY S5	25/10/2018	GY9500A	0	14007	65DS/GY9500A

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTFHT02P700245552	1KD2827794	60	Francis Cher T S	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
11	B	BP-LAB2 REMOVE ALL NECESSARY DAMAGED PARTS TO REPLACE, REPAIR, STRAIGHTEN TAIL-GATE, TAIL-LAMP PANEL, REAR BUMPER, FLOOR PANEL AND AFFECTED PORTION OF CAR.				3600 4320.00
12	B	BP-RES2 SPRAY PAINT ON DAMAGED AFFECTED PORTION OF CAR.				1770 2950.00
13	1	T52159-26470 REAR BUMPER COVER, de	1.00	481.80		481.80
14	2	T58385-26070 REAR BUMPER BRACKET, xan	3.00	27.70		83.10
15	3	T52158-26010 L/R SIDE BPR RETAINER, xan	1.00	24.80		24.80
16	4	T52157-26010 R/R SIDE BPR RETAINER, xan	1.00	24.80		24.80
17	5	T57069-26120 REAR OUTER FLR MEMBER, bt	1.00	363.70		363.70
18	6	T57068-26320 REAR INNER FLR MEMBER, bt	1.00	1172.50		1172.50
19	7	T67005-26L50 REAR BACK DOOR PANEL, bt	1.00	2293.20		2293.20
20	8	T68105-26151 GLASS SUB-ASSY, BACK ne	1.00	1419.80		1419.80
21	9	T90975-02064 EMBLEM, SYMBOL ne	1.00	72.20		72.20
22	0	T75441-26281 "TOYOTA HIACE" EMBLEM, Bne	1.00	51.60		51.60
23	1	T67935-26190 PLATE, BACK DOOR bt	1.00	112.30		112.30
24	2	TREVSE-FMS02 ZGE 2 PT SENSOR FOR HIACE nw	1.00	56.40		56.40

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd			16,094.20
	Please acknowledge receipt of vehicle	Parts	6,156.20
		Labour	8,638.00
		Sublet	1,300.00
		Lubrication/Fluid	0.00
		Others	0.00
		GST 7.00%	1,126.59
		Less	0.00
		Amount Due	17,220.79