



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details	Account No.	Customer Details
THIRD PARTY CLAIM	S1000020 / TPCLAIM	M/S Tak Products & Services Pte Ltd 41 Sungei Kadut Avenue Singapore 729665 Mobile: 88208025
	Document No. 0	
	Document Date 22/03/2022	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2018	KDH201R	SBMDY S5	25/10/2018	GY9500A	0	14007	65DS/GY9500A
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
JTFHT02P700245552	1KD2827794	60	Francis Cher T S	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES T/P INS. : T/P VEH. : SMV1067G ACC DATE : 21.03.22 BY :				100.00
2	Z	BP-SLANT SUPPLY SEALANT (NETT)				100.00
3	S	BP-SUBLET RESET AND REPROGRAMME ECU.				180.00
4	B	BP-LAB2 CHK REAR WIRING SYSTEM AND CONDUCT WATER TEST.				180.00
5	B	BP-LAB2 DRILL HOLE TO INSTALL REVERSE SENSOR.				180.00
6	B	BP-LAB2 REMOVE TAIL-GATE COMPONENTS TO TRANSFER ONTO NEW DOOR.				328.00
7	B	BP-LAB2 REPLACE REAR W/SCREEN GLASS TO ASSIST REPAIR.				450.00
8	S	BP-SUBLET REMOVE BOOT INTERIOR UPHOLSTERY TO ASSIST REPAIR.				720.00
9	S	BP-SUBLET INSTALL TAIL-GATE COMPANY LOGO.				400.00
10	Z	BP-SUNDRY SUPPLY AND INSTALL 70KM.H AND 5 PAX STICKER.				30.00

For & on behalf of Borneo Motors (Singapore) Pte Ltd	Customer's Signature	Charge Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less
			Amount Due

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details				Account No.		Customer Details			
THIRD PARTY CLAIM				S1000020 / TPCLAIM		M/S Tak Products & Services Pte Ltd 41 Sungei Kadut Avenue Singapore 729665 Mobile: 88208025			
				Document No. 0					
				Document Date 22/03/2022					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks		
2018	KDH201R	SBMDY S5	25/10/2018	GY9500A	0	14007	65DS/GY9500A		
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On		
JTFHT02P700245552		1KD2827794	60	Francis Cher T S	--/--/----		0.00 --/--/----		
L	Cd	Job/Parts Description				Qty	Unit Price	Disc %	Amount
11	B	BP-LAB2 REMOVE ALL NECESSARY DAMAGED PARTS TO REPLACE, REPAIR, STRAIGHTEN TAIL-GATE, TAIL-LAMP PANEL, REAR BUMPER, FLOOR PANEL AND AFFECTED PORTION OF CAR.							4320.00
12	B	BP-RES2 SPRAY PAINT ON DAMAGED AFFECTED PORTION OF CAR.							2950.00
13	1	T52159-26470 REAR BUMPER COVER,				1.00	481.80		481.80
14	2	T58385-26070 REAR BUMPER BRACKET,				3.00	27.70		83.10
15	3	T52158-26010 L/R SIDE BPR RETAINER,				1.00	24.80		24.80
16	4	T52157-26010 R/R SIDE BPR RETAINER,				1.00	24.80		24.80
17	5	T57069-26120 REAR OUTER FLR MEMBER,				1.00	363.70		363.70
18	6	T57068-26320 REAR INNER FLR MEMBER,				1.00	1172.50		1172.50
19	7	T67005-26L50 REAR BACK DOOR PANEL				1.00	2293.20		2293.20
20	8	T68105-26151 GLASS SUB-ASSY, BACK				1.00	1419.80		1419.80
21	9	T90975-02064 EMBLEM, SYMBOL				1.00	72.20		72.20
22	0	T75441-26281 "TOYOTA HIACE" EMBLEM,				1.00	51.60		51.60
23	1	T67935-26190 PLATE, BACK DOOR				1.00	112.30		112.30
24	2	TREVSE-FMS02 ZGE 2 PT SENSOR FOR HIACE				1.00	56.40		56.40
or & on behalf of		Customer's Signature		Charge Summary		Total			
Borneo Motors (Singapore) Pte Ltd		Please acknowledge receipt of vehicle				16,094.20			
				Parts		GST 7.00%			
				Labour		1,126.59			
				Sublet		Less			
				Lubrication/Fluid		0.00			
				Others		0.00			
				Amount Due		17,220.79			

Customer Copy