

Co Reg No : 1977014696

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name /LIM JOO LENG Reg No/Reg Date SGH8719H / 16/07/202 Date In/Mileage 25/03/2022/ 0 Chassis No MMBSTA13AKH000719 Engine No 3A92UHM3517 Make/Model MIT/19MY ATTRAGE 1.2 CVT Colour/Trim P57 WINE RED PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
KAX00008	Credit	25/03/2022/ 18:02	BLK	282 / Kevin Leong	21936		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE REAR BUMPER, BODY KIT & AFFECTED AREA REPAIR ON REAR LH FENDER				480 X 1			1800.00
E PNT98000 PAINT WORK ON REAR BUMPER, BODY KIT & REAR LH FENDER				350 X 3			1050.00
E PNT88000 REMOVE & REPALCE BODY KIT							80, 120.00
E PNT88000 REMOVE & INSTALL REAR PARKING ASSISTS FOR FACILITATE REPAIR							80, 120.00
M SUNDRY PERFORM RUST PREVENTION							X 40.00
A 54900099 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM							30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM							120.00
M SUNDRY SUNDRIES							20 50.00
M UNPAINTED BODYKITS				1.00	1643.00	20.00	1314.40
M LAMP ASSY, COMB, RR LH				1.00	337.00	23.00	259.49
M BRACKET, RR BUMPER, LH				1.00	28.00	23.00	21.56
M FACE, RR BUMPER				1.00	751.00	23.00	578.27

Estimate

Steve (LKK)
28/3/22, 11.00

DD. LI AL
EXCHG-?
PIP
M BL Ly
6 4 Ly

Steve (LKK)
28/3/22, 11.30

DD- L1 AL
EXCHG-?
PIP
M BL Ly
6 4 Ly

Confirm & accepted by repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and

Authorized signatory and company stamp

7% GST on **5503.72** **Nett** **5,503.72**
385.26
Total Payable **5,888.98**

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.