


Car-in

30/5/22

wip: 16869

# PREMIUM AUTOMOBILES

Benji



Veron.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

C.T - Adrian

- 5 days

## MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMO 1609 U

### DAMAGED PARTS & PRICES

| S/N                   | PARTS DESCRIPTION                                    | QTY | S/NETT       | REMARKS  |
|-----------------------|------------------------------------------------------|-----|--------------|----------|
| 1                     | REAR BUMPER <i>Delid</i>                             | 1   | \$ 3,188.00  | ✓        |
| 2                     | REAR BUMPER SPOILER <i>Delid</i>                     | 1   | \$ 913.00    | ✓        |
| 3                     | REAR BUMPER REINFORCEMENT BEAM <i>Broken Dented</i>  | 1   | \$ 1,131.00  | ✓ 3 fls. |
| 4                     | REAR BUMPER SEAL <i>Per</i>                          | 2   | \$ 32.00     | ✓        |
| 5                     | REAR BUMPER GUIDE SECTION - LH / RH <i>New</i>       | 2   | \$ 98.00     | +        |
| 6                     | REAR BUMPER GUIDE SECTION UPPER - LH / RH <i>New</i> | 2   | \$ 52.00     | +        |
| 7                     | GUIDE SECTION PIN <i>New</i>                         | 2   | \$ 5.00      | +        |
| 8                     | REAR PARKING AID SENSOR - INNER / OUTER ?            | 2   | TBC          | ?        |
| 9                     | REAR PARKING AID SENSOR SEAL RING ?                  | 4   | \$ 10.00     | ?        |
| 10                    | REAR BUMPER WIRING SET <i>New</i>                    | 1   | \$ 745.00    | +        |
| 11                    | REAR BUMPER REFLECTOR - LH / RH ? <i>LH cracked</i>  | 1   | \$ 92.00     | 46       |
| 12                    | REAR LID <i>Dented</i>                               | 1   | \$ 4,103.00  | ✓        |
| 13                    | REAR LID ATTACHMENT PARTS <i>New</i>                 | 1   | \$ 160.00    | +        |
| 14                    | REAR LID LOCK MICROSWITCH <i>New</i>                 | 1   | \$ 300.00    | +        |
| 15                    | BONNET LOCK COVER <i>New</i>                         | 1   | \$ 13.00     | +        |
| 16                    | REAR LID FLAP GASKET <i>New</i>                      | 1   | \$ 263.00    | +        |
| 17                    | REAR LID LOCK ACTUATOR <i>New</i>                    | 1   | \$ 1,478.00  | +        |
| 18                    | REAR LID STRIKER PLATE <i>New</i>                    | 1   | \$ 74.00     | +        |
| 19                    | REAR PACKING ADHESIVE <i>New</i>                     | 1   | \$ 21.00     | ✓        |
| 20                    | AUDI EMBLEM <i>Free</i>                              | 1   | \$ 103.00    | ✓        |
| 21                    | AS EMBLEM                                            | 1   | \$ 80.00     | ✓        |
| SUB TOTAL SPARE PARTS |                                                      |     | \$ 12,862.00 |          |

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
SPARE PARTS ARE SPECIAL NETT.

# PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMO 1609 U

|                      |                                            |     | DAMAGED PARTS & PRICES |               |
|----------------------|--------------------------------------------|-----|------------------------|---------------|
| S/N                  | PARTS DESCRIPTION                          | QTY | S/NETT                 | REMARKS       |
| 21                   | A5 EMBLEM <i>new</i>                       | 1   | \$ 80.00               | ✓             |
| 22                   | REAR LID CARBON SPOILER <i>new</i>         | 1   | \$ 1,842.00            | ✓             |
| 23                   | REAR WINDSCREEN <i>new</i>                 | 1   | \$ 1,301.00            | ✓             |
| 24                   | PRIMER                                     | 1   | \$ 22.00               | ✓             |
| 25                   | ADDITIONAL BRAKE LIGHT <i>new</i>          | 1   | \$ 642.00              | ✓ <i>H.S.</i> |
| 26                   | GASKET SET                                 | 1   | \$ 96.00               | ✓             |
| 27                   | LED LICENCE PLATE LIGHT <i>new</i>         | 2   | \$ 113.00              | ✓             |
| 28                   | TAIL LIGHT - INNER / OUTER <i>new</i>      | 2   | \$ 2,270.00            | ✓             |
| 29                   | TAIL LIGHT TRIM - LH / RH                  | 2   | \$ 68.00               | ✓             |
| 30                   | REAR WINDSCREEN SEALANT <i>new</i>         | S/N | \$ 200.00              | ✓             |
| 31                   | REAR LID CARBON SPOILER SEALANT <i>new</i> | S/N | \$ 200.00              | ✓             |
| 32                   | REAR NO PLATE <i>Revised</i>               | S/N | \$ 60.00               | ✓             |
| 33                   | SUNDRIES                                   |     | \$ 350.00              | ?             |
| TOTAL SPARE PARTS    |                                            |     | \$ 20,106.00           |               |
| TOTAL LABOUR CHARGES |                                            |     | \$ 8,492.00            |               |
| GRAND TOTAL          |                                            |     | \$ 28,598.00           |               |

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.

*Resigned*  
*Adrian Cj*  
*01/06/22.*