

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
	AXA INSURANCE	PTE LTD	Ref:	CS/ASM22002831/Aty3e2
	8 SHENTON WAY AXA TOWERSING		Date:	24/05/2022
	ATTN: CHAN KIAN	CHUAN	Code:	ASM
1.	Policy Particulars :- THIRD PARTY CLAIM			
	Insured Veh.	SHA 7466T	Veh. Inspected	SLE 1762J
	Policy No.		Coverage (\$)	0.00
	Claim No.	S2M03WV8	Excess (\$)	0.00
	Assign From	CHAN KIAN CHUAN	Assign Date	28/03/2022
2. Vehicle Particulars & Condition				
	Make & Model	B.M.W. 116D	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2016
	Chassis No.	WBA1V720305C07299	Colour	BLUE
	Odometer	110751 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	205/55 R16	CONTINENTAL	6 mm
	L/H Front Tyre	205/55 R16	CONTINENTAL	6 mm
	R/H Rear Tyre	205/55 R16	CONTINENTAL	6 mm
	L/H Rear Tyre	205/55 R16	CONTINENTAL	6 mm
4.	Description of Damages			
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.			
	DAMAGES SEE DETAILS.			
5.	General Information			
	Accident Date	26/03/2022	Inspection Date	29/03/2022
	Survey held at	CHENG MOTOR WORK CO.	-	
		NO.1 KAKI BUKIT AVE 6 #01-83 SINGAPORE 417883		
5a.	Remarks			
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b.	Estimate Days of Repair			