

LEE BROTHERS AUTOMOTIVE PTE. LTD.

NO 1 KAKI BUKIT AVE 6 #02-47

AUTOBAY SINGAPORE 417883

Tel : 6509 5521 / 65095524 Fax : 6509 5523

→ 451A 7.0m

Repair Sum \$13,800

Not Authorized
28/3/22

Repair Sum \$13,800

5 days.

The Motor Claims Dept.

AXA INSURANCE SINGAPORE PTE LTD

8 SHENTON WAY

#27-01 AXA TOWER

SINGAPORE 068811

SDT663J

ESTIMATE

DATE : 04.04.2022

VEHICLE NO : SMJ996U

MAKE/MODEL : MERC E200

ACC DATE : 26.03.2022

PARTICULAR

UNIT PRICE

AMOUNT

QTY	LIST PRICE	SS	SS
1	1 FRONT BUMPER	1645.00	1,989.61
2	1 FRONT BUMPER SIDE GRILLE - LH		110.25
3	1 FRONT BUMPER LOWER GRILLE - CTR		171.64
4	1 FRONT BUMPER LOWER CHROME MOULDING - CTR	365.00	553.02
5	2 FRONT BUMPER LOWER CHROME MOULDING - RH/LH		221.43
6	6 FRONT BUMPER PDC SENSOR	225x2 = 450	281.33
7	6 FRONT BUMPER PDC SENSOR HOLDER		12.10
8	1 FRONT BUMPER PDC SENSOR WIRE HARNESS		421.33
9	1 FRONT BUMPER FOAM		641.32
10	1 FRONT BUMPER FRAME PAD		209.78
11	1 FRONT BUMPER GUIDE - CTR		221.43
12	2 FRONT BUMPER GUIDE - RH/LH		196.63
13	1 FRONT BUMPER TOP SEAL		105.50
14	1 FRONT BUMPER TOP GUIDE SUPPORT	338.00	126.20
15	1 FRONT BUMPER REINFORCEMENT	640.00	441.50
16	2 FRONT BUMPER REINFORCEMENT STAYS - RH/LH	155.00	189.65
17	1 FRONT BONNET		2,654.80
18	1 FRONT BONNET LOCK - LH		141.35
19	1 FRONT BONNET LOCK RELEASE CABLE		126.20
20	1 FRONT BONNET SEAL		110.25
21	1 FRONT BONNET INSULATOR		281.59
22	15 FRONT BONNET INSULATOR CLIPS		6.50
23	1 FRONT BONNET BADGE		89.95
24	1 FRONT FENDER - LH	1042.16	1,175.81
25	1 FRONT FENDER UNDERCOVER		181.53
26	1 FRONT FENDER UNDERCOVER EXTENSION		118.53
27	1 FRONT GRILLE ASSY - AMG	1242.16	1,381.55
28	1 FRONT HEADLAMP - LH	5302.37	5,665.91
29	1 FRONT HEADLAMP PANEL - LH		281.95
30	1 FRONT HEADLAMP LOWER BRACKET		110.25
31	1 FRONT HEADLAMP SIDE GARNISH - LH		86.65
32	2 FRONT HEADLAMP CONTROL UNIT - LH	945.25	1,210.50
33	1 FRONT NUMBER PLATE GARNISH		102.65
34	1 FRONT TOP PANEL		607.28
35	1 FRONT TOP PANEL AIR DUCT		244.32

14099.79

LEE BROTHERS AUTOMOTIVE PTE. LTD.

PARTICULAR		UNIT PRICE	AMOUNT
QTY		SS	SS
36	1 FRONT TOP PANEL BRACKET - CTR	121.50 ^7	121.50 X
37	1 AIR CLEANER INTAKE DUCT	186.90 11	186.90 X
38	1 AIR CON CONDENSER	1,373.43 11	1,373.43 X
39	1 AIR CON CONDENSER AIR DUCT	191.63 11	191.63 X
40	1 AIR INTERCOOLER	1,410.59 11	1,410.59 X
41	1 AIR INTERCOOLER AIR DUCT	221.43 11	221.43 X
42	1 HORN	101.50 11	101.50 X
43	1 WIPER TANK	341.55 De	341.55 ✓
44	1 WIPER TANK AIR HOSE	182.60 11	182.60 X
45	1 WIPER TANK MOTOR	186.95 11	186.95 X
46	1 FRONT UNDERCOVER	221.50 11	221.50 ✓
47	1 FRONT SHOCK ABSORBER - LH	781.60 11	781.60 X
48	1 FRONT TOP CONTROL ARM	602.50 11	602.50 X
49	1 FRONT LOWER CONTROL ARM	670.50 11	670.50 X
50	1 FRONT KNUCKLE ARM	1,310.85 11	1,310.85 X
51	1 FRONT WHEEL BEARING	581.75 11	581.75 X
			33,022.55
		LESS 10%	3,302.26
			<u>29,720.30</u>

SPECIAL NETT ITEMS

1	1 FRONT SPORT WHEEL - LH	1,200.00 waped	1,200.00 800
2	1 FRONT TYRE - LH	600.00 11	600.00 X
3	1 (SET) FRONT BUMPER CLIP WITH REVET	80.00 11	80.00 60
			<u>1,880.00</u>

LABOUR CHARGES:

1	TO CHECK FRONT ELECTRICAL WIRING		50.00 20
2	TO REMOVE & REPLACE FRONT UNDERCARRIAGE PARTS	11	250.00 X
3	TO CONDUCT COMPUTERISED WHEEL ALIGNMENT		120.00 60
4	TO TUFF KOTE		100.00 40
5	TO REMOVE & REPLACE AIR CON CONDENSER & RADIATOR & TOP UP GAS	11	150.00 X
6	TO DIGNOSS AND ERASE FAULT MEMORY AFTER REPAIR		350.00 50
7	TO PUTTY, SPRAY PAINT & POLISH AFFECTED PARTS		1,200.00 600
8	TO PANEL BEAT, CUT, WELD, REMOVE & REPLACE DAMAGED PARTS		1,200.00 600
			<u>3,420.00</u>

ESTIMATE PARTS AND LABOUR GRAND TOTAL : \$ **35,020.30**

P- 14662-84

/02

P- 13196-SJK

S.N- 860

L- 1370

15426.55
17087

Lee Brothers Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: